This type of ceiling is carried throughout the first floor, except in the pantry, first floor bathroom, and laundry room, in which the ceiling has been lowered. The laundry room is one step down from the kitchen. There are tile sills and casement windows, but these open outward rather than inward. There is a half basement. There is a hallway attaching the laundry room with the front entrance. The upstairs bathroom is one step above the level of the upstairs hall. All bathrooms in the house have two doors. There are quarters intended for servants on the third floor, ventilated through the eyebrow windows. The room over the garage was a billards room and has a roof rafter and bie beam ceiling. The ridge dormer provides ventilation for it. There is a n airing po rch off the second floor.

This house is architecturally significant because is is one of a group of stone masonry houses built by Arnold F. Meyer & Company, Inc. according to the methods of Ernest Flagg. It is also significant because it is one of four homes built by Arnold F. Meyer for membefs of his own family. His brother Henry A. Heyer, who occupied this home, was president of the M<sup>L</sup>lwaukee Tug Boat line. The house is located in a neighborhood of larger homes in which it was not uncommon to employ servants in the 1920's.



