



WIDOWS' HOME
Hartford, Connecticut

Facades (west) and north elevations;
view to southeast.

M. Kerski, 1982

Negative filed: Hartford Architecture
Conservancy

#1 of 10



WIDOWS' HOME

Hartford, Connecticut

Facade (west), southern-most
building; view to east.

M. Kerski, 1982

Negative filed: Hartford Architecture
Conservancy

#2 of 10



WIDOWS' HOME

Hartford, Connecticut

South (side) elevation of southernmost building, showing roof cornice with returns only; view to northwest.

M. Kerski, 1982.

Negative filed: Hartford Architecture
Conservancy #3 of 10



WIDOWS' HOME


Hartford, Connecticut

Typical doorway (southern-most building, second floor).

M. Kerski, 1982

Negative filed: Hartford Architecture
Conservancy

#4 of 10



WIDOWS' HOME
Hartford, Connecticut

Typical window opening (southern-most
building, second floor).

M. Kerski, 1982

Negative filed: Hartford Architecture
Conservancy

#5 of 10



WIDOWS' HOME


Hartford, Connecticut

Newel post and banisters, southern-
most building.

M. Kerski, 1982

Negative filed: Hartford Architecture
Conservancy

#6 of 10



WIDOWS' HOME

Hartford, Connecticut

Mantelpiece, first floor, southern-
most building.

M. Kerski, 1982

Negative filed: Hartford Architecture
Conservancy

#7 of 10



WIDOWS' HOME

Hartford, Connecticut

Doorways, second floor, northern-
most building.

M. Kerski, 1982

Negative filed: Hartford Architecture
Conservancy

#8 of 10



WIDOWS' HOME
Hartford, Connecticut

Mantelpiece, second floor, northern-
most building.

M. Kerski, 1982

Negative filed: Hartford Architecture
Conservancy

#9 of 10



WIDOWS' HOME

Hartford, Connecticut

Typical doorway (northern-most building, first floor).

M. Kerski, 1982

Negative filed: Hartford Architecture
Conservancy

#10 of 10