



Photo No. 1:

Rocky Point site as seen from north  
side of river looking south.

FWS · Photo---2/75

*Fergus County*



Montana

Photo No. 2:

Single story barn and storage shed  
at Rocky Point.

*Forge County* FWS Photo---2/75



Photo No. 3:

Two story barn and storage building  
at Rocky Point showing present  
and rapidly deteriorating condition.

FWS Photo--2/75



Photo No. 4:

One of the existing buildings at Rocky Point renovated in 1965 by Wildlife Range personnel.

FWS Photo--2/75