

Location: Mishawaka, Indiana Photographer: Marian O'Keefe Photograph Date: March, 1979 Location of Negative: LeRoy Troyer and Associates 415 Lincolnway East, Mishawaka, Indiana 46544

Property Name: Ellis-Schindler House

Description: Exterior view of house on original site showing condition prior to move. PHOTO 1.



Location: Mishawaka, Indiana Photographer: Phil Cartwright Photograph Date: January, 1987 Location of Negative: LeRoy Troyer and Associates 415 Lincolnway East, Mishawaka, Indiana 46544 Description: Exterior view showing the condition of the house after the move, but prior to

Property Name: Ellis-Schindler House

restoration.



Property Name: Ellis-Schindler House Location: Mishawaka, Indiana Photographer: Phil Cartwright Photograph Date: January, 1987 Location of Negative: LeRoy Troyer and Associates 415 Lincolnway East, Mishawaka, Indiana 46544 Description: View from the southwest showing south and west facades.



Photographer: Phil Cartwright

Photograph Date: January, 1987

Location of Negative: LeRoy Troyer and Associates

415 Lincolnway East, Mishawaka, Indiana 46544

Description: View from the southeast showing south and

Property Name: Ellis-Schindler House

Location: Mishawaka, Indiana



Property Name: Ellis-Schindler House Location: Mishawaka, Indiana Photographer: Phil Cartwright Photograph Date: January, 1987 Location of Negative: LeRoy Troyer and Associates 415 Lincolnway East, Mishawaka, Indiana 46544 Description: View from the northeast showing north and east facades.



Property Name: Ellis-Schindler House Location: Mishawaka, Indiana Photographer: Phil Cartwright Photograph Date: January, 1987 Location of Negative: LeRoy Troyer and Associates 415 Lincolnway East, Mishawaka, Indiana 46544 Description: Detail of entry door showing transom and door surround.



Property Name: Ellis-Schindler House Location: Mishawaka, Indiana Photographer: Phil Cartwright Photograph Date: January, 1987 Location of Negative: LeRoy Troyer and Associates 415 Lincolnway East, Mishawaka, Indiana 46544 Description: Frieze and door surround detail.



Location: Mishawaka, Indiana Photographer: Phil Cartwright Photograph Date: January, 1987 Location of Negative: LeRoy Troyer and Associates 415 Lincolnway East, Mishawaka, Indiana 46544 Description: Detail of trim work at front entry ceiling. PUOTO 8 -

Property Name: Ellis-Schindler House



Location: Mishawaka, Indiana

Photographer: Phil Cartwright

Photograph Date: January, 1987

Location of Negative: LeRoy Troyer and Associates

415 Lincolnway East, Mishawaka, Indiana 46544

Description: Frieze detail showing attic windows.

Property Name: Ellis-Schindler House



FUIS-SHINTER HOUSE MISLA WAKA, N Pall CARTINTOISELT NECATIVE AT A LINCOLNWAY WEST, MICHALLINA 1ST FLICE INTERIOR UNDER REHABILHATION, CHOWING CENTER HALLINAY 14-010



Property Name: Ellis-Schindler House Location: Mishawaka, Indiana Photographer: Phil Cartwright Photograph Date: May, 1988 Location of Negative: LeRoy Troyer and Associates 415 Lincolnway East, Mishawaka, Indiana 46544 Description: View of central corridor.

Purto 11



Property Name: Ellis-Schindler House Location: Mishawaka, Indiana Photographer: Phil Cartwright Photograph Date: May. 1988 Location of Negative: LeRoy Troyer and Associates 415 Lincolnway East, Mishawaka, Indiana 46544 Description: View of parlor.



Property Name: Ellis-Schindler House
Thotographer: Phil Cartwright
Photograph Date: May, 1988

Location of Negative: LeRoy Troyer and Associates 415 Lincolnway East, Mishawaka, Indiana 46544 Description: Window surround and shutters.

PHOTO B



Location: Mishawaka, Indiana Photographer: Phil Cartwright Photograph Date: May, 1988 Location of Negative: LeRoy Troyer and Associates 415 Lincolnway East, Mishawaka, Indiana 46544 Description: View of upstairs bedroom.

Property Name: Ellis-Schindler House