



ST. UNION ST.
MAIN ST.

ONE
WAY
→
NO
LEFT
TURN

88-A-20

South Union Street Historic District
Burlington, Vermont
Credit: David Tansey
Date: March, 1988
Negative Filed at Vermont Division for
Historic Preservation
Description: Streetscape (on right #1)
View Looking South
Photograph #1



84-78

South Union Street Historic District
Burlington, Vermont
Credit: Lauren H. Murphy
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: South Union Street
Streetscape; View Looking South
Photograph #2 (#13 ON LEFT)



South Union Street Historic District
Burlington, Vermont
Credit: Lauren Murphy
Date: March, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Kingsland Terrace
Streetscape (#3) ON LEFT
Photograph #3



South Union Street Historic District
Burlington, Vermont
Credit: Steven Engelhart
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: South Union Street
Streetscape; View Looking Northeast
Photograph #4 (#42 ON LEFT)

84-74



84-74

South Union Street Historic District
Burlington, Vermont
Credit: Steven Engelhart
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: South Union Street
Streetscape; View Looking Northeast
Photograph #5 (#47 ON RIGHT)



84-74

South Union Street Historic District
Burlington, Vermont
Credit: Steven Engelhart
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Cliff Street Streetscape
View Looking Northeast (#17 ON LEFT)
Photograph #6



South Union Street Historic District
Burlington, Vermont
Credit: Michele Plourde
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Bayview Street Streetscape
View Looking Northeast (#66 on LEFT)
Photograph #7

84-75



South Union Street Historic District
Burlington, Vermont
Credit: Michele Plourde
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Bayview Street Streetscape
View Looking Northwest (#69 ON RIGHT)
Photograph #8

84-75



84-75

South Union Street Historic District
Burlington, Vermont
Credit: Michele Flourde
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Bayview Street Streetscape
View Looking Northwest (#69 ON LEFT)
Photograph #9



84-75

South Union Street Historic District
Burlington, Vermont
Credit: Michele Plourde
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Bayview Street Streetscape
View Looking Southeast (#79 ON RIGHT)
Photograph #10



South Union Street Historic District
Burlington, Vermont
Credit: Michele Plourde
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Bayview Street Streetscape
View Looking Southwest (#73 ON LEFT)
Photograph #11



South Union Street Historic District
Burlington, Vermont
Credit: Clare Sheppard
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: South Union Street
Streetscape (#100 ON LEFT)
Photograph #12

84-77



84-72

South Union Street Historic District
Burlington, Vermont
Credit: Lisa Schaeffer
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: South Union Street
Streetscape; View Looking Southeast
Photograph #13 (#103 ON LEFT)



84-72

South Union Street Historic District
Burlington, Vermont
Credit: Lisa Schaffer
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: South Union Street
Streetscape; View Looking Southeast
Photograph #14 (#109 ON LEFT)



South Union Street Historic District
Burlington, Vermont
Credit: Lauren H. Murphy
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: T. Bigelow House,
153 South Union #1; View Looking West
Photograph #15

84-A-76



South Union Street Historic District
Burlington, Vermont
Credit: Lauren H. Murphy
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 157-159 South Union
Street #2; View Looking West
Photograph #16

84-26



84-76

South Union Street Historic District
Burlington, Vermont
Credit: Lauren H. Murhpy
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Oliver Eastman House, 163
South Union Street #3 and #3A
View Looking West
Photograph #17



84-76

South Union Street Historic District
Burlington, Vermont
Credit: Lauren H. Murphy
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Kelley Apartments,
167-171 South Union Street #4
View Looking West
Photograph #18



28-P-20
South Union Street Historic District
Burlington, Vermont

Credit: David Tansey

Date: March, 1988

Negative Filed at Vermont Division for
Historic Preservation

Description: John Saxe House,
175-177 South Union Street #5,

View Looking Southwest

Photograph #19



South Union Street Historic District
Burlington, Vermont
Credit: Lauren H. Murphy
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: E.R. Hand House, 181 South
Union Street #6, View Looking West
Photograph #20

84-26



84-76

South Union Street Historic District
Burlington, Vermont
Credit: Lauren H. Murphy
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: J.H. Lane House, 192 South
Union Street #7, View Looking East
Photograph #21



84-76

South Union Street Historic District
Burlington, Vermont
Credit: Lauren H. Murphy
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: E.W. Burritt House,
196 South Union Street #8;
View Looking East
Photograph #22



South Union Street Historic District
Burlington, Vermont
Credit: Lauren H. Murphy
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: A.E. Richardson House,
202-204 South Union Street #9,
View Looking East
Photograph #23



South Union Street Historic District
Burlington, Vermont
Credit: Lauren H. Murphy
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 210 South Union Street #10
View Looking East
Photograph #24

84-76



84-76

South Union Street Historic District
Burlington, Vermont
Credit: Laurenn H. Murphy
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Garage #10A;
View Looking East
Photograph #25



84-76

South Union Street Historic District
Burlington, Vermont

Credit: Lauren H. Murphy

Date: February, 1984

Negative Filed at Vermont Division for
Historic Preservation

Description: 216 South Union Street #11
View Looking East

Photograph #26



South Union Street Historic District
Burlington, Vermont
Credit: Lauren H. Murphy
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 222 South Union Street #12
View Looking East
Photograph #27

84-76



South Union Street Historic District
Burlington, Vermont
Credit: Craig S. Adams
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Albert L. Catlin House,
230 South Union Street #13,
View Looking East
Photograph #28

84-A-71



84-A-71

South Union Street Historic District
Burlington, Vermont
Credit: Craig S. Adams
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Fred Johonott House,
236 South Union Street #14
View Looking East
Photograph #29



84-A-71

South Union Street Historic District
Burlington, Vermont
Credit: Craig S. Adams
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Catlins Carriage House #15
View Looking East
Photograph #30



84-A-71

South Union Street Historic District
Burlington, Vermont
Credit: Craig S. Adams
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: G.A. Pope House #16
View Looking East
Photograph #31



South Union Street Historic District
Burlington, Vermont

Credit: Lauren H. Murphy

Date: March, 1984

Negative Filed at Vermont Division for
Historic Preservation

Description: #16A; View Looking
Northwest

Photograph #32

Photograph #32



84-A-71

South Union Street Historic District
Burlington, Vermont
Credit: Craig S. Adams
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: William Greenleaf House
#17 & #17A; View Looking East
Photograph #33



88-A-20

South Union Street Historic District
Burlington, Vermont
Credit: David Tansey
Date: March, 1988
Negative Filed at Vermont Division for
Historic Preservation
Description: 254 South Union Street
17A; View Looking Northeast
Photograph #34



84-A-71

South Union Street Historic District
Burlington, Vermont
Credit: Craig S. Adams
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: J.B. Henderson House #18
View Looking East
Photograph #35



South Union Street Historic District
Burlington, Vermont
Credit: Craig S. Adams
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: J.W. McGeary House #19
View Looking East
Photograph #36

84-A-71



South Union Street Historic District
Burlington, Vermont
Credit: Craig S. Adams
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Moody House, 276 South
Union Street #20; View Looking East
Photograph #37

84-A-71



84-A-71

South Union Street Historic District
Burlington, Vermont
Credit: Craig S. Adams
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: C.B. Wetherby House #21
View Looking East
Photograph #38



84-7-71

South Union Street Historic District
Burlington, Vermont
Credit: Craig S. Adams
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: #21A; View Looking North
Photograph #39



South Union Street Historic District
Burlington, Vermont
Credit: Craig S. Adams
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Howard Shufelt House,
292 South Union Street #22
View Looking East
Photograph #40

84-V-71



South Union Street Historic District
Burlington, Vermont
Credit: Craig S. Adams
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 300 South Union Street #23
View Looking East
Photograph #41

89A-71



84-A-114

South Union Street Historic District
Burlington, Vermont
Credit: Anne Herman
Date: March, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 14 Kingsland Terrace #24
View Looking Northwest
Photograph #42



84-A-114

South Union Street Historic District
Burlington, Vermont
Credit: Anne Herman
Date: March, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 22 Kingsland Terrace #25
View Looking Northwest
Photograph #43



50-17-30
South Union Street Historic District
Burlington, Vermont
Credit: David Tansey
Date: March, 1988
Negative Filed at Vermont Division for
Historic Preservation
Description: 28 Kingsland Terrace #26
View Looking Northeast
Photograph #44



South Union Street Historic District
Burlington, Vermont
Credit: Anne Herman
Date: March, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: O. Frentiss House,
32 Kingsland Terrace #27;
View Looking Northeast
Photograph #45

84-A-114



84-A-114

South Union Street Historic District
Burlington, Vermont
Credit: Anne Herman
Date: March, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: B.J. Boynton House,
40 Kingsland Terrace #28;
View Looking North
Photograph #46



84-A-115

South Union Street Historic District
Burlington, Vermont
Credit: Lauren Murphy
Date: March, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 50 Kingsland Terrace #29
View Looking West
Photograph #47



South Union Street Historic District
Burlington, Vermont

Credit: Anne Herman

Date: March, 1984

Negative Filed at Vermont Division for
Historic Preservation

Description: Harold Slocum House,
41 Kingsland Terrace #30;

View Looking South

Photograph #48



South Union Street Historic District
Burlington, Vermont
Credit: Anne Herman
Date: March, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Hunter House, 35 Kingsland
Terrace #31; View Looking Southeast
Photograph #49

84-A-114



84-A-114

South Union Street Historic District
Burlington, Vermont
Credit: Anne Herman
Date: March, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: N.D. Bissonette House,
27 Kingsland Terrace #32
Photograph #50



84-A-115

South Union Street Historic District
Burlington, Vermont
Credit: Lauren Murphy
Date: March, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 23 Kingsland Terrace #33
View Looking Southwest
Photograph #51



South Union Street Historic District
Burlington, Vermont
Credit: Anne Herman
Date: March, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Dr. Whitney House,
19 Kingsland Terrace #34
Photograph #52

84-A-114



South Union Street Historic District
Burlington, Vermont
Credit: Craig S. Adams
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Dr. Partridge House
36 South Union Street #35;
View Looking East
Photograph #53

84-A-71



84-A-71

South Union Street Historic District
Burlington, Vermont
Credit: Craig S. Adams
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Powell House, 316 South
Union Street #36; View Looking East
Photograph #54



84-A-71

South Union Street Historic District
Burlington, Vermont
Credit: Craig S. Adams
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Captain Grey House,
324 South Union Street #37;
View Looking East
Photograph #55



South Union Street Historic District
Burlington, Vermont
Credit: Craig S. Adams
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Paul Kelley House,
334 South Union Street #38;
View Looking East
Photograph #56

89-H-71



South Union Street Historic District
Burlington, Vermont
Credit: Lauren Murphy
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 118 Spruce Street
#39 & 39A; View Looking Northeast
Photograph #57

84-78-13A



84-78

South Union Street Historic District
Burlington, Vermont
Credit: Lauren Murphy
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Clarence L. Smith House,
124 Spruce Street #40 & #40A;
View Looking North
Photograph #58



84-78

South Union Street Historic District
Burlington, Vermont
Credit: Lauren Murphy
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 119 Spruce Street #41
View Looking Southeast
Photograph #59



South Union Street Historic District
Burlington, Vermont
Credit: Steven Engelhart
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 346 South Union Street #42
View Looking East
Photograph #60

84-73



South Union Street Historic District
Burlington, Vermont
Credit: Steven Engelhart
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 354 South Union Street #43
View Looking East
Photograph #61

84-73



88-A-20

South Union Street Historic District
Burlington, Vermont
Credit: David Tansey
Date: March, 1988
Negative Filed at Vermont Division for
Historic Preservation
Description: 362 South Union Street #44
View Looking Northeast
Photograph #62



887-20

South Union Street Historic District
Burlington, Vermont
Credit: David Tansey
Date: March, 1988
Negative Filed at Vermont Division for
Historic Preservation
Description: 368 South Union Street #45
View Looking East
Photograph #63



South Union Street Historic District
Burlington, Vermont
Credit: Steven Engelhart
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 374 South Union Street #46
View Looking East
Photograph #64

84-73



South Union Street Historic District
Burlington, Vermont
Credit: Steven Engelhart
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 378 South Union Street #47
View Looking East
Photograph #65

84-73



84-73

South Union Street Historic District
Burlington, Vermont

Credit: Steven Engelhart

Date: February, 1984

Negative Filed at Vermont Division for
Historic Preservation

Description: 14 Cliff Street #48

View Looking North

Photograph #66



84-73

South Union Street Historic District
Burlington, Vermont
Credit: Steven Engelhart
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: D.A. Brodie House,
20 Cliff Street #49;
View Looking North
Photograph #67



South Union Street Historic District
Burlington, Vermont
Credit: Steven Engelhart
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 24-26 Cliff Street #50
View Looking North
Photograph #68



South Union Street Historic District
Burlington, Vermont
Credit: Steven Engelhart
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 32 Cliff Street #51
View Looking North
Photograph #69

84-73



84-74

South Union Street Historic District
Burlington, Vermont
Credit: Steven Engelhart
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 55 Cliff Street #52
View Looking South
Photograph #70



84-74

South Union Street Historic District
Burlington, Vermont
Credit: Steven Engelhart
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 53 Cliff Street #53
View Looking South
Photograph #71



South Union Street Historic District
Burlington, Vermont
Credit: Steven Engelhart
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 49 Cliff Street #54
View Looking South
Photograph #72

84-74



South Union Street Historic District
Burlington, Vermont
Credit: Steven Engelhart
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 45 Cliff Street #55
View Looking South
Photograph #73

84-74



84-74

South Union Street Historic District
Burlington, Vermont
Credit: Steven Engelhart
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 39 Cliff Street #56 & 56A
View Looking South
Photograph #74



84-74

South Union Street Historic District
Burlington, Vermont
Credit: Steven Engelhart
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 37 Cliff Street #57
View Looking South
Photograph #75



77-7-21
South Union Street Historic District
Burlington, Vermont

Credit: David Tansey

Date: March, 1988

Negative Filed at Vermont Division for
Historic Preservation

Description: 31 Cliff Street #58
View Looking South

Photograph #76



88A-20

South Union Street Historic District
Burlington, Vermont
Credit: David Tansey
Date: March, 1988
Negative Filed at Vermont Division for
Historic Preservation
Description: 25 Cliff Street #59
View Looking South
Photograph #77



84-74

South Union Street Historic District
Burlington, Vermont
Credit: Steven Engelhart
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 19 Cliff Street #60
View Looking South
Photograph #78



84-79

South Union Street Historic District
Burlington, Vermont
Credit: Steven Engelhart
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 7-15 Cliff Street #61
View Looking Southeast
Photograph #79



South Union Street Historic District
Burlington, Vermont
Credit: Steven Engelhart
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 390 South Union Street #62
View Looking East
Photograph #80



South Union Street Historic District
Burlington, Vermont
Credit: Michele Plourde
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Ambrose A. Drew House
394-396 South Union Street #63;
View Looking East,
Photograph #81

84-80



88-7-20

South Union Street Historic District
Burlington, Vermont
Credit: David Tansey
Date: March, 1988
Negative Filed at Vermont Division for
Historic Preservation
Description: Smalley House, 400 South
Union Street #64; View Looking East
Photograph #82



84-80

South Union Street Historic District
Burlington, Vermont
Credit: Michele Flourde
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Hamilton Peck House,
406 South Union Street #65;
View Looking East
Photograph #83



8-7-20
South Union Street Historic District
Burlington, Vermont

Credit: David Tansey

Date: March, 1988

Negative Filed at Vermont Division for
Historic Preservation

Description: Carrie Huntington House,
24 Bayview #66; View Looking Northwest
Photograph #84



South Union Street Historic District
Burlington, Vermont
Credit: Michele Plourde
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Solomon Story House,
32 Bayview Street #67;
View Looking Northeast
Photograph #85

84-80



88A-20

South Union Street Historic District
Burlington, Vermont
Credit: David Tansey
Date: March, 1988
Negative Filed at Vermont Division for
Historic Preservation
Description: Walter Holtham House,
38 Bayview Street #68
Photograph #86



84-80

South Union Street Historic District
Burlington, Vermont
Credit: Michele Plourde
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Sherrod S. Brown House,
44 Bayview Street #69;
View Looking Northeast
Photograph #87



58-A-20
South Union Street Historic District
Burlington, Vermont
Credit: David Tansey
Date: March, 1988
Negative Filed at Vermont Division for
Historic Preservation
Description: Cora Beach House,
50 Bayview Street #70;
View Looking Northwest
Photograph #88



88-A-20

South Union Street Historic District
Burlington, Vermont
Credit: David Tansey
Date: March, 1988
Negative Filed at Vermont Division for
Historic Preservation
Description: Winthrop Parker House,
54 Bayview Street #71;
View Looking Northwest
Photograph #89



84-80

South Union Street Historic District
Burlington, Vermont
Credit: Michele Flourde
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Arthur M. Hook House,
58 Bayview Street #72;
View Looking Northeast
Photograph #90



88A-20

South Union Street Historic District
Burlington, Vermont
Credit: David Tansey
Date: March, 1988
Negative Filed at Vermont Division for
Historic Preservation
Description: John W. Foss House,
47-49 Bayview Street #73;
View Looking South
Photograph #91



88-47-20
South Union Street Historic District
Burlington, Vermont

Credit: David Tansey

Date: March, 1988

Negative Filed at Vermont Division for
Historic Preservation

Description: William Wears House,
45 Bayview Street #74;

View Looking South

Photograph #92



South Union Street Historic District
Burlington, Vermont
Credit: Michele Flourde
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Robert Noble House #75
View Looking Southeast (35 BAYVIEW)
Photograph #93

84-75



84-75

South Union Street Historic District
Burlington, Vermont
Credit: Michele Flourde
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Nelson Warner House
29 Bayview Street #76;
View Looking Southeast
Photograph #94



88A-20

South Union Street Historic District
Burlington, Vermont
credit: David Tansey
Date: March, 1988
Negative Filed at Vermont Division for
Historic Preservation
Description: Hall House, 25 Bayview
Street#77; View Looking Southeast
Photograph #95



South Union Street Historic District
Burlington, Vermont
Credit: David Tansey
Date: March, 1988
Negative Filed at Vermont Division for
Historic Preservation
Description: George Lewis House,
17 Bayview Street #78;
View Looking Southwest
Photograph #96



88-A-20

South Union Street Historic District
Burlington, Vermont
Credit: David Tansey
Date: March, 1988
Negative Filed at Vermont Division for
Historic Preservation
Description: Elsie Miller House,
13 Bayview Street #79;
View Looking Southwest
Photograph #97

84-79

South Union Street Historic District
Burlington, Vermont
Credit: Anne Herman /
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: First Church of Christian
Science #80; View Looking East
Photograph #98



ENTRANCE
ONLY

ENTRANCE
ONLY

84-79

South Union Street Historic District
Burlington, Vermont
Credit: Anne Herman
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 424 South Union Street #81
View Looking Northeast
Photograph #99



South Union Street Historic District
Burlington, Vermont
Credit: Anne Herman
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Adams School #82
View Looking Northeast (440-444 SOUTH
UNION)
Photograph #100

84-79



South Union Street Historic District
Burlington, Vermont
Credit: Anne Herman
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: C.E. McEven House,
452-454 Union Street #83;
View Looking Northeast
Photograph #101

84-79



84-70

South Union Street Historic District
Burlington, Vermont
Credit: Anne Herman
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: C.L. Soule House
458 South Union Street #84
View Looking Northeast
Photograph #102



84-81

South Union Street Historic District
Burlington, Vermont
Credit: Clare Sheppard
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Raymond Soule House
457 South Union Street #85
View Looking Southwest
Photograph #103



South Union Street Historic District
Burlington, Vermont
Credit: Clare Sheppard
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Dolan House, 455 South
Union Street #86;
View Looking Northwest
Photograph #104



South Union Street Historic District
Burlington, Vermont
Credit: Clare Sheppard
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Cosgrove Family House
445 South Union Street #87
View Looking West
Photograph #105

84-87



84-81-4

South Union Street Historic District
Burlington, Vermont
Credit: Clare Sheppard
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 445 South Union Street
#87A; View Looking Northwest
Photograph #106



84-81

South Union Street Historic District
Burlington, Vermont
Credit: Clare Sheppard
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Russell House and Garage
437 South Union Street #89;
View Looking Southwest
Photograph #107



South Union Street Historic District
Burlington, Vermont
Credit: Clare Sheppard
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Black House, 431-433 South
Union Street #90;
View Looking Northwest
Photograph #108

84-81



South Union Street Historic District
Burlington, Vermont
Credit: Clare Sheppard
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: John Black House,
421 South Union Street #91
Photograph #109

84-81



84-81

South Union Street Historic District
Burlington, Vermont
Credit: Clare Sheppard
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: John J. Wright House,
415 South Union Street #92;
View Looking Northwest
Photograph #110



84-87

South Union Street Historic District
Burlington, Vermont
Credit: Clare Sheppard
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 415 South Union Street #92
View Looking Southwest
Photograph #111



South Union Street Historic District
Burlington, Vermont
Credit: Clare Sheppard
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Haynes House, 409 South
Union Street #93; View Looking West
Photograph #112

84-81



South Union Street Historic District
Burlington, Vermont
Credit: Clare Sheppard
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Weaver House,
401-405 South Union Street #94;
View Looking Northwest
Photograph #113

84-81



84-81

South Union Street Historic District
Burlington, Vermont
Credit: Clare Sheppard
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Hobart J. Shanley House,
391 South Union Street #95
View Looking Southwest
Photograph #114



84-77

South Union Street Historic District
Burlington, Vermont
Credit: Clare Sheppard
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 391 South Union Street
#95A; View Looking Southwest
Photograph #115



South Union Street Historic District
Burlington, Vermont
Credit: Clare Sheppard
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 387 South Union Street #96
View Looking West
Photograph #116

84-77



South Union Street Historic District
Burlington, Vermont
Credit: Clare Sheppard
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: William Weaver House
381 South Union Street #97;
View Looking Northwest
Photograph #117

84-77



84-77

South Union Street Historic District
Burlington, Vermont
Credit: Clare Sheppard
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: H.K. Weaver House,
375 South Union Street #98;
View Looking West
Photograph #118



84-77-8A

South Union Street Historic District
Burlington, Vermont
Credit: Clare Sheppard
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 375 South Union Street
#98A; View Looking Northwest
Photograph #119



South Union Street Historic District
Burlington, Vermont
Credit: Clare Sheppard
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Frank Boynton House,
369 South Union Street #99;
View Looking West
Photograph #120

84-77



South Union Street Historic District
Burlington, Vermont
Credit: Clare Sheppard
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 361 South Union Street
#100; View Looking Southwest
Photograph #121

84-77



84-77

South Union Street Historic District
Burlington, Vermont
Credit: Clare Sheppard
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: William Walker House
355 South Union Street #101;
View Looking Northwest
Photograph #122



84-77

South Union Street Historic District
Burlington, Vermont
Credit: Clare Sheppard
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: John B. Seymour House
347 South Union Street #102;
View Looking Northwest
Photograph #123



877-20
South Union Street Historic District
Burlington, Vermont

Credit: David Tansey

Date: March, 1988

Negative Filed at Vermont Division for
Historic Preservation

Description: H.O. Wheeler House

355 South Union Street #103;

View Looking Northwest

Photograph #124



South Union Street Historic District
Burlington, Vermont
Credit: Lisa Schaeffer
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: F.H. Parker House
325 South Union Street #104;
View Looking Northeast
Photograph #125

84-72



84-72

South Union Street Historic District
Burlington, Vermont
Credit: Lisa Schaeffer
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: C.L. Greene House
319 South Union Street #105;
View Looking Southeast
Photograph #126



84-72

South Union Street Historic District
Burlington, Vermont
Credit: Lisa Schaeffer
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: John Griffin House
311 South Union Street #107
Photograph #127



South Union Street Historic District
Burlington, Vermont
Credit: Lisa Schoeffer
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: George D. Wright House
305 South Union Street, #108;
View Looking Southeast
Photograph #128

88-72



South Union Street Historic District
Burlington, Vermont
Credit: Lisa Schaeffer
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Henry R. Conger House
299 South Union Street #109;
View Looking Northeast
Photograph #129

84-72



84-72

South Union Street Historic District
Burlington, Vermont
Credit: Lisa Schaeffer
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Henry Hickok House
291 South Union Street #110;
View Looking Southeast
Photograph #130



84-72

South Union Street Historic District
Burlington, Vermont
Credit: Lisa Schaeffer
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Dr. J.H. Linsley House
283 South Union Street #111;
View Looking Northeast
Photograph #131



South Union Street Historic District
Burlington, Vermont
Credit: Lisa Schaeffer
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 271-275 South Union Street
#112; View Looking Southeast
Photograph #132

84-72



South Union Street Historic District
Burlington, Vermont
Credit: Lisa Schaeffer
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: William G. Shaw House
257 South Union Street #113 & #113A;
View Looking Southeast
Photograph #133

84-72



84-72

South Union Street Historic District
Burlington, Vermont
Credit: Lisa Schaeffer
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Henry Shaw House
251-253 South Union Street #114;
View Looking Northeast
Photograph #134



84-72

South Union Street Historic District
Burlington, Vermont
Credit: Lisa Schaeffer
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: 239 South Union Street
#115; View Looking Southeast
Photograph #135



South Union Street Historic District
Burlington, Vermont
Credit: Lisa Schaeffer
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Dr. Lewis House
231 South Union Street #116;
View Looking Southeast
Photograph #136



South Union Street Historic District
Burlington, Vermont
Credit: Lauren Murphy
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Hilar Roby House,
217 South Union Street #117;
View Looking West
Photograph #137

84-76



84-76

South Union Street Historic District
Burlington, Vermont
Credit: Lauren Murphy
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Charles Ordway House
207 South Union Street #118;
View Looking West
Photograph #138



88-A-20

South Union Street Historic District
Burlington, Vermont
Credit: David Tansey
Date: March, 1988
Negative Filed at Vermont Division for
Historic Preservation
Description: 207 1/2 South Union Street
#119; View Looking Northwest
Photograph #139



South Union Street Historic District
Burlington, Vermont
Credit: Lauren Murphy
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Henry Ballard House,
199 South Union Street #120;
View Looking West
Photograph #140



South Union Street Historic District
Burlington, Vermont
Credit: Lauren Murphy
Date: February, 1984
Negative Filed at Vermont Division for
Historic Preservation
Description: Johonott House,
193-195 South Union Street #121;
View Looking West
Photograph #141

84-76