1. Name of Resource:

2. Original Owner: Unknown 3. Other Names:

4. Prehistoric Site

6. Owner's Name:

8. Evaluation: NR 9. Recognition & Date: Nat.Landmark

10. N.R.Status & Date:

Thematic Name: 12. Historical Theme:

13. Statement of Significance:

do not compromise its form.

11. N.R.Group:

John Cook 7. Owner's Address:

5. Location:

NOV 1 5 1988

68

 $\sum_{i=1}^{n} a_{i} = \frac{1}{2}$

KENTUCKY HISTORIC RESOURCES Individual

Individual Inve		Shelby County
Name of Resource: Redmon House	16. Date: Original Building	c. 1850 [6]
Original Owner:	Addition C. 1	980 [1]
Unknown	17. Style:	
Other Names: None	Antebellum Vern	acular [3V]
Prehistoric Site X Building Object Historic Site Structure Other	18. Architect/Builder: Unknown	
Location:	19. No. of Stories:	2 [2.0]
East side KY 395, 2 mi. N of Bagdad	20. Original Floor Plan:	
Owner's Name:	Dogtrot	[DT]
Owner's Name:	21. Single Pile X Do	uble Pile N.A.
T-1 - 0 - 1	The state of the s	<u> </u>
John Cook P P P P P P P P P P P P P P P P P P	Gable, standing seam 23. Structural Material:	metanot Original
Owner's Audress:		r - 1
Route 1, Box 318 Bagdad, KY 40083	Log(hewn) 24. Exterior Material:	<u> </u>
	24. Exterior Material: Sawn weatherbo	ard [W]
Evaluation: NR I N I Recognition & Date:	25. Foundation Material	
Nat.Landmark Local Landmark	Stone, rubble	r S j
Nat.Register HABS/HAER	26. Major Alterations:	None
Highway Marker KY Inventory 8-15-80	Moved/Rebuilt	Other
KY Landmark Certificate	X Additions	o tino.
). N.R.Status & Date:	27. Special Features:	
. N.R.Group:	None	
District Name: []	28. Outbuildings:	
Mult.Resource Area: Shelby County []	None	[0]
Thematic Name:	29. Original Function:	
2. Historical Theme:		single dwelling[01A]
Primary: Architecture [030]	30. Present Use:	
Secondary: []	As above	[01A]
Other: []	31. Condition: Excellent	
3. Statement of Significance:	Excellent	[^E]
This property is significant under criteria	32. Endangered:	Yes
C as a rare example of the log dogtrot	_	No X
form in Shelby County. Only one other dogtrot	33. Attach Photos:	
plan is recorded and it has been altered beyond recognition. Alterations to the structure	Roll: Photo No	s: No. of Slides:

14. History:

Property was occupied by Bohanon family in 1872. Owned by R.M. Redmon in 1882.

15. Source of historical information and/or contact person: Interview with Mrs. John Cook, February 1986. Atlas of Henry and Shelby Counties, KY, 1882.

34.	Prepared by:	C. Worsham		
35.	Organization:	V, Shelby Co.	Hist.	Society
36.	Date: Feb	ruary 1986		
37.	New Survey	Resur	vev 😽	

KENTUCKY HISTORIC RESOURCES Individual Inventory Form


Resource	#	68	
nesum ce	•		

38.	UTM Point of Primary Building: Quadrant: No. Pleasurevill	Zone e _1 <u>6</u>	Easting 6 6 9 6 8 0	Northing 4 2 3 9 2 6 0		G.I.S. Mod. Coordi.Accuracy	[]
41.	UTM Points of Boundary (for N. R. eligible sites only):							
	A. B C.	<u>-</u>	D E F					

42. Total Acreage in Present Property: 137 43. Acreage included in proposed N.R. boundary: 0.42 44. Site Plan (and boundary description and justification for N.R. sites):

Beginning at A, in a corner of the drive, S 150' along the drive to B, W 120' along a fence to C, NW 100'with a fence to D, at KY 395, NE 100'along the east side of KY 395 to E, E 120' along the drive to the point of origin. Boundaries drawn to encompass the house and domestic space as defined by fences and drive as separate from fields. No contributing outbuildings.

Point A is at the intersection of a fence with the southern edge of the drive and is 83 feet north northeast of the northeastern corner of the ell.



45. Description and House Plan:

Exterior

2-story, 3-bay log dogtrot with exterior stone end chimneys, rubble stone foundation, weatherbord, frame one-story replaced c. 1980 with brick veneer ell of same shape and proportions, hipped roof porch on brick piers 20th century, original 6/6 sash

Interior

Logs exposed in rear of house inside connection to ell, ell designed as self-contained unit for modern living so that log portion may be left intact, Greek Revival mantel in south log pen, mantel removed and closet added in north pen, high baseboard in north pen, low baseboard with no bead in south room, baseboard profiles similar in both pens and dogtrot, square open wall stair in dogtrot, earred on surrounds in dogtrot.

The boundaries enclose one contributing building.

