

WALTON HOTEL Monroe, Walton County, Georgia Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description(1 of 8): Front facade and south side; photographer facing northeast.



WALTON HOTEL Monroe, Walton County, Georgia Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description (2 of 8): Front facade and north side; photographer facing southeast



WALTON HOTEL Monroe, Walton County, Georgia Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description (3 of 8): North side and rear of building; photographer facing south-

west.



WALTON HOTEL Monroe, Walton County, Georgia Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description (4 of 8): Rear of building and north side; photographer facing northwest.



WALTON HOTEL Monroe, Walton County, Georgia Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description (5 of 8): Second floor hall with stairway; photographer facing northwest.



WALTON HOTEL Monroe, Walton County, Georgia Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description (6 of 8): Second floor hall, stairway; photographer facing south.



WALTON HOTEL. Monroe, Walton County, Georgia Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description (7 of 8): Third floor hall, detail of bathroom door and interior window; photographer facing south.



WALTON HOTEL Monroe, Walton County, Georgia Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description (8 of 8): Third floor hotel room; photographer facing northeast.