



Ellsworth-Jones Bldg  
511 Washington, Iowa Falls  
Hardin County, Iowa

Frank McCord

Winter 1992-93

SWSE (HPB)

3/4 view of facade, looking SW

#1



Ellsworth-Jones Bldg  
511 Washington Ave, Iowa Falls  
Hardin County, Iowa

Frank McCord

Winter 1992-93

SHSI (HPB)

Detail: 2<sup>nd</sup> & 3<sup>rd</sup> floor of facade, looking S  
#2




Ellsworth-Jones Bldg  
511 Washington Ave, Iowa Falls  
Hardin County, Iowa

Frank McCord

Winter 1992-93

SHSI (HPB)

3/4 view of rear elevation, looking NW  
#3



Ellsworth-Jones Bldg  
511 Washington Ave, Iowa Falls  
Hardin County, Iowa

Frank McCord

Winter 1992-93

SHSI (HPB)

Interior: Detail of fireplace in front office (1<sup>st</sup> floor)  
looking E

#4



ELLSWORTH & JONES.

Eng. Safe Co.



Ellsworth - Jones Bldg  
511 Washington Ave, Iowa Falls  
Hardin County, Iowa


Frank McCord

Winter 1992-93

SMSE (HPB)

Interior: Looking N through the vault

#5



Ellsworth-Jones Bldg  
511 Washington Ave, Iowa Falls  
Hardin County, Iowa

Frank McCord

Winter 1992-93

SHSI (N-PB)

Interior: detail of woodwork

#6



Ellsworth-Jones Bldg  
511 Washington Ave, Iowa Falls  
Hardin County, Iowa

Frank McCord

Winter 1992-93

SHSI (HPB)

Interior; Detail of mural of Ellsworth properties  
#7