

JUL 3 1 1978

Gloria Mills February 1977 Kentucky Heritage Commission Frankfort, Kentucky

Photo 1.3 Main facade viewed from east. Note projection of dormers on north and south.



JUL 3 1 1978

Gloria Mills February 1977 Kentucky Heritage Commission Fr**a**nkfort, Kentucky

Photo 2. View from south-west.



JUL 3 1 1978


Gloria Mills February 1977 Kentucky Heritage Commission Frankfort, Kentucky

Photo 3. North side.



Gloria Mills
February 1977
Kentucky Heritage Commission
Frankfort, Kentucky

Photo 4. Portion of western ends showing additions.



Gloria Mills February 1977 Kentucky Heritage Commission Frankfort, **K**entucky

Photo 5. Original mantel on second floor.



Gloria Mills
February 1977
Kentucky Heritage Commission
Frankfort, Kentucky

Photo 6. Fireplace installed in 1910.



Gloria Mills February 1977 Kentucky Heritage Commission Frankfort, Kentucky

Photo 7. First floor mantel with cast-iron components.



Gloria Mills February 1977 Kentucky Heritage Commission Frankfort, Kentucky

Photo 8. First floor mantel and chimney-piece of cherry.



Gloria Mills February 1977 Kentucky Heritage Commission Frankfort, Kentucky

Photo 9. Ca. 1895 staircase in first floor's central hall.



Gloria Mills
February 1977
Kentucky Heritage Commission
Frankfort, Kentucky

Photo 10. Stained glass windows of second floor.



Gloria Mills JUL 31 1978 February 1977 Kentucky Heritage Commission Frankfort, Kentucky

Photo 11. Second floor's passage from stair landing to hall.