



Calvary Baptist Church

Oklahoma City, OK

Don Simmons - 1978

813 NE 23 OK City OK

1) Exterior from

8/16/78

NEW OR

EX - 19 1978



SIMMONS STUDIO  
OKLA. CITY, OKLA.

Calvary Baptist Church

OKlahoma City, Oklahom

Don Simmons - 1978


813 NE 23 OK City OK

2) Exterior from NW

1978

NOV 1978

DEC 19 1978



SIMMONS STUDIO  
CINCINNATI, OHIO, OHIO

Calvary Baptist Church  
OKlahoma City, Oklahoma  
Don Simmons - 1978

813 NE 23 OK City OK

3) Unusual cross-shaped  
skylight in stained  
glas

**NOV 6 1978**  
**DEC 19 1978**



553

BY PU

W. H. H. H.

SIMMONS STUDIO  
ORCA CITY, ORCA

NOV 6 1978

Calvary Baptist Church  
Oklahoma City, Oklahoma  
Don Simmons - 1978

813 NE 23 OK City, OK

4) Unusual black figures  
in stained glass in  
W (front) wall at  
back of sanctuary

OKC 19 1978





SIMMONS STUDIO  
ORCA, CHY, ORCA

NOV 6 1978

Calvary Baptist Church  
Oklahoma City, Oklahoma  
Don Simmons - 1978  
813 NE 23 - OK City OK

5) S view of interior  
with pulpit area (L)  
and double bank of  
stained glass windows

DEC 19 1978