



WESTOVER

Milledgeville, Baldwin County, GA.

Photographer: James R. Lockhart

Negative Filed: Georgia Department of
Natural Resources

Date: October, 1985.

Description: 1 of 17): Main house and
front gardens. Photographer facing
southeast.



WESTOVER

Milledgeville, Baldwin County, GA.

Photographer: James R. Lockhart

Negative Filed: Georgia Department of
Natural Resources

Date: October, 1985.

Description: 2 of 17): Main house and
side gardens. Photographer facing east.



WESTOVER

Milledgeville, Baldwin County, GA.

Photographer: James R. Lockhart

Negative Filed: Georgia Department of
Natural Resources

Date: October, 1985.

Description: 3 of 17): Main house (rear),
garage/apartment, kitchen. Photographer
facing northwest.



WESTOVER

Milledgeville, Baldwin County, GA.

Photographer: James R. Lockhart

Negative Filed: Georgia Department of
Natural Resources

Date: October, 1985.

Description: 4 of 17): Plantation office.

Photographer facing east.



WESTOVER

Milledgeville, Baldwin County, GA.

Photographer: James R. Lockhart

Negative Filed: Georgia Department of
Natural Resources

Date: October, 1985.

Description: 5 of 17): Front gardens,
circular Path/drive. Photographer facing
south



WESTOVER

Millledgeville, Baldwin County, GA.

Photographer: James R. Lockhart

Negative Filed: Georgia Department of
Natural Resources

Date: October, 1985.

Description: 6 of 17): Front gardens,
from 2nd floor balcony of house, showing
remains of formal boxwood garden. Photo-
grapher facing west.



WESTOVER

Milledgeville, Baldwin County, GA.

Photographer: James R. Lockhart

Negative Filed: Georgia Department of
Natural Resources

Date: October, 1985.

Description: 7 of 17): Front gardens,
from 2nd floor balcony of house, showing
front path. Photographer facing northwest.



WESTOVER

Milledgeville, Baldwin County, GA.

Photographer: James R. Lockhart

Negative Filed: Georgia Department of
Natural Resources

Date: October, 1985.

Description: 8 of 17): Cistern, north-
east of house. Photographer facing north.



WESTOVER

Milledgeville, Baldwin County, GA.

Photographer: James R. Lockhart

Negative Filed: Georgia Department of
Natural Resources

Date: October, 1985.

Description: 9 of 17): Kitchen, (play-
house) and garage/apartment. Photographer
facing northwest.



WESTOVER

Milledgeville, Baldwin County, GA.

Photographer: James R. Lockhart

Negative Filed: Georgia Department of
Natural Resources

Date: October, 1985.

Description: 10 of 17): Plantation
office. Photographer facing west.



WESTOVER

Milledgeville, Baldwin County, GA.

Photographer: James R. Lockhart

Negative Filed: Georgia Department of
Natural Resources

Date: October, 1985.

Description: 11 of 17): Smoke house
(foreground), wash house site, well house,
& commissary (background). Photographer
facing north.



WESTOVER

Milledgeville, Baldwin County, GA.

Photographer: James R. Lockhart

Negative Filed: Georgia Department of
Natural Resources

Date: October, 1985.

Description: 12 of 17): Outbuildings
(smokehouse, left; kitchen, wash^house
site, well house, center; commissary,
right. Photographer facing southwest.



WESTOVER

Milledgeville, Baldwin County, GA.

Photographer: James R. Lockhart

Negative Filed: Georgia Department of
Natural Resources

Date: October, 1985.

Description: 13 of 17): Kitchen (Garden
House), Smokehouse to rear. Photographer
facing north.



WESTOVER

Milledgeville, Baldwin County, GA.

Photographer: James R. Lockhart

Negative Filed: Georgia Department of
Natural Resources

Date: October, 1985.

Description: 14 of 17): Fence, front
yard. Photographer facing northwest.



WESTOVER

Milledgeville, Baldwin County, GA.

Photographer: James R. Lockhart

Negative Filed: Georgia Department of
Natural Resources

Date: October, 1985.

Description: 15 of 17): Spring house.

Photographer facing southeast.



WESTOVER

Milledgeville, Baldwin County, GA.

Photographer: James R. Lockhart

Negative Filed: Georgia Department of
Natural Resources

Date: October, 1985.

Description: 16 of 17): Slave house.

Photographer facing south.



WESTOVER

Milledgeville, Baldwin County, GA.

Photographer: James R. Lockhart

Negative Filed: Georgia Department of
Natural Resources

Date: October, 1985.

Description: 17 of 17): Slave house.

Photographer facing west.