



1. Bisbee Women's Club Aug. 1981

This is a view of the front of the building facing South. I am standing on Ledge Ave. To my left is Cross Ave.

You clearly see the double front door and the windows on either side. Also the dormer, the front porch and part of the roof.

Note the planting which we have done recently

1. Bisbee Woman's Club Clubhouse
2. Bisbee, Arizona
3. Photo By: Art Small
4. Photo Date: August 1981
5. Negative At: Arizona SHPO
6. North elevation looking south
7. Photo 1 of 7



3. Bisbee Woman's Club Aug, 1981

I am standing on the corner of Hodge and Cross Avenues. I am facing the east side and the front, with a view of the work to the entry.

Note the doorway. Also again I point out the planting.

The tall building to the right is the Cochise County Courthouse. It houses many county offices.

1. Bisbee Woman's Club Clubhouse
2. Bisbee, Arizona
3. Photo By: Art Small
4. Photo Date: August 1981
5. Negative At: Arizona SHPO
6. Perspective of north and east elevations looking southwest
7. Photo 2 of 7



NO PARKING

NO PARKING

RESTRICTED
PARKING
HANDICAPPED
AND
COUNTY CARRIERS
ONLY

2. Bisbee Woman's Club - Aug. 1981

I am standing at the northwest corner of the building, facing the front. My position is on Ledge Ave. Just the corner where Ledge crosses Cross St. I am facing the double front door that leads into the Pentry Hall. There are rooms of the same size on each side of the entry. This view clearly shows the west side of the building with the fireplace and the many windows.

Notice also, the planting we have recently done.

This is be

1. Bisbee Woman's Club Clubhouse
2. Bisbee, Arizona
3. Photo By: Art Small
4. Photo Date: August 1981
5. Negative At: Arizona SHPO
6. Perspective of north and west elevations looking southeast
7. Photo 3 of 7



4 Bisbee Woman's Club Aug 1981

I am standing on Cross Ave near the rear of the building. This shows the kitchen door and the window in the South wall, over the kitchen sink. Part of this kitchen was added on when we did some remodeling. This view was taken before we painted. You can see the damaged wood. If you look closely you can see where there is some damage to the East wall caused by plumbing pipes.

1. Bisbee Woman's Club Clubhouse
2. Bisbee, Arizona
3. Photo By: Art Small
4. Photo Date: August 1981
5. Negative At: Arizona SHPO
6. Perspective of south and east elevations looking northwest
7. Photo 4 of 7



5. Bisbee Woman's Club Clubhouse Aug 1981

This is a view from just inside the entrance showing the large meeting room, the stage with its proscenium arch. In the center of the stage is the Knobe Baby Grand piano. It was a gift from one of the officials of Phelps Dodge Co. and is one of two in Bisbee and a rare one. On either side are doors - the left goes to the kitchen and the right to the powder room. Also in the room. Also in the paintings - gifts I am selling I am wearing a ha Schern, Pres.

1. Bisbee Woman's Club Clubhouse
2. Bisbee, Arizona
3. Photo By: Art Small
4. Photo Date: August 1981
5. Negative At: Arizona SHPO
6. Interior - Meeting Room, looking south
7. Photo 5 of 7



6. Bisbee Woman's Club. Aug 1981

This is a view of the West wall of the large meeting room. It shows the fireplace and some of the windows as well as the doors to the front rooms and entrance. Sam standing near the kitchen doors.

Carmen Graham, Ch. Nest Comm.
1981

1. Bisbee Woman's Club Clubhouse
2. Bisbee, Arizona
3. Photo By: Art Small
4. Photo Date: August 1981
5. Negative At: Arizona SHPO
6. Interior - Meeting Room, looking northwest
7. Photo 6 of 7



7. Bisbee woman's Club Aug 1981

This is an interior view facing north or toward the entry hall and the room on either side of it. It also shows the northeast corner of the large meeting room, the beautified wood floor we installed, some windows and a view of the ceiling tile which is relatively new. I am standing near the south of the room close to the stage

1. Bisbee Woman's Club Clubhouse
2. Bisbee, Arizona
3. Photo By: Art Small
4. Photo Date: August 1981
5. Negative At: Arizona SHPO
6. Interior - Meeting Room, looking northeast
7. Photo 7 of 7