

Photographer: Date: 1979 Warren Jagger

Negative filed at: Rhode Island Historical

Preservation Commission

150 Benefit Street Providence, RI

View from the southwest.



Photographer: Warren Jagger Date: 1983

Negative filed at: Rhode Island Historical

Preservation Commission

150 Benefit Street Providence, RI

View: Southeast parlor.



Photographer: Warren Jagger

Date: 1983

Negative filed at: Rhode Island Historical

Preservation Commission

150 Benefit Street

Providence, RI

View: Southwest parlor.



Photographer: Warren Jagger


Date: 1983

Negative filed at: Rhode Island Historical

Preservation Commission

150 Benefit Street Providence, RI

View: Southwest parlor, cornice.



Photographer: Warren Jagger Date: 1983

Negative filed at: Rhode Island Historical

Preservation Commission

150 Benefit Street Providence, RI

View: Southwest parlor, ceiling painting.



Photographer: Warren Jagger

Date: 1983

Negative filed at: Rhode Island Historical

Preservation Commission

150 Benefit Street Providence, RI

View: Southeast parlor ceiling.