



PHOTO #1 FEB 26 1979  
LAUGHLIN/SHADY FARM  
WINDSOR, CA. VIEW

Front of house, fence and  
entrance gate.

Taken from West side of  
property looking East.

APR 9 1979

PHOTOGRAPHER  
AND HOLDER OF NEGATIVES  
DAN PETERSON, AIA  
ARCHITECT  
NOVEMBER 1978

Laughlin, JAMES H. + FRANCES E. HOUSE  
SONOMA County



Laughlin, JAMES H. + FRANCES E. HOUSE  
SONOMA COUNTY

FEB 26 1979

PHOTO #2  
LAUGHLIN/SHADY FARM  
WINDSOR, CA. VIEW

West side or front of  
house.

Veranda on right is  
original, closed-in in  
the 1950's.

APR 9 1979

PHOTOGRAPHER  
AND HOLDER OF NEGATIVES  
DAN PETERSON, AIA  
ARCHITECT  
NOVEMBER 1978



Laughlin, JAMES H. & FRANCES E. HOUSE  
SONOMA COUNTY

FEB 26 1979

PHOTO #3  
LAUGHLIN/SHADY FARM  
WINDSOR, CA. VIEW

North side of house, in

original condition  
including picket fence  
in the foreground.

APR 9 1979

PHOTOGRAPHER  
AND HOLDER OF NEGATIVES  
DAN PETERSON, AIA  
ARCHITECT  
NOVEMBER 1978



Laughlin, JAMES H. & FRANCES E. HOUSE  
SONOMA COUNTY

FEB 26 1979

PHOTO #4  
LAUGHLIN/SHADY FARM  
WINDSOR CA. VIEW

South side of the house,

unaltered except for  
enclosed veranda (1950').

PHOTOGRAPHER  
AND HOLDER OF NEGATIVES  
DAN PETERSON, AIA

ARCHITECT APR 9 1979  
NOVEMBER 1978



SHADY FARM  
1855



Laughlin, James H. & Frances E. House  
Sond MA County

PHOTO #5  
LAUGHLIN/SHADY FARM  
WINDSOR, CA. VIEW

Original entrance gate  
with original hardware.  
Barn in background one  
of four agricultural  
structures.

FEB 26 1979

PHOTOGRAPHER  
AND HOLDER OF NEGATIVES  
DAN PETERSON, AIA

APR 9 1978 ARCHITECT  
NOVEMBER 1978



Laughlin, James H. & Frances E. House  
SONOMA County

PHOTO #6  
LAUGHLIN/SHADY FARM  
WINDSOR, CA. VIEW

East side of house (rear),  
showing one of the four

accessary buildings, plus  
water tower on left.

APR 9 1979

FEB 26 1979

PHOTOGRAPHER  
AND HOLDER OF NEGATIVES  
DAN PETERSON, AIA  
ARCHITECT  
NOVEMBER 1978



Laughlin, JAMES H. + FRANCES E. HOUSE  
SONOMA County

PHOTO #7 FEB 26 1979  
LAUGHLIN/SHADY FARM  
WINDSOR, CA. VIEW

Interior of Dining Room,

original fireplace, typical  
wainscoating, 4 panel doors  
and pull down kerosene  
lamp fixture. Unaltered  
except for wall paper.

PHOTOGRAPHER  
AND HOLDER OF NEGATIVES  
DAN PETERSON, AIA  
ARCHITECT  
NOVEMBER 1978

APR 9 1979



Laughlin, James H. + Frances E. House  
Sonoma County

FEB 26 1979

PHOTO #8  
LAUGHLIN/SHADY FARM  
WINDSOR, CA. VIEW

~~Original metal fireplace~~  
in parlor (unaltered) with  
pull down kerosene lamp  
and ceiling medallion and  
elaborate graining.

PHOTOGRAPHER  
AND HOLDER OF NEGATIVES  
DAN PETERSON, AIA  
ARCHITECT  
NOVEMBER 1978

APR 9 1979