



1. Willoughby Gregory House
2. Highway 274 and Krausland Road, Vicinity of Quincy (Gadsden County) Florida
3. Larry Paarlberg
4. July 1983
5. Florida Division of Archives, History and Records Management
6. Gregory House from the end of Krausland Road
7. Photo 1 of 8



1. Willoughby Gregory House
2. Highway 274 and Krausland Road, vicinity of Quincy (Gadsden County) Florida
3. Larry Paarlberg
4. July 1983
5. Florida Division of Archives, History and Records Management
6. North (main) facade
7. Photo 2 of 8



1. Willoughby Gregory House
2. Highway 274 and Krausland Road, Vicinity of Quincy (Gadsden County) Florida
3. Larry Paarlberg
4. July 1983
5. Florida Division of Archives, History and Records Management
6. North and east facade
7. Photo 3 of 8



1. Willoughby Gregory House
2. Highway 274 and Krausland Road, Vicinity of Quincy  
(Gadsden County) Florida
3. Larry Paarlberg
4. July 1983
5. Florida Division of Archives, History and  
Records Management
6. west facade
7. Photo 4 of 8





1. Willoughby Gregory House
2. Highway 274 and Krausland Road, Vicinity of Quincy (Gadsden County) Florida
3. Larry Paarlberg
4. July 1983
5. Florida Division of Archives, History and Records Management
6. south facade
7. Photo 5 of 8



1. Willoughby Gregory House
2. Highway 274 and Krausland Road, Vicinity of Quincy (Gadsden County) Florida
3. Larry Paarlberg
4. July 1983
5. Florida Division of Archives, History and Records Management
6. Detail of paneled reveal for interior doors
7. Photo 6 of 8



1. Willoughby Gregory House
2. Highway 274 and Krausland Road, Vicinity of Quincy (Gadsden County) Florida
3. Larry Paarlberg
4. July 1983
5. Florida Division of Archives, History and Records Management
6. Fireplace typical of those found throughout building
7. Photo 7 of 8



1. Willoughby Gregory House
2. Highway 274 and Krausland Road, Vicinity of Quincy (Gadsden County) Florida
3. Larry Paarlberg
4. July 1983
5. Florida Division of Archives, History and Records Management
6. second floor hallway and doors to balcony.  
Note thickness of interior walls, trim around openings and stairway.
7. Photo 8 of 8