

Bettie L. Kerr, Historic Commission 253 Market Street Lexington, KY 40508 September 1980

Photo 1 of 7
Sayre School looking northeast




Bettie L. Kerr, Historic Commission 253 Market Street Lexington, Kentucky 40508 September 1980

Photo 2 of 7 Interior of front entrance of Sayre School showing pilasters, transom and sidelights



Bettie L. Kerr, Historic Commission 253 Market Street Lexington, Kentucky 40508 September 1980

Photo 3 of 7 Stair in central hall and rear door of central hall



Bettie L. Kerr, Historic Commission 253 Market Street Lexington, KY 40508 September 1980

Photo 4 of 7
Frieze in double parlors with Anthemion crown molding.



Bettie L. Kerr, Historic Commission 253 Market Street Lexington, Kentucky 40508 September 1980

Photo 5 of 7
Parlor mantel with incized panels and Tudor arch opening



Bettie L. Kerr, Historic Commission 253 Market Street Lexington, Kentucky 40508 September 1980

Photo 6 of 7 Greek "earred" doorframes with chevron jambs on second floor



Bettie L. Kerr, Historic Commission 253 Market Street Lexington, Kentucky 40508 September 1980

Photo 7 of 7
Parlor ceiling recessed modillion
panel