



Remington - Williamson Farm

Huntington, Chittenden County, VT

Photo by JACK ANDERSON, MARCH 1999

Negatives on file at VT DHP, Montpelier, VT - Vermont Division for Historic Preservation

View of the farmstead to the south
(context)

Photo #1



Remington-Williamson Farm
Huntington, Chittenden County, VT

Photo by JACK ANDERSON, MARCH 1999

Negatives on file at the VT DHP, - VERMONT DIVISION FOR HISTORIC
MONTPELIER, VT PRESERVATION

View of the farmhouse to the west

Photo #2



Remington-Williamson Farm
Huntington, Chittenden County, VT
Photo by JACK Anderson MARCH 1999

Negatives on file at the VT

Division For Historic Preservation - Vermont
Montpelier

DIVISION FOR HISTORIC
PRESERVATION

View of the farmhouse to the east

Photo #3



Remington-Williamson Farm
Nantunton, Chittenden County, VT

Photo by Jack Anderson, MARCH 1999

Negatives on file at the VT DHP, Montpelier - Vermont Division for Historic Preservation

Interior view of the farmhouse to the east

Photo #4



Remington-Williamson Farm

Huntington, Chittenden County, VT

Photo by Jack Anderson, MARCH 1999 -

Negatives on file at the VT DHP, Montpelier - VERMONT DIVISION FOR HISTORIC
PRESERVATION

View of the bank barn to the east

Photo #5



Remington-Williamson Farm
Huntington, Chittenden County, VT

Photo by JACK ANDERSON, MARCH 1999

Negatives on file at the VT DHP, - VERMONT DIVISION FOR HISTORIC
MONTPELIER PRESERVATION

View of the bank barn to the west.

Photo #6



Remington-Williamson Farm
Huntington, Chittenden County, VT

Photo by Jack Anderson, MARCH 1999

Negatives on file at VT DHP, Montpelier-Vermont Division for Historic
Preservation

View of the small barn/pole shed
to the southeast

Photo # 7