



WA-11-715

Good-Reilly House

107 E Main St.

Sharpsburg, Washington Co. MD

P. Reed

2/02

MDSHPO

South elevation, view N

1/21



WA-11-715

Good-Reilly House

107 E Main St. Sharpsburg

Washington Co, MD

P. Reed

2/02

MDSHPO

West elevation view E

2/21



Something went wrong while we were encoding this page.
Please check the log file to find out the details.

WA-11-715

Good-Reilly House

107 E Main St Sharpsburg

Washington Co, MD

P. Reed

2/02

MDSHPO

North elevation, view 8

3/21



WA-11-715

Good-Reilly House

107 E. Main St. Sharpsburg
Washington Co., MD

P Reed

2/02

MDSHPO

North elevation, view SW

4/21



WA-11-715

Good-Reilly House

107 E Main St Sharpsburg
Washington Co., MD


P. Reed

2/02

MDSHPO

rear yard, view N

5/21



ROD'S
BARBER
SHOP

WA-11-715

Good-Reilly House

107 E. Main St Sharpsburg

Washington Co., MD

P. Reed

2/02

MDSHPO

South elevation, view NW

0/21



WA-11-715

Good-Reilly House

107 E. Main St Sharpsburg
Washington Co., MD

P. Reed

2/02

MDSHPO

interior, center hall, 1st floor, view toward S entrance

7/21



WA-11-715

Good-Reilly House

107 E Main St Sharpsburg

Washington Co., MD

P. Reed

2/02

MDS HPO

Interior, SE Room, Parlor

8/21



WA-11-715

Good-Reilly House

107 E Main St. Sharpsburg
Washington Co., MD

P. Reed

2/02

MDSHPO

plaster medallion, SE room

9/21



WA-11-715

Good-Reilly House

107 E Main St Sharpsburg
Washington Co., MD

P. Reed

2/02

MDSHPO

Interior, SW Room, office

10/21



WA-11-715

Good-Reilly House

107 E Main St Sharpsburg

Washington Co., MD

P. Reed

2/02

MDSHPO

Interior, NW room, kitchen, diagonal fireplace

11/21



WA-11-715

Good-Reilly House

107 E Main St. Sharpsburg

Washington Co., MD

P. Reed

2/02

MDSHPO

Interior, NE room, diagonal fireplace + cupboard

12/21



WA-11-715

Good-Reilly House

107 E Main St. Sharpsburg
Washington Co., MD

P. Reed

2/02

MDSHPO

Door from rear hallway to NE room

13/21



WA-11-715

Good-Reilly House

107 E Main St. Sharpsburg

Washington Co., MD

P. Reed

2/02

MDSHPO

Rear entrance, hall and stairs from upper landing

14/21



WA-11-715

Good-Reilly House

107 E Main St Sharpsburg
Washington Co., MD

P. Reed

2/02

MDSHPO

Staircase

15/21



WA-11-715

Good-Reilly House

107 E Main St. Sharpsburg

Washington Co., MD


P. Reed

2/02

MDSHPO

View from rear entrance, of staircase. Note removal
of second run along right (west) wall.

16/21



WA-11-715

Good-Reilly House

107 E Main St. Sharpsburg
Washington Co., MD

P. Reed

2/02

MDSHPO

West wall of rear hall showing evidence of second run
of stairs.

17/21



WA-11-715

Good-Reilly House

107 E Main St. Sharpsburg
Washington Co., MD

P Reed

2/02

MDSHPO

Knepace, NE room, Cell 45

18/21.



WA-11-715

Good-Reilly House

107 E Main St. Sharpsburg
Washington Co., MD

P. Reed

2/02

MDSHPO

Joist System

South room, Cellar

19/21



WA-11-715

Good-Reilly House

107 E Main St. Sharpsburg
Washington Co., MD

P. Reed

2/02

MDSHPO

upper level, original door & hardware, from west room
to stair landing

20/21



WA-11-715

Good - Reilly House

107 E Main St. Sharpsburg
Washington Co., MD

P. Reed

2/02

MDSHPO

Upper level, west room, cornice molding and chair rail

21/21