



NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

STATE California	
COUNTY Ventura	
FOR NPS USE ONLY	
ENTRY NUMBER MAR 7 1975	DATE

SEE INSTRUCTIONS

1. NAME

COMMON: Mission Aqueduct

AND/OR HISTORIC: San Buenaventura Mission Aqueduct (Canada Larga Viaduct)

2. LOCATION

STREET AND NUMBER:
234 Canada Larga Rd.

CITY OR TOWN:
Ventura,

STATE: California	CODE 06	COUNTY: Ventura	CODE 711
----------------------	------------	--------------------	-------------

3. PHOTO REFERENCE


PHOTO CREDIT: Jim Isom, for Board of Supervisors

DATE OF PHOTO: August 13, 1973

NEGATIVE FILED AT: Ventura County Cultural Heritage Board
County Office Bldg., Ventura, CA 93001

4. IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC.
Looking due east along the longer surviving portion of the viaduct. Rectangle hollow man is looking at is bottom of collapsed water trough. Note buttresses, overgrowth. Tank visible over aqueduct is part of orchard installation. Pylons once held chain fence.



1082

PROPERTY OF THE NATIONAL REGISTER




NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

STATE California	
COUNTY Ventura	
FOR NPS USE ONLY	
ENTRY NUMBER MAR 7 1975	DATE

SEE INSTRUCTIONS

1. NAME			
COMMON: Mission Aqueduct			
AND/OR HISTORIC: San Buena Ventura Mission Aqueduct (Canada Larga Viaduct)			
2. LOCATION			
STREET AND NUMBER: 234 Canada Larga Rd.			
CITY OR TOWN: Ventura			
STATE: California	CODE 06	COUNTY: Ventura	CODE 111
3. PHOTO REFERENCE			
PHOTO CREDIT: Jim Isom, for Board of Supervisors			
DATE OF PHOTO: August 13, 1973			
NEGATIVE FILED AT: Ventura County Cultural Heritage Board County Office Bldg., Ventura, CA 93001			
4. IDENTIFICATION			
DESCRIBE VIEW, DIRECTION, ETC. Looking due east showing portion of aqueduct nearest creekbed, gap cut for road (no longer existing), and longest portion of aqueduct. Pylong at left once held chain fence. Note cobble construction, remains of plaster on outer surface of buttresses. Tank visible over aqueduct is part of orchard installation.			



#282

PROPERTY OF THE NATIONAL REGISTER