



Precious Blood Church Complex
Carrington and Park Avenues
Woonsocket, Rhode Island

Photographer: Susan Dynes
Date: October, 1980

Negative: Rhode Island Historical Preservation
Commission.

View: Facade of the Church, view from the southeast.

Photo #1.

NOV 17 1980



Precious Blood Church Complex
Carrington and Park Avenues
Woonsocket, Rhode Island

Photographer: Sysan Dynes
Date: October, 1980

Negative: Rhode Island Historical Preservation
Commission

View: Church and Rectory, view from the west.

Photo #2.

NOV 17 1980



Precious Blood Church Complex
Carrington and Park Avenue
Woonsocket, Rhode Island

Photographer: Susan Dynes
Date: October, 1980

Negative: Rhode Island Historical Preservation
Commission

View: School from the east with the Dauray Monument
in the foreground.

Photo #3.

NOV 17 1980



Precious Blood Church Complex
Carrington and Park Avenues
Woonsocket, Rhode Island

Photographer: Susan Dynes
Date: October, 1980

Negative: Rhode Island Historical Preservation
Commission

View: Church interior from the south.

Photo #4.

NOV 17 1980



NOV 17 1980

Precious Blood Church Complex
Carrington and Park Avenues
Woonsocket, Rhode Island

Photographer: Susan Dynes
Date: October, 1980

Negative: Rhode Island Historical Preservation
Commission.

View: Detail of east side aisle of Church, showing
column details and balcony.

Photo #5.



JESUS-MARIE CONVENT AND ACADEMY—WOONSOCKET.

Precious Blood Church Complex
Carrington and Park Avenues
Woonsocket, Rhode Island

Photographer: Susan Dynes
Date: October, 1980

Negative: Rhode Island Historical Society Library.

View: 1906 view of the Convent and School.

Photo #6.

NOV 17 1980