

NOV 9 1976

Mary Cronan January 1976 Kentucky Heritage Commission, Frankfort, Kentucky

Photo 19 Photo taken from the east showing the facade of the Daniel Rudy House. The original section of the house is on the right.



Mary Cronan January 1976 Kentucky Heritage Commission, Frankfort, Kentucky

Photo 2 Photo taken from the east showing the front of the Daniel Rudy house. The glass around the door is tinted blue.

DOE



Photographer unknown.
May 1939
MAY 19 1978

NOV 9 1976

Photo 3 Photo taken from the east showing the facade of the Daniel Rudy house. The barn that can be seen on the right has been destroyed.



NOV 9 1976

Mary Cronan January 1976 Kentucky Heritage Commission, Frankfort, Kentucky

Photo 4. Photo taken from the north of the Daniel Rudy House. The new frame garage is on the right and the brick kitchen with

brick passageway is in the center.

DOE MAY 1 9 1978



NOV 9 1970

Mary Cronan January 1976 Kentucky Heritage Commission, Frankfort, Kentucky

Photo 5.172 Photo taken from the west showing the back of the Daniel Rudy House.



Photographer unknown.

May 1939.

MAY 1 9 1978

NOV 9

1976

Photo 6. Photo taken from the west of the Daniel Rudy House. Notice the brick kitchen on the left, before the frame garage was attached.



Mary Cronan January 1976

Kentucky Heritage Commission, Frankfort, Kentucky

Photo 7 Photo taken from the north showing the facade of the John Herr House. This portion was added c. 1850.



NOV 9 1976

Mary Cronan

January 1976

Kentucky Heritage Commission,
Frankfort, Kentucky

Photo 8¹⁴² Photo taken from the south showing the oldest portion of the John Herr House. Notice the belt course that extends across the back.



Kentucky NOV 9 1976

Mary Cronan
January 1976
Kentucky Heritage Commission,
Frankfort, Kentucky

Photo 9 Photo taken from the north-west showing the west side of the John Herr House. The back section is the original portion.



Kentucky

NOV 9 1976

Mary Cronan
January 1976

MAY 19 1978

Kentucky Heritage Commission, Frankfort, Kentucky

Photo 10. Photo taken from the northeast showing the combination springhouse/servants quarters, which is located behind the John Herr House.



Mary Cronan
January 1976
Kentucky Heritage Commission,
Frankfort, Kentucky

Photo 11.42 Photo taken from the southeast of the John Herr house slave quarters. The board and batten room under the side roof was the wash room.



NOV 9 1976

Mary Cronan January 1976 Kentucky Heritage Commission, Frankfort, Kentucky

Photo 12. Photo taken from the west of the smokehouse behind the John Herr House.



HI

Robert Steinau March 1975 4519 Statton Road, Louisville

HER

Photo 13. Photo taken from the west showing the avenue in front of the Edwards-Herr House.



NOV 9 1976

Robert Steinau March 1975 4519 Statton Road, Louisville

Photo 13 a Photo taken from the west showing the facade of the Edwards-Herr House.



Photographer unknown. c. 1870s or 80s Kentucky Heritage Commission, Frankfort, Kentucky

Photo 14 Photo taken from the west showing the facade of the Edwards-Herr House.



NOV 9 1976

Photographer unknown. c. 1898 Kentucky Heritage Commission, Frankfort, Kentucky

Photo 15 Photo taken from the west showing the facade of the Edwards-Herr House.



Herr-Rudy Family Houses

Jefferson County Kentucky DXE MAY 1 9 1978

Robert Steinau NOV 9 197 March 1975 4519 Statton Road, Louisville

HER

Photo 16. Photo taken from the south showing the side elevation of the Edwards-Herr House. The back wing was added around 1900.



Robert Steinau March 1975 4519 Statton Road, Louisville

Photo $17\sqrt[4/2]{2}$ Photo taken from the east showing the back of the Edwards-Herr House.

NOV 9



MARCH - 1975

HI Herr-Rudy Family Houses
Louisville
Jefferson County
Kentucky

NOV 9 1976

Robert Steinau March 1975 4519 Statton Road, Louisville

Photo 18⁴⁴²Interior photo showing a mantel in the Edwards-Herr House.

DOE 1978



MARCH ~ 1975

Herr-Rudy Family Houses Louisville Jefferson County

Kentucky

NOV 9 1976

Robert Steinau March 1975 4519 Statton Road, Louisville

FR

Photo 19! Interior photo showing the staircase in the Edwards-90E MAY 19 1978 Herr House.



MARCH - 1975

HI Herr-Rudy Family Houses
Louisville
Jefferson County NOV 9
Kentucky

Robert Steinau March 1975 4519 Statton Road, Louisville

Photo 20 Interior photo showing the detail of a riser in the Edwards-Herr House.

AY 19 1978



MARCH - 1975

Herr-Rudy Family Houses
Louisville
Jefferson County
Kentucky

NOV 9 - 1976

DV

Robert Steinau March 1975

AFIO CLAS

4519 Statton Road, Louisville

30 C

MAY 1 9 1978

Photo 21 Interior photo of the door in the back of the hall of the Edwards-Herr House. The door opens onto the c. 1900 wing.



NOV 9 1976

Mary Cronan
September 1976
Kentucky Heritage Commission,
Frankfort, Kentucky
MAY 19 1978

Photo 22 Photo taken from the southeast showing the facade of the Vulcan Rudy House. The porch was added within the last twenty years.



NOV 9 1976

Mary Cronan September 1976 Kentucky Heritage Commission, Frankfort, Kentucky

Photo 23 Photo taken from the northeast showing the back of the Vulcan Rudy House. Notice the raised roofline on the right

which marks the addition.



NOV 9 1976

Mary Cronan
September 1976
Kentucky Heritage Commission,
Frankfort, Kentucky

MAY 1 9 197

Photo 24 Photo taken from the west showing the west elevation of the Vulcan Rudy House, where the early addition was made.



Kentucky

NOV 9 1976

Mary Cronan
September 1976
Kentucky Heritage Commission,
Frankfort, Kentucky

Photo 25, 42 Photo taken from the north showing the facade of the George Herr House. DOC.




NOV 9 1976

Mary Cronan September 1976 Kentucky Heritage Commission, Frankfort, Kentucky

Photo 26. Photo taken from the northeast of the facade of the George Herr House. The onestory wing on the left was added

c. 1945.

DDE MAY 1 9 1978



Photographer unknown. April 1945.

Kentucky Heritage Commission, Frankfort, Kentucky

Photo 27. Photo taken from the northwest of the George Herr House.



NOV 9 06 1976 MAY 1 9 1978

Photographer unknown. April 1945 Kentucky Heritage Commission, Frankfort, Kentucky

Photo 28. Photo taken from the southeast showing the rear of the George Herr House. Note the foundation and basement in the

foreground was where the 1 1/2 story frame kitchen was removed.



NOV 9 1976

Mary Cronan September 1976 Kentucky Heritage Commission, Frankfort, Kentucky

Photo 29 Photo taken from the south of the back of the George Herr House.



DOE MAY 19 1978

Photographer unknown.
April 1945
Kentucky Heritage Commission,
Frankfort, Kentucky

Photo 30 Photo taken from the south of the back of the George Herr House. The one-story wing on the right was added in 1945.



NOV 9 1976

Mary Cronan September 1976 Kentucky Heritage Commission, Frankfort, Kentucky

Photo 31 Photo taken from the southwest of the stone smokehouse located behind the George Herr House.



Mary Cronan September 1976 Kentucky Heritage Commission, Frankfort, Kentucky

Photo 32 Photo taken from the north of the two-room stone spring-house in front of the George Herr House.



NOV 9 1976

Mary Cronan September 1976 Kentucky Heritage Commission, Frankfort. Kentucky

Photo 33 1/42 Photo taken from the west of the Taylor-Herr-Oldham MAY 1 9 1978 House.



10V 9 1976

Mary Cronan
September 1976
Kentucky Heritage Commission,
Frankfort, Kentucky RC
MAY 19 1978

Photo 34 Photo taken from the south of the 1940 addition to the Taylor-Herr-Oldham House. The original portion is on the left.



NOV 9 1976

Mary Cronan September 1976 Kentucky Heritage Commission, Frankfort, Kentucky

Photo 35 Photo taken from the north of the A. G. Herr House.

MAY 19 1978



NOV 9 1976

Mary Cronan MAY 19 1978 September 1976 Kentucky Heritage Commission, Frankfort. Kentucky

Photo 36 Photo taken from the west showing the detail of the main block of the A. G. Herr House.



NOV 9 1976

Mary Cronan
September 1976
MAY 19 1978
Kentucky Heritage Commission,
Frankfort, Kentucky

Photo 38. Photo taken from the northeast showing the original side porch.



NOV 9 1976

Mary Cronan September 1976 Kentucky Heritage Commission, 104 Bridge Street, Frankfort

Photo 39. Photo taken from the north of the back of the A. G. Herr House.



NOV 9 1976

Mary Cronan MAY 19 1978
September 1976
Kentucky Heritage Commission,
Frankfort, Kentucky

Photo 40 Photo taken from the northwest showing the brick smoke-house behind the A. G. Herr House.



Mary Cronan MAY 19 1978
September 1976
Kentucky Heritage Commission,
Frankfort, Kentucky

Photo 41, Photo taken from the east of the stone cabin situated behind the A. G. Herr House.



NOV 9 1976

Mary Cronan September 1976 Kentucky Heritage Commission, Frankfort, Kentucky

Photo 42. Photo taken from the southeast of the brick slave quarters that are terraced below the A. G. House.

MAY 19 1978