NEW JERSEY OFFICE OF CULTURAL AND ENVIRONME HISTORIC PRESERVATION SECTION	AUG 2 9 1996
INDIVIDUAL STRUCTURE SURVEY FORM	HISTORIC SITES INVENTORY NO. 13
HISTORICNAME: Ackerman-Dawsmap House LOCATION: 176 East Saddle River Road	COMMON NAME BLOCK/LOT 1402/32
MUNICIPALITY: Saddle River USGG QUAD: Park Ridge OWNER/ADDRESS: Borough of Saddle River 100 East Allendale Road Saddle River, NJ 07458	COUNTY: Bergen UTM REFERENCES: Zone/Northing/Easting
DESCRIPTION A + 8: C. 1835-40	
Construction Date: C: c. 1870	Source of Date: visual
Architect: D: post-WW II	Builder: ~
Style: vernacular	Form/Plan Type: see page 3
Number of Stories: A: 1½, B: 2, C: 1½, D: 1 A: coursed ashlar except E side Foundation: C: coursed roughly squared ashl	e is rubble. 8: rubble. Jar. D: cinder block
Exterior Wall Fabric: Clapboard except N+E walls	of A have composition shingles
Fenestration: A: south side: 3 bays, N side:	2 bays, 6/6; 8 + C: 6/6
Roof/Chimneys: gables; A: interior end chim	mey at East, B: interior chimney at south
pediment;circular louvered opening in attic with shaped side boards. Interior remodele B: c. 1870 staircase, northside has Queen	d. Anne style window with colored glass. ide with doors with round-headed glazed
PHOTO Negative File No. 6-9, view lookin	9 HE, slides Map (Endicate North)
	4
	Budia-1161 - 3
	18 1 A 461
	The second secon
	3 454
	13- 1
	0 33 34
	A A A A A A A A A A A A A A A A A A A
the later of the later	and the second se
and the second se	and the second second

page 2 13 SITING, BOUNDARY DESCRIPTION, AND RELATED STRUCTURES:

Property has 5.187 acres. The house has a generous setback from the road. The gable end of section A faces the road. Along the road is a c. 1900 boulder wall with gate posts. SW of the house is a boulder well, filled-in swimming pool is at the SE.To E about 100' in recent woods is a small frame English barn with appears to date from the 1830's. It has a gable roof with central hip-roofed ventilator and is covered predominately with shiplap siding. The eastern part of the property is wooded. The house (cont.) Suburban 🖾 SURROUNDING ENVIRONMENT: Urban Scattered Buildings Agricultural 🗔 Village 🗔 Open Space Woodland Residential 🖾 Downtown Commerical 🗔 Highway Commercial Other 🗀 Industrial 🗔 Across East Saddle River Road to west is a recent 1-story shopping center in Colonial Revival style. To north are residences to south is Borough police offices in an old hous (0258-14). SIGNIFICANCE:

The Ackerman-Dewsnap House is a pleasing example of local vernacular architecture, It represents the evolution of a 3 bay wide, $1\frac{1}{2}$ story frame farm house built about 1835 into a picturesque, L-shaped late 19th century country home. On the exterior, the building largely retains is late 19th century appearance enhanced by circa 1900 landscape features such as boulder walls, gates, and well, as well as an early 19th century English The house is associated with the Ackerman family, one of Bergen County's oldest barn. families, and with the Dewsnap family, a locally interesting one.

The property was part of Garret A. Ackerman's farm. The homestead of this farm is located at 199 East Saddle River Road (BCSHS #160, 0258-16). A building appears at this site on an 1840 U.S.Coast Survey map and the 1861 Hopkin's map associates it with A. G. Ackerman.

In 1864 Ackerman sold the property to James Dewsnap who appears on 1876, 1902, and 1913 maps as its owner. According to the 1876 Atlas Dewsnap was a plumber and gas fitter. It is likely he remodelled the house and added section C (see plan) and the plan of the building on the 1876 map suggests section C had been built. It is likely James Dewsnap was the father of Walter and John P. Dewsnap, mentioned in local newspapers as New York City real tors in the 1880's and 90's specializing in selling country houses and farms (cont.)

orage

COMMENTS:

The house was recently purchased by the municipality. Its future function is unclear. To the north and east its property abuts that owned by the borough and the Selective clearing of trees near house is needed. The barn is in need school board. of maintenance and the area around it needs to be cleared of vegetation.

REFERENCES: NJHSI 0258-15 1840: U.S. Coast Survey map #132: on. 1861: Hopkins map: A. G. Ackerman. 1887 Driving Map: Dewsnap 1876 Walker Atlas: Jas Dewsnap Robinson map: Jas. Dewsnap. 1902: Bromley Atlas: J. Dewsnap. 1913: Inskeep map: A. G. Ackerman, 1852; Jas. Dewsnap 1864. 1861: Walker Atlas, p. 164. SRHC files: old photograph, notes of CK Tholl, The Landscape. (cont.) RECORDED BY: CK Tho11/TRB DATE: 1981-83 ORGANIZATION: BCHSAB/BCOC&HA

Ackerman-Dewsnap House, 176 East Saddle River Road, Saddle River

SIGNIFICANCE: (continued)

in Bergen County. James was possibly also the father of William Dewsnap, an architect who began practicing in New York City about 1899, William Dewsnap designed the H. F. Durbar House in Saddle River at 3 West Church Road (0258-54).

REFERENCES: (continued) CRT List, C. K. Tholl, "Bergen County Historic Sites Advisory Board Register of Important Structures and Sites" Survey form, April 1981. SITIME: (continued)

is surrounded by trees and shrubs.





The English barn Looking SW Neg. file # 1-2

FORM/PLAN TYPE

13 page 3



View looking morth showing section A and part of C. neg. file #6-3

showing section A neg, file # 6-6

View looking N showing sections C.B.D neg file #6-8