



FARMINGTON CANAL

Hartford & New Haven Counties, CT

HRC Photo, 4/84

Negative filed with Conn.

Hist. Comm., Hartford

Prism, south of Queen Street,
Southington, view north

2



FARMINGTON CANAL

Hartford & New Haven Counties, CT

HRC Photo, 4/84

Negative filed with Conn.

Hist. Comm., Hartford

Prism, south of Latimer Road,
Simsbury, view south

3



FARMINGTON CANAL

Hartford & New Haven Counties, CT

HRC Photo, 4/84

Negative filed with Conn.

Hist. Comm., Hartford

Feeder canal prism, north of
Sequassen Road, Farmington,
view east

4



FARMINGTON CANAL

Hartford & New Haven Counties, CT

HRC Photo, 4/84

Negative filed with Conn.

Hist. Comm., Hartford

Prism, north of Todd Street,
Hamden, view north



FARMINGTON CANAL

Hartford & New Haven Counties, CT

HRC. Photo, 4/84

Negative filed with Conn.

Hist. Comm., Hartford

Ten Mile River Culvert, Cheshire,
view west

6



FARMINGTON CANAL

Hartford & New Haven Counties, CT

HRC Photo, 4/84

Negative filed with Conn.

Hist. Comm., Hartford

Hop Brook Culvert, Simsbury, view
northwest

7



FARMINGTON CANAL
Hartford & New Haven Counties, CT

HRC Photo, 4/84
Negative filed with Conn.
Hist. Comm., Hartford

Thompson Brook Culvert, Avon,
view southeast



FARMINGTON CANAL

Hartford & New Haven Counties, CT

HRC Photo, 4/84

Negative filed with Conn.

Hist. Comm., Hartford

Eaton Brook Culvert, Hamden,
view west

9



FARMINGTON CANAL

Hartford & New Haven Counties, CT

HRC Photo, 4/84

Negative filed with Conn.

Hist. Comm., Hartford

Arch fragment, north bank, Salmon
Brook Culvert, East Granby,
view west # 10



FARMINGTON CANAL

Hartford & New Haven Counties, CT

HRC Photo, 4/84

Negative filed with Conn.

Hist. Comm., Hartford

Drain end, south of South School,
Simsbury, view southwest

11



FARMINGTON CANAL

Hartford & New Haven Counties, CT

HRC Photo, 4/84

Negative filed with Conn.

Hist. Comm., Hartford

Aqueduct abutment, west of
Farmington River, Farmington,
view west

12



FARMINGTON CANAL

Hartford & New Haven Counties, CT

HRC Photo, 4/84

Negative filed with Conn.

Hist. Comm., Hartford

Lock 10, Cheshire, view south

13



FARMINGTON CANAL

Hartford & New Haven Counties, CT

HRC Photo, 4/84

Negative filed with Conn.

Hist. Comm., Hartford

Lock 14, Hamden, view southeast

14



FARMINGTON CANAL

Hartford & New Haven Counties, CT

HRC Photo, 4/84

Negative filed with Conn.

Hist. Comm., Hartford

Lockkeeper's house at Lock 14,
Hamden, view north

15



FARMINGTON CANAL

Hartford & New Haven Counties, CT

HRC Photo, 4/84

Negative filed with Conn.

Hist. Comm., Hartford

Road bridge abutment, south of
Griffen Avenue, Granby,
view south

16



FARMINGTON CANAL

Hartford & New Haven Counties, CT

HRC Photo, 4/84

Negative filed with Conn.

Hist. Comm., Hartford

Road bridge abutment, Route 10
north of Route 44, Farmington,
view east

17



FARMINGTON CANAL

Hartford & New Haven Counties, CT

HRC Photo, 4/84

Negative filed with Conn.

Hist. Comm., Hartford

Probable waste weir fragment,
east of Brooksvale Avenue,
Hamden, view south

18



FARMINGTON CANAL

Hartford & New Haven Counties, CT

HRC Photo, 4/84

Negative filed with Conn.

Hist. Comm., Hartford

Remains of carriage spring
factory in prism north of Todd
Street, Hamden, view north # 19



FARMINGTON CANAL

Hartford & New Haven Counties, CT

HRC Photo, 4/84

Negative filed with Conn.

Hist. Comm., Hartford

Eroded canal bank, south of
Floydsville Road, East Granby,
view southeast

20



FARMINGTON CANAL

Hartford & New Haven Counties, CT

HRC Photo, 4/84

Negative filed with Conn.

Hist. Comm., Hartford

Bank reinforcement at feeder,

west of Atwater Street,

Southington, view southwest # 21