National Register of Historic Places Registration Form



617

This form is for use in nominating or requesting determinations for individual properties and districts. See instructions in How to Complete the National Register of Historic Places Registration Form (National Register Bulletin 16A). Complete each item by marking "X" in the appropriate box or by entering the information requested. If an item does not apply to the property being appropriate to the property being

. Name of Property	
historic name King-Dennis Farm	
other names/site number	177-536-1355
2. Location	
street & number 2939 King Road	<u>N/A</u> □ not for publication
city or town Centerville	
the state of the s	ne code <u>177</u> zip code <u>47330</u>
3. State/Federal Agency Certification	
As the designated authority under the National Historic Preservation Act, a request for determination of eligibility meets the documentation standar Historic Places and meets the procedural and professional requirements so meets does not meet the National Register criteria. I recommend the nationally statewide locally. (See continuation sheet for action of certifying official/Title	rds for registering properties in the National Register of et forth in 36CFR Part 60. In my opinion, the property nat this property be considered significant dditional comments.)
State or Federal agency and bureau In my opinion, the property meets does not meet the National Regionments.)	ister criteria. (See continuation sheet for additional
Signature of certifying official/Title	Date
State or Federal agency and bureau	
4. National Park Service Certification	N 00
I hereby certify that the property is: entered in the National Register. See continuation sheet.	Date of Action G - 15 OC
- · · · · · · · · · · · · · · · · · · ·	
determined eligible for the National Register	
☐ determined eligible for the	

King-Dennis Farm		Wayne		
Name of Property		County	and State	
5. Classification				
Ownership of Property (Check as many boxes as apply)	Category of Property (Check only one box)	Number of Resourc (Do not include previously		
⊠ private ☐ public-local	building district	Contributing Nor	ncontributing	
public-local public-State	site	7	2	buildings
public-Federal	structure	0	0	sites
	object	3	0	structures
		0	0	objects
		10	2	Total
Name of related multiple pro	• •	Number of contributing rein the National Register	sources previo	ously listed
N/A		0	- ·	
6. Function or Use				
Historic Functions (Enter categories from instructions)		Current Functions (Enter categories from instructions)		
DOMESTIC:	Single Dwelling	DOMESTIC: Single Dwel		le Dwelling
DOMESTIC:	Secondary Structure			dary Structure
AGRICULTURE/SUBSIST	biorage	AGRICULTURE/SUBSIS		Storage
AGRICULTURE/SUBSIST	Agricultural Outbuilding	AGRICULTURE/SUBSIS	TE Agricult	ural Outbuilding
7. Description				
Architectural Classification (Enter categories from instructions)	1	Materials (Enter categories from instructions	s)	
OTHER:	I-House (traditional)	foundation	BRIC	K
OTHER:	English Barn	walls	BRICI	
		roof	ASPHA	LT
		other	WOOD: Weat	herboard
			METAI.	Tin

Narrative Description (Describe the historic and current condition of the property on one or more continuation sheets.)

_	ennis Farm	Wayne IN
Name of	Property	County and State
8. Sta	tement of Significance	
Applic (Mark ": for Nation	able National Register Criteria "in one or more boxes for the criteria qualifying the property onal Register listing.)	Areas of Significance (Enter categories from instructions)
ΠΑ	Property is associated with events that have made a significant contribution to the broad patterns of our history.	ARCHITECTURE
В	Property is associated with the lives of persons significant in our past.	
⊠c	Property embodies the distinctive characteristics of a type, period, or method of construction or represents the work of a master, or possesses high artistic values, or represents a significant and distinguishable entity whose components lack individual distinction.	Period of Significance 1840-1950
_ D	Property has yielded, or is likely to yield, information important in prehistory or history.	
Critori	a Considerations	Significant Dates
	" in all the boxes that apply.)	1840
	Property is:	
_ A	owned by a religious institution or used for religious purposes.	Significant Person (Complete if Criterion B is marked above)
В	removed from its original location.	N/A
С	a birthplace or grave.	Cultural Affiliation
D	a cemetery.	N/A
ΠE	a reconstructed building, object, or structure.	IN/A
F	a commemorative property.	
□. □G	less than 50 years of age or achieved significance	
G	within the past 50 years.	Architect/Builder
		Unknown
Narrat (Explain	ive Statement of Significance the significance of the property on one or more continuation sheets.)	
9. Majo	or Bibliographic References	
Biblio	graphy	
	books, articles, and other sources used in preparing this form or us documentation on file (NPS):	n one or more continuation sheets.) Primary location of additional data:
	· · · · · · · · · · · · · · · · · · ·	State Historic Preservation Office
☐ preliminary determination of individual listing (36 CFR 67) has been requested		
previously listed in the National Register		Other State agency
previously determined eligible by the National Register		Federal agency
	ignated a National Historic Landmark	☐ Local government
rec	orded by Historic American Buildings Survey	☐ University ☐ Other
recorded by Historic American Engineering		-
Red	cord #	Name of repository:
		Indiana Historic Sites and Structures Inventory

King-Dennis Farm Name of Property	Wayne IN County and State
10. Geographical Data	
Acreage of Property appx. 3.6 acres	
UTM References (Place additional UTM references on a continuation sheet.)	
1	3 Zone Easting Northing
2	4
	□ See continuation sheet
Verbal Boundary Description (Describe the boundaries of the property on a continuation sheet.)	
Boundary Justification (Explain why the boundaries were selected on a continuation sheet.)	
11. Form Prepared By	
name/title John Warner	
organization Weintraut & Associates, Hist., Inc.	date 9/30/99
street & number 800 Sugarbush Ridge	telephone 317-283-5450
city or town Zionsville	state IN zip code 46077
Additional Documentation	
Submit the following items with the completed form: Continuation Sheets	
Maps	
A USGS map (7.5 or 15 minute series) indicating the partial A Sketch map for historic districts and properties have	• •
Photographs	
Representative black and white photographs of the	property.
Additional items (Check with the SHPO or FPO for any additional items)	
Property Owner	
(Complete this item at the request of SHPO or FPO.)	
name William C. and Ellen Dennis	
street & number 610 W. Main St.	telephone 317-842-0880 (business)
city or town Richmond	state IN zip code 47374

Paperwork Reduction Act Statement: This information is being collected for applications to the National Register of Historic Places to nominate properties for listing or determine eligibility for listing, to list properties and to amend existing listings. Response to this request is required to obtain a benefit in accordance with the National Historic Preservation Act, as amended (16 U.S.C. 470 et seq.).

Estimated Burden Statement: Public reporting burden for this form is estimated to average 18.1 hours per response including time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding this burden estimate or any aspect of this form to the Chief, Administrative Services Division, National Park Service, P.O. Box 37127, Washington, DC 20013-7127; and the Office of Management and Budget, Paperwork Reductions Projects (1024-0018), Washington, DC 20503.

National Register of Historic Places Continuation Sheet – King/ Dennis Farm

Sections 7, 8, 9, and 10

Page 1

Section 7 Description

The King/Dennis Farm is situated north of the city of Centerville, Wayne County, Indiana. Approximately 3.6 acres of the 180-acre farm are included in this nomination. Situated on these 3.6 acres are the following contributing resources: seven buildings, one silo, and two corn cribs. The remainder of the original acreage is cultivated under lease but is still owned by the Dennis family. The buildings, all original to the farm, are: a large two-story, brick I-house residence; a summer kitchen; a poultry house; a small barn; a livestock barn; a milk house; and an equipment barn. A large metal hay storage barn situated in the southeastern corner of the nominated property and the frame storage shed on the north side of the driveway are non-contributing. With the exception of the summer kitchen, all the contributing buildings are in good to fair condition. A site plan is attached.

The boundaries of the nominated property nearly form a triangle with the base to the east and the apex to the west and the sides to the north and south. The apex is located adjacent to King Road where it crosses a small bridge over Noland's Fork. The driveway off King Road leads into the farmstead in a generally east-west direction. The residence, on the south side of the driveway, is the first building encountered; the driveway continues east into the center of the collection of agricultural buildings. Noland's Fork, a stream that flows through the northwest quadrant of the full 180-acre parcel is north of the nominated property.

Residence

An original two-room wide, one-room deep I-house (1840) forms the nucleus of the residence with a more recent 11/2 story, wing addition on the north side.

Exterior

The two-story brick residence is sited with its gable ends generally east and west. The brick exterior walls are constructed using the Flemish-bond pattern of headers and stretchers in each row. The south or formal main façade has five ranks of double-hung, single-glazed windows (photo 1) and a simple concrete stoop that provides access to the plain paneled wooden door. The brick foundation extends above grade to accommodate a band of windows that allow light into the dirt floored basement. The window openings have flat, soldiered brick lintels and no sills. The window frames are wood on all four sides and are pegged at the corners (photo 2). The doorframe and the lintel are constructed of simple wood members. A transom light extends across the top of the opening. A plain wood frieze board appears at the roof-wall junction. The

National Register of Historic Places Continuation Sheet – King/ Dennis Farm

Sections 7, 8, 9, and 10

Page 2

moderately pitched roof is clad in diamond-shaped asphalt composition shingles. A single brick chimney rises above the roof on the west gable.

The west gable end (photo 3) contains a single rank of windows along its left edge, nearest to the added wing. Positioned in the gable peak are two fixed-frame windows that allow light into the unfinished attic space. The façade also includes basement windows.

The north façade has undergone the most significant changes. A 11/2-story wing was added at some time, circa 1890, (photos 4 and 5). The wing has brick exterior walls, a wood shingled gable end, and an enclosed porch at its northeast corner. The porch is enclosed with horizontal wood siding. On the east and west sides are small concrete stoops leading to single entry doors. The portion of the original I-house north façade has two full ranks of windows and basement windows above grade. The roof of the wing is sheathed in composition shingle. A large single door, original to the I-house residence, (photo 6- for interior view and photo 5 for exterior view), permits entry into the basement.

The east gable end is similar to the west gable in fenestration and construction.

Interior

As might be expected the interior of the original residence is relatively plain and lacking in decorative architectural detail. However, irrespective of the changes made to some of the interior and its poor condition, the house retains unquestioned integrity. From the simple, painted newel posts and balusters in the staircase between floors (photo 7) to the unadorned interior paneled doors (photo 8) and the painfully plain, probably locally produced, door casings (photo 9), a current visitor experiences a quick trip back in time. This impression is reinforced by the presence of some original door hardware (photo 10) and Greek Revival-inspired mantelpieces and modified fireboxes (photo 11). The quality of the mantelpieces indicates local craftsman accomplished the work. The shallow fireboxes, more to be expected in a late-Victorian period house, are more suited to the burning of coal rather than wood logs. The absence of an extensive hearth also indicates the likelihood the fireplaces were modified after original construction. Also of interest in photograph 11 are the built-in, full-height closets that flank the fireplace.

The interior of the wing addition includes a kitchen on the first floor and a living space directly above. The date of the construction is questionable but from an examination of the materials used and the construction of the windows and their hardware (photo 12) the time frame (1890s) is plausible. The living space is one long room with only an overhead electric light to add any sense of creature comfort. The

National Register of Historic Places Continuation Sheet – King/ Dennis Farm

Sections 7, 8, 9, and 10

Page 3

walls and ceiling of the upstairs space are constructed of a generic wallboard material. Without the presence of two doors, a small brick chimney (no longer visible from the exterior), and the windows, the kitchen space is unremarkable

The basement and the attic of the original residence offer interesting aspects of use and construction. In the east end of the dirt-floored basement, is a large fireplace (photo 13) suitable for meeting the cooking needs of the earlier tenants. Unlike the other fireplaces in the house this one retains its original design. Photograph 14 shows a portion of one of the hand-hewn timbers visible in the basement that were used to support the floors above. The roof rafters (photos 15 and 16) meet in the peak of the roof and the angles are secured by the use of a through mortise and tenon joint fixed with a large single peg, driven at right angle, through the joint.

Summer Kitchen

The summer kitchen (photo 17), located just to the east of the residence is in deteriorated condition. Constructed of dimension lumber and in the typical form of a small building, approximately 9'X12' with a large front overhang, the kitchen was used to cook meals away from the main building when the summer heat made use of the basement facility untenable. Although in poor condition, the building, circa 1895, retains sufficient integrity to warrant stabilization and eventual restoration.

Poultry House

The poultry house (photo 18), circa 1910, is located northwest of the residence across the driveway. In good condition, the building retains its integrity. Constructed on a concrete foundation, the exterior walls are vertical board siding, and the shed roof is sheathed in corrugated metal sheets. The south facing side has five, fixed-frame windows in varying degrees of repair. The glazing is two over two. A large sliding door on the east end, constructed of the same wooden siding material, provides access to the interior.

Small Barn

The small barn (photo 19), built circa 1910, is located northeast of the residence on the south side of the driveway. The 1½ story building is situated on a concrete foundation. The exterior walls are vertical board siding. There are large, double-sliding doors in both ends of the barn, and a double-hung window, glazed six over six, is centered in each gable end above the doors. The steeply pitched roof is sheathed in corrugated metal sheets. A large metal shed extension is added to the south side of the building. The interior is relatively open; the stalls or other livestock feeding structures

National Register of Historic Places Continuation Sheet – King/ Dennis Farm

Sections 7, 8, 9, and 10

Page 4

ن ع ردد ،

once integral to the building's use, have since been removed. However, the barn retains integrity sufficient to be contributing.

Livestock Barn

The livestock barn (photo 20) is the second oldest building on the property. Records are not available to accurately date the barn but from an examination of the hand-hewn, post- and- girt frame structural members, it was most likely built in the late 1860s or early 1870s. Now clad in metal siding and corrugated metal-sheet roofing and with shed additions attached to both ends, the livestock barn retains integrity irrespective of these changes to its original materials and shape. The building is situated on a concrete foundation that was likely added after the 1910s. A portion of the original foundation visible in the interior of the barn appears to have been formed by timber sills placed on native stone of various sizes. Framing members (photos 21 and 22) show marks of hand tools used to shape the logs of the original builders. Photograph 23 shows an example of a hand cut mortise and the peg hole arrangement used throughout the building to secure major construction joints.

Milk House

The milk house (photo 24) abuts the southeastern corner of the livestock barn. While the date of its construction is unclear, the building was likely built after the other outbuildings on the property, possibly in the mid-1920s. There is some documentary evidence that indicates a "milk barn" was constructed around this time. The first floor exterior walls are concrete block, and the upper portion is clad in vertical board siding. The low-pitched roof is covered with composition shingle.

Equipment Barn

The equipment barn (photo 25) was constructed about the same time as the small barn and the poultry shed. Clad with the same vertical board siding, this building is a 1story model of the small barn. With double doors in both gable ends of the building and fixed-sash windows, glazed two by three, the barn served for many years as a storage shelter for farm equipment. Loft doors are centered in the gable ends above each set of doors.

Silo

The silo (photo 26), circa 1950, is located near the northeast corner of the livestock barn for easy access. Used at one time to store fodder for farm animals, the silo no longer has the protective top that maintained the organic material in a dry and stable environment. Built of concrete on a concrete base and with a wooden, metal or

National Register of Historic Places Continuation Sheet – King/ Dennis Farm

Sections 7, 8, 9, and 10

Page 5

ceramic domed top, the silo made it possible to feed animals, particularly cows throughout the entire winter.

Corn Cribs

The two corncribs (photo 27) are typical of structures found on a Hoosier farm in the early twentieth century. Corn cribs were often constructed of wood with slatted sides to promote air circulation; these cribs are not of that variety and are not as old as many of the other elements of the farm. Built circa 1950, both cribs are constructed of wire mesh containment walls and are covered to reduce the amount of moisture reaching the stored crop thereby reducing the loss to molds or rot. The southern most crib, on the left in the photograph, appears to be a farm-fabricated structure and the other one is a commercial product seen all over the state.

Section 8 Statement of Significance

Located in CenterTownship, near the junction of Noland's Fork and King Roads, the King/Dennis Farm is one of the earliest farms established in the township; it is significant under Criterion C in the area of Architecture that embodies distinctive characteristics of a type, period, or method of construction. The period of greatest development for the county-at-large occurred during the early years of the nineteenth century and resulted in a predominance of Federal style houses in Centerville.

Labeled Federal style in a number of sources, possibly because of its lack of distinctive characteristics and its age, the residence is more accurately an example of the traditional I-house family quarters. The most recent survey of Center Township, Wayne County, conducted for the *Indiana Historic Sites and Structures Inventory* rated the residence Outstanding, one of only seven with this rating in this style remaining in the township. Unlike the King/Dennis Farm residence, most of the 47 Federal residences in the township have been altered to an extent that only very minimal stylistic details remain. Although the north wing constitutes an alteration, the house possesses significant integrity in exterior visual and physical characteristics and in interior spatial configuration. As integral components of the farm, the residence and the livestock barn in particular demonstrate the vitality and distinctive characteristics of brick and timber frame construction, respectively, in imparting a sense of permanence.

The King/Dennis Farm possesses significant historical integrity. The farm's buildings and residence retain each of the seven qualities evaluated in the assessment of integrity -- location, setting, design, materials, workmanship, feeling, and association - which characterize the property's historic period. Although a few ancillary buildings and structures have succumbed to time and weather, the remaining buildings, with their

National Register of Historic Places Continuation Sheet – King/ Dennis Farm

Sections 7, 8, 9, and 10

Page 6

integrity in purpose and design well intact, conjure historical images of Indiana's agricultural past. The extent of this integrity is such that with little imagination a visitor may easily visualize the daily family routines and farm activities that once characterized this exceptional example of Hoosier agricultural heritage; an historical image that is rapidly disappearing from our view. The King/Dennis Farm's period of significance is 1840-1950.

Although secondary in a hierarchy of significance, the King/Dennis Farm also possesses historic value for its role in the lives of two well-known Wayne County families. An example of the multi-purpose family farm that once dotted the landscape of the Midwest, the King/Dennis Farm exemplifies the agricultural development in the Hoosier state. The house and barn form the nucleus of the farmstead today as in the 1840s. Originally, the barn housed a variety of animals and equipment until the farmer built the adjoining buildings, such as the small storage barn, with more specific functions. In the twentieth century as markets for milk opened with urbanization, the farmer milked cows in the large barn and then stored the milk in the milk house before shipping to a commercial processing plant. The silo completes the picture of the twentieth century dairy function, with the fodder being fed to milk cows. A poultry house was built for the chickens that the farmer's wife tended and supplemented the family income through the sale of eggs. The corn cribs suggest a later period of agriculture during which farmers stored unshelled corn to feed animals or for later sale. Even though the pole barn is noncontributing, it too demonstrates the evolution of agriculture as farming equipment became too large for the small storage barn; modern farmers built large storage buildings for their expensive new equipment as farming began the transition to agribusiness. The King/Dennis Farm provides us with a visual image of our past agricultural heritage, symbolic of a pattern of settlement and agricultural development that defines our history.

The King/Dennis Farm is located north of Centerville, Center Township, Wayne County, Indiana. The county was organized in 1810 and was named in honor of General Anthony Wayne. In 1814, Israel Elliott, the first land patent holder in the area, donated 96 acres of land to Centerville for the purposes of establishing the county seat there. Centerville was chosen because its location was the approximate center of the county. Many of the first settlers in the county were members of the Society of Friends from Virginia and the Carolinas.

Centerville was prominent in the economic and commercial growth of Wayne County for over five decades. One of the first events that sparked economic growth in Centerville was the opening of the National Road, which is also Centerville's main eastwest street, in 1828. By 1836, as many as 100 wagons per week were passing through Centerville carrying commercial goods and agricultural production in and out of Indiana. Farmers in the area were quickly connected with larger commercial markets.

National Register of Historic Places Continuation Sheet – King/ Dennis Farm

Sections 7, 8, 9, and 10

Page 7

7.100

Another event that brought recognition to Centerville was the establishment of Wayne County Seminary, later known as Whitewater College, in 1827-28. Such well-known Hoosiers as former governor Oliver P. Morton, author-Civil War General Lew Wallace, and Civil War General Ambrose Burnside, facial hair trendsetter for whom "sideburns" were named, were students and graduates of the Seminary.

Centerville continued to grow throughout the 1850s and 1860s, but prosperity was limited. The coming of major railroads that intersected at Richmond rather than Centerville changed the economic complexion and transportation mix for the entire county. Lacking a major power-producing water source and with limited access to rail transportation, Centerville lost its status of primary urban community to Richmond; the county seat moved to Richmond in 1872. Although its municipal/governmental status changed significantly, Centerville remained a hub of commercial and agricultural activity for many decades and provided local and rural residents with the necessities of the an increasingly bountiful life.

The King/Dennis Farm, today approximately 180 acres, began as an 80-acre holding belonging to Abraham and Susanah Kinsey. The land was recorded in their names in 1840. Farms of this size were common at this time. Given the physical ability to clear and later till the land with agricultural equipment of the day, much more than this would have been superfluous to the family needs. As equipment became more efficient and clearing the land was no longer necessary, farms tended towards more and more acreage.

The size of the farm changed a number of times in the next two to three decades under different owners such as George Fosler and Jacob Wolf. Eventually, it reached 275 acres by the 1860s. The heirs of Jacob Wolf appear to have sold approximately 180 acres to Lorenzo King circa 1867; the farm at that time included the entire NW ¼ and 20 acres in the NE ¼ of the same section. A map of the county dated 1867 shows a building, most likely the residence, on the property and Lorenzo King is noted as the owner.

Lorenzo King's father Jesse King and his large family, which included five sons – Samuel, Daniel, Elisha, Lorenzo, and John – came to the county from Kentucky and settled near Washington, Indiana, in 1826. The brothers, with the exception of Samuel who moved to Iowa and Kansas during his lifetime, settled in the county and married into local families. Lorenzo, after living in Green, Indiana, for a time, moved to the farm in the NW ¼, Section 4, T16N, R14E, circa 1867 with his sons William, Joseph, and Absalom.

Starting in 1872-74, historical atlases designate the farm as the property of "Heirs of Lorenzo D. King," and continue in this manner through the last decades of the 19th

National Register of Historic Places Continuation Sheet – King/ Dennis Farm

Sections 7, 8, 9, and 10

Page 8

century. William King, one of Lorenzo's sons, sold the farm in 1894. During a 15-year period, spanning the turn-of-the-century, the ownership of the farm changed four times. The longest period of ownership, by Samuel Wolf, was 1899 to 1909.

In 1909, the name of Emma Z. Dennis, the second wife of well-respected Earlham College professor of biology Dr. David W. Dennis, appears in the Wayne County land records as the new owner. There is no information on record to explain why the land was recorded in Emma's name. The Dennis family has owned the property since that time. According to a family member, the farm under Dennis ownership has been and continues to be operated as a leased property on a shared-profit basis.

Section 9 Bibliography

"Biographical and Genealogical History of Wayne, Fayette, Union and Franklin Counties." (Chicago: Lewis Publishing Company, 1899).

Griffing, Stevenson. *Atlas of Wayne County, Indiana*. (Philadelphia, Penna.: Griffing, Stevenson Company, Publishers, 1874).

Harris, Cyril M. *Illustrated Dictionary of Historic Architecture*. (New York: Dover Publications, Inc., 1977).

Madison, James. The Indiana Way. (Indianapolis: Indiana Historical Society, 1986).

Map of Wayne County, 1867. No publication information.

McAlester, Virginia and Lee. A Field Guide to American Houses. (New York: Alfred A. Knopf, 1989).

Richmond, Indiana. Palladium-Item. 1 January, 1981.

Spahr, Walter E. *History of Centerville, Indiana*. (Richmond, Ind.: Wayne County Historical Society, 1966).

Section 10 Geographical Description

Boundary Description

Starting from the junction of the property driveway and King Road turn south and walk along the road for approximately 35 yards; turn east and proceed along the south

National Register of Historic Places Continuation Sheet – King/ Dennis Farm

Sections 7, 8, 9, and 10

Page 9

fence line at the edge of the field for approximately 180 yards; turn north and proceed along the fence line at the edge of the field for approximately 137 yards; turn west and proceed along the north fence line for approximately 200 yards and close on the start point.

Boundary Justification

The boundary as described includes all the buildings and structures within the immediate proximity of the farmstead center and there appears to be no other significant agriculture-related resources to consider.