



Photograph No. 1

Round Lake Logging Dam

Price County, Wisconsin

(John Vogel, 1980; Negative: Supervisor's Office,
Chequamegon National Forest, Park Falls, WI)

JUL 2

1981

SEP 17 1981

DEC 3 1980

Northwest elevation. This photograph shows the north sluiceway. This is the sluiceway through which the greatest volume of water flows. This sluiceway no longer has its plank bottom.



Photograph No. 2

Round Lake Logging Dam

Price County, Wisconsin

(John Vogel, 1980; Negative: Supervisor's Office,
Chequamegon National Forest, Park Falls, WI)

JUL 2 1981

DEC 3 1980

Southwest elevation. This photograph shows the floodgate that is made of the original timber. It also shows the sagging decking on the south side, created by the collapsing of the south abutment.

SEP 17 1981



Photograph No. 3

Round Lake Logging Dam

JUL 2 1981 DEC 3 1980

Price County, Wisconsin

(John Vogel, 1980; Negative: Supervisor's Office,
Chequamegon National Forest, Park Falls, WI)

Northeast elevation. This photograph shows the dam's decking, or working platform.

SEP 17 1981



Photograph No. 4

Round Lake Logging Dam

Price County, Wisconsin

(John Vogel, 1980; Negative: Supervisor's Office,
Chequamegon National Forest, Park Falls, WI)

JUL 2 1981

DEC 3 1980

SEP 17 1981

Southeast elevation. This photograph shows the embankment to the south. This section comprises the greater part of the dam's length. Also seen on the right hand side is the deteriorating upstream abutment on the north embankment.



Photograph No. 5

Round Lake Logging Dam

JUL 2 1981

DEC 3 1980

Price County, Wisconsin

(John Vogel, 1980; Negative: Supervisor's Office,
Chequamegon National Forest, Park Falls, WI)

This photograph shows the
machinery used for raising and
lowering the floodgates on the
dam.

SEP 17 1981