

KENTUCKY HISTORIC RESOURCES INVENTORY

Site No. Sc 60

1. Historic Name(s) <u>Ash, Emison, slave quarters</u>		22. ADD/County <u>Bluegrass, Scott</u>	
Original Owner <u>Ash Emison</u>		23. U.S.G.S. Quadrant (15'/75') <u>Plain v.c.</u> G.I.S. Mod. <input type="checkbox"/>	
2. Present Name <u>Ash Emison slave quarters</u>		24. UTM Reference <u>16 71 38 00 42 37 22 0</u>	
3. Location <u>1/2 mi off E side Hwy 25 at Dry Run Creek, 2.9 mi N. of Ephraim Creek</u>		Zone Easting Northing	
4. Owner's Name <u>Mrs. Sallie Gibson</u>		25. Coordinate Accuracy <input type="checkbox"/>	
5. Owner's Address <u>110 Marvin Graves, Route 2 Cincinnati Pike, Georgetown Ky. 40324</u>		26. Prehistoric Site Object Historic Site Structure Building Other	
6. Open to Public Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	7. Visible from road Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	27. National Register District Name: <input type="checkbox"/>	
8. Ownership Private <input checked="" type="checkbox"/> Local <input type="checkbox"/> State <input type="checkbox"/> Federal <input type="checkbox"/>		28. Significance Evaluation <input type="checkbox"/>	
9. Local Contact/Organization <u>son in law Marvin Graves</u>		29. Status <input type="checkbox"/> Date _____ National Landmark _____ National Register _____ Landmark Certificate _____ Kentucky Survey _____ Local Landmark _____ HABS/HAER _____	
10. Site Plan with North Arrow <u>see attached boundary form</u>		30. Historic Theme Primary <u>architecture</u> <input type="checkbox"/> C Secondary <u>black history</u> <input checked="" type="checkbox"/> B <input checked="" type="checkbox"/> B Other _____	
11. Architect		31. Endangered Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
12. Builder		32. Preservation Project Status <input type="checkbox"/>	
13. Date <u>1840s</u> <u>2nd 1/4 19th Ca.</u> <input checked="" type="checkbox"/> B. <input type="checkbox"/>		Actual Cost in \$1,000s <input type="checkbox"/>	
14. Style A. <u>Farm</u> <input checked="" type="checkbox"/> B. <input type="checkbox"/>		33. ATTACH PHOTO <u>in attached envelope</u>	
15. Original Use <u>multi fam res.</u> <input checked="" type="checkbox"/>		Roll No. _____ Picture No. _____ Direction _____	
16. Present use <u>vacant</u>		34. Prepared by: <u>C.M. Wooley</u>	
17. Condition <u>ruins</u> <input checked="" type="checkbox"/> E		35. Organization _____	
18. Description <u>Two 1 story dry stone hall-parlor plans joined end to end with exterior chimneys on E and W ends. Each unit divided into 2 rooms by frame partition, stone wall between units. On W. end of building was later added</u> (over) (Continue on Back)		36. Date <u>1983</u>	
No. Stories <u>1</u> <input type="checkbox"/>		37. Revision Dates _____ 38. Staff Review _____	
Single Pile <input checked="" type="checkbox"/> NA _____ Double Pile _____			
Floor Plan <u>double hall parlor</u> <input checked="" type="checkbox"/>			
Structural Fabric <u>stone</u> A. <input checked="" type="checkbox"/> B. <input type="checkbox"/>			
Decorative Fabric _____ A. <input type="checkbox"/> B. <input type="checkbox"/>			
Roof Form <u>gable</u>			
19. History <u>Built on the 1000 acre land grant of Irishman Ash Emison, who first came to Ky in 1775 from Westminster Co Penn. to claim land. Became "Emison's Station" during settlement period. Inherited by (over)</u>			
20. Significance <u>In present condition, illustrates masonry construction method. Archaeological possibilities for substantial slave quarters.</u>			
21. Source of Information <u>18. inspection 19. 1977 survey form</u>			

18. Cont.:

one room of cement mortared stone, (photo 2)
and beyond it, one room of frame.

All exterior doors are on the N.
wall. In the original house, there is
an outside door to each bay only;
interior doorway between the two units.
Cellar access S exterior wall. Had
porch full length of N. wall.

Common, looted, dry stone; large
stones, flat pointing, no voussiers
(~~probable cause of collapsed wall~~). Pegged
frames, no trim. 6 panel doors

Roof has collapsed. Exterior portion
of center bay of S wall has fallen out,
revealing the mud filled interior wall (photo 4)
loosely and ends of floor joists resting
on the wooden foundation plate.

Quarry located N. E. of structure.

Said to have had matching quarters
nearby.

Face N, uphill.

19. Cont.:

family in 1824.

VERBAL BOUNDARY DESCRIPTION & JUSTIFICATION

Beginning at a point 100 ft S of the S.E. corner of the building and on a line w. E. end of same, thence W. 140 ft parallel w S wall of building to B, thence at right angles, N 200 ft to C, thence parallel to A-B E 190 ft to D, thence S 200 ft to E, thence W at right angles 50 ft to the beginning, containing 9/10 acre.

SKETCH MAP OF SITE SHOWING BOUNDARIES AND KEY BUILDINGS AND FEATURES WITH NORTH ARROW.

