



Seven Oaks

Sac County, Iowa

Photo by Bruce Becker (has negative)

October 1994

East and North (front of house) - camera view to SW

Photo #1



SEVEN DARS

Seven Oaks

Sac County, Iowa

Photo by Bruce Becker (has negative)

October 1994

North (front of house) - camera view to South

Photo # 2



SEVEN OAKS

Sac County, Iowa

Photo by Bruce Becker (has negative)

October 1994

West and South of house - camera view to NE

Photo #3



Seven Oaks

Sac County, Iowa

Photo by Bruce Becker (has negative)

August 1995

1st floor fireplace - camera view to West

Photo # 4



Seven Oaks

Sac County, Iowa

Photo by Bruce Becker (has negative)

August 1995

1ST floor ceiling, chandelier, stained glass
window, window casing, rosette blocks
and sculptural relief - camera view to N

Photo #5



Seven Oaks

Sac County, Iowa

Photo by Bruce Becker (has negative)

August 1995

Stairway to 2nd floor, stained glass windows,
light fixture - camera view to East

Photo #6



Seven Oaks

Sac County, Iowa

Photo by Bruce Becker (has negative)

August 1995

Carriage house (North side and West end) and
lamp post (camera view to SE)

Photo #7



Seven Oaks


Sac County, Iowa

Photo by Bruce Becker (has negative)

August 1995

Carriage house (South side and East end) camera view to NW

Photo #8



Seven Oaks

Sac County, Iowa

Photo by Bruce Becker (has negative)

August 1995

Original electric generator for house (in ba

Photo #9