Form KHC1985-2

Page 1 of _____ pages^{\exists}

KENTUCKY HISTORIC RESOURCES Individual Inventory Form

2909 NOV 1 5 1988

SHELBOURCE #_____

County

ويحجب والمحاجب المتعاد المكار فتقتص والمحاج والمحاج والمحاج والمحاج والمحاج والمحاج والمحاج والمحاج والمحاج وال		
JR Name of Resource	FICE AND RES	IDENCE
DR. Original Owner:	IS	
3. Other Names:		
4. Prehistoric Site	Building	Object
Historic Site	Structure	Other
5. Location: MT. EDEN QUAD.;	W.S. KY. 53	IN SOUTH
VILLE, DIRECTLY	N. OF SH 227	(STORE)
6. Owner's Name: MRS. CLARENCE PE	RRY	<u>ر</u> ها
7. Owner's Address: ROUTE 4 SHELBYVILLE, KEN	TUCKY 40065	
8. Evaluation: N . R . F		r N 1
9. Recognition & Dat		<u> </u>
Nat.Landmark		
	Local La	the second se
Nat.Register	HABS/H	and the second se
Highway Marker	KY Inven	tory 1986
KY Landmark Ce		·····
10. N.R.Status & Date		
11. N.R.Group:		
District Name:		
Mult.Resource An	ea onclot co	
Thematic Name:]
12. Historical Theme:		
	H/MEDICINE	[¹⁵⁰]
Secondary:		[]
Other:		[]
13. Statement of Signi	ficance:	

THE DR. MORRIS RESIDENCE AND OFFICE PROPERTY IS LOCALLY SIG-NIFICANT UNDER CRITERIA A, FOR ASSOCIATION WITH THE ACTIVITIES THAT TOOK PLACE IN RURAL SHELBY COUNTY AT THE TURN- (CONTINUED) [A]

14. History: THIS PROPERTY CONTAINS THE ORIGINAL OFFICE AND HOME AND THE LATER OFFICE OF DR. WILLIAM MORRIS, A GENERAL PRACTI-TIONER OF MEDICINE IN SOUTH CENTRAL SHELBY COUNTY AT THE TURN OF THE CENTURY DR. MORRIS HAD THIS HOUSE BUILT BY LOCAL AREA CARPENTER JAMES W. ADAMS (SH 216) IN ABOUT 1899-1900. THE HOUSE ORIGINAL-LY SERVED AS OFFICE AND LIVING QUARTERS AND THE PLAN INDICATES THIS MULTI-USE. FOUR OF FIVE ROOMS OPEN OFF THE LARGE, CENTRAL HALL THAT WAS THE (CONTINUED)

15. Source of historical information and/or contact person:

ROGER BROWN; DOC PERRY; SHELBY COUNTY CLERK AND RECORDER OFFICE

16. Date: Original Building	 , 4 ,
Addition	
1700 Style NACULAR	,5V ,
18. Architect/Builder:	
19. No. of Stories:	[1.0]
20. Original Floor Plan: ASYMETRICAL / FICTURESQUE	
21. Single Pile Double Pile	N.A. ×
22. Roof Form & Material: Ori	iginal
Not Or	iginal ×
23. Structural Material: FRAME	[W]
24. Exterior Material: CLAFEOARD	[ω]
25. Foundation Material:	
STONE	[S]
26. Major Alterations: None	X
Moved/Rebuilt Other	
Additions	
27. Special Features:	
28. Outbuildings: ONE, COAL/WOOD STORAGE	[^{NC}]
29. Original Function: MEDICAL BUSINESS/OFFICE	[^{12D}]
30. Present Use: BUSINESS	[02A]
31. Condition:	
FAIR	[F]
32. Endangered:	Yes
	No <u>X</u>
33. Attach Photos: Roll ¹² Photo Nos: $\frac{1}{5}$ No. of	Slides:

34.	Prepared by:	CHRIST	INE AMOS	
35.	Organization:	SHELBY	CO. HIST.	SOC.
36.	Date:	971986		
37.	New Survey	X	Resurvey	

Page 2 of 3 pages

KENTUCKY HISTORIC RESOURCES Individual Inventory Form

Resource # SH 260

And the second second

and the second second

n de service nom de la composition de l La composition de la c

38.	UTM Point of Primary Building: Quadrant: Mt. Eden	Zone	Easting 659200	Northing 4219480	G.I.S. Mod. Coordi.Accuracy	[] [•,]
41.	UTM Points of Boundary (for N. R A.	. eligibl	e sites only): I)	 la constanta da seria	
12.	B. C. Total Acreage in Present Property		E F Vn 43. Acre		 d N.R. boundary: 4	1

44. Site Plan (and boundary description and justification for N.R. sites):

Maria Maria Managara Ang Pangara

The nominated property contains three associated frame buildings located in the crossroads community of Southville, at the junction of Ky. 55, the Mt. Eden Road, and Ky. 714. The buildings were originally constructed at the turn-of-the-century by local builder/craftsman, James W. Adams, who lived across the street, for Dr. William Morris, and served as his residence and office. The single story frame house, small, two room office and wood/coal shed are located within the property boundary beginning at point A, on the east edge of KY. 53, 35 feet north of the north wall of the office; then south along the road edge to point B, on a line 35 feet south of the south wall of the residence; then from point B west along the line paralell to and 35 feet south of the south wall of the residence to point C, on that line and 50' west of the west wall of the residence; then north from point C along that line 50' west of the west wall of the residence to point D, along a line 35' north of and parallel to the north wall of the office; then east along that line to the point of origin.

1+1

45. Description and House Plan:

The proerty is the turn-of-the-century office of Dr. William Morris, his house, and woodshed/coal house, all located in the crossroads community of Southville on the Mt. Eden Road at the intersection with imesy, 714. The small, hip roofed office, sited close to the highway is one on the most prominent buildings in town. Perhaps this is because it houses a second hand dealership with offerings of the trade displayed throughout the yard and aboard the exterior walls. Small tools, tires, discarded machinery and two signs proclaiming "BUY OF THE WEEK" tend to detract from the physical qualities of the building, but nevertheless, integrity has been maintained. The house is in only fair condition but also maintains good physical integrity. The poor condition of the wood shed/coal house count it a non-contributing element of the property. The three buildings are contained in the yard area that is bordered by SH 227, Carriss's Grocery to the south, a residence to the north, and the Mt. Eden Road to the east.

The office has a stone foundation, measures approximately 15 feet square, with a hip roof; 5' plain weatherboard walls with corner trim; an off-centered chimney flue; single light sash windows; original operable shutters and a recessed entry beneath a porch in the southeast SH 260 Dr. Morris house and office

13. Statment of Significance, continued

of-the-century. Beginning roughly around 1885, the county's white population began to increase for the first time since the settlement period, as new farms and rural communities were established. Southville, one such community contained a post office, scales, mercantile and this, the doctor's office. This property is locally significant as a representation of the type of health care and medical facilities available in rural Shelby County during this time.

14. History, continued

waiting room. Possibly about 1910, Morris had Adams build the small office on near the road to separate his business from living quarters.

45. Description and House Plan, continued


corner of the building. There are two half light entries, one into the waiting room and the other into the office. The office has a built in bookcase from floor to ceiling and there is a small room, said to have been used to store medicines. All interior woodwork is unpainted pine and floors are also of pine. See photos 12-1-3,5.

The residence was constructed for Dr. Morris by prominent local carpenter/builder, James W. Adams, who built and resided in the house across the road, SH 216. The residence originally served as Dr. Morris' office until the above described building was built at some later date. The house is one story with an asymmetrical plan. Characteristic of Adams, the the interior has a multitude of doors with the central hall, originally the waiting room, accessed by four doors not counting the main entry. Details include a stone foundation; one story rear addition with bath, 5' plain weatherboard siding; exterior shutters with three sections of individually operated louvres; single light sash windows, boxed eave, scallped shingles in the gable ends, two interior chimneys; three interior metal fireplace mantles; and an asymmetrical facade with partially wrapping porch with turned posts, brackets and sawtooth frieze. Although condition of the house is only fair, material and design integrity are intact.

A gable roofed, wood sided coal shed, located north of the house and behind, west, of the office is a non-contributing element of the property due to deteriorated condition.

The nominated area includes two contributing buildings and one noncontributing building.

residence C office C coal house NC



(2)

 \square

PORCH

--- 15'-

R

 $\mathbf{\hat{U}}$

•~ 3

.0

7

A

BOOKLASE