



UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

STATE Connecticut	
COUNTY Windham	
FOR NPS USE ONLY	
ENTRY NUMBER 71.8.09.0016	DATE 8/5/71

1. NAME

COMMON: William Jillson Stonehouse
AND/OR HISTORIC:

2. LOCATION

STREET AND NUMBER:
561 Main Street
CITY OR TOWN:
Willimantic
STATE: Connecticut CODE COUNTY: CODE
09 015

3. PHOTO REFERENCE

PHOTO CREDIT: Richard Moriarty - Colonial Photo Service
DATE OF PHOTO: May, 1970
NEGATIVE FILED AT:
Colonial Photo Service - 57 Echo Drive, Willimantic, Conn.

4. IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC.
View of front of house, looking north across Main Street and railroad spur. Brick addition to left entirely removed 1970.
①

SEE INSTRUCTIONS



UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

STATE	
Connecticut	
COUNTY	
Windham	
FOR NPS USE ONLY	
ENTRY NUMBER	DATE
71.8.09.0016	8/5/71

SEE INSTRUCTIONS

1. NAME			
COMMON: <u>The William Jillson Stonehouse</u>			
AND/OR HISTORIC:			
2. LOCATION			
STREET AND NUMBER: 561 Main Street			
CITY OR TOWN: Willimantic			
STATE: Connecticut	CODE 09	COUNTY: Windham	CODE 015
3. PHOTO REFERENCE			
PHOTO CREDIT: <u>Richard Moriarty</u>			
DATE OF PHOTO: <u>May 1969</u>			
NEGATIVE FILED AT: Colonial Photo Service, 57 Echo Drive, Willimantic, Conn.			
4. IDENTIFICATION			
DESCRIBE VIEW, DIRECTION, ETC. View of the rear of the house, looking south taken from Union street. This shows only a small part of the roof of the brick wing.			

②

