

B. Clouette Photo, 2/83 Negative filed with Conn. Hist. Comm., Hartford

Facades, 209-231 Bank St., view northeast



B. Clouette Photo, 2/83 Negative filed with Conn. Hist. Comm., Hartford

North and west elevations, view south



B. Clouette Photo, 2/83 Negative filed with Conn. Hist. Comm., Hartford

South and rear elevations, view north



B. Clouette Photo, 2/83 Negative filed with Conn. Hist. Comm., Hartford

Facade, Pritchard Building, 207-211 Bank Street, view east



B. Clouette Photo, 2/83 Negative filed with Conn. Hist. Comm., Hartford

Facade, Whittemore Building, 213-219 Bank Street, view east



BANK STREET HISTORIC DISTRICT

Bruce Clouette Photo, 4/79 Negative with Connecticut Historical Commission, Hartford, CT

Detail, Griggs Building, Bank Street, view east



B. Clouette Photo, 2/83 Negative filed with Conn. Hist. Comm., Hartford

Storefront, Griggs Building, 221-227 Bank Street, view southeast



B. Clouette Photo, 2/83 Negative filed with Conn. Hist. Comm., Hartford

Interior, Griggs Building, 221-227 Bank Street, stairway and hall, view east



B. Clouette Photo, 2/83 Negative filed with Conn. Hist. Comm., Hartford

Interior, Griggs Building, 221-227 Bank Street, safe and mantel, second-floor front room, view west



B. Clouette hoto, 2/83 Negative filed with Conn. Hist. Comm., Hartford

Cornice detail, Republican Building, 229-231 Bank St., view southwest