



Creston  
20

Carlton State and Savings Bank  
109 West Main Street  
Carlton, Yamhill County, Oregon

*SOUTH AND EAST MEASUREMENTS  
FROM INTERSECTION OF MAIN AND*

Alex R. Clemens Photo, 1987  
615 SW Caruthers  
Portland OR 97201

*1 OF 4*



SPEED  
20

Carlton State and Savings Bank  
109 West Main Street  
Carlton, Yamhill County, Oregon

*SOUTH (FRONT) ELEVATION  
FROM MAIN STREET*

Alex R. Clemens Photo, 1987  
615 SW Caruthers  
Portland OR 97201

*2 OF 4*



Carbon  
DRUG

Carlton State and Savings Bank  
109 West Main Street  
Carlton, Yamhill County, Oregon

*WEST AND SOUTH ELEVATIONS  
FROM MAIN STREET*

Alex R. Clemens Photo, 1987  
615 SW Caruthers  
Portland OR 97201

*3 OF 4*



Carlton State and Savings Bank  
109 West Main Street  
Carlton, Yamhill County, Oregon

*NORTH (REAR) ELEVATIONS*

Alex R. Clemens' Photo, 1987  
615 SW Caruthers  
Portland OR 97201

*4 OF 4*



Carlton State and Savings Bank  
109 West Main Syreet  
Carlton, Yamhill County, Oregon

Supplementary series, interior views  
1 of 6

Ground story bank interior, looking  
southeasterly toward entrance, showing  
original toplights of storefront,

chair rail, picture molding, plaster  
coved cornice and window trim.



Carlton State and Savings Bank  
109 West Main Street  
Carlton, Yamhill County, Oregon

Supplementary series, interior views  
2 of 6

Ground story bank interior, looking  
south toward entrance, showing  
original toplights of storefront,  
chair rail, picture molding, plaster  
coved cornice and window trim.



Carlton State and Savings Bank  
109 West Main Street  
Carlton, Yamhill County, Oregon

Alex R. Clemens Photo, 1987  
615 SW Caruthers  
Portland OR 97201

Supplementary series, interior views  
3 of 6  
Ground story bank interior, looking  
north at vault with its classical  
architrave.



Carlton State and Savings Bank  
109 West Main Street  
Carlton, Yamhill County, Oregon

Supplementary series, interior views  
4 of 6  
Ground story bank interior, looking  
northwesterly at vault with its  
classical architrave.



Carlton State and Savings Bank  
109 West Main Street  
Carlton, Yamhill County, Oregon

Supplementary series, interior views  
5 of 6

Second story hallway, looking south,  
showing original doors and frames with  
architrave moldings, transoms.



Carlton State and Savings Bank  
109 West Main Street  
Carlton, Yamhill County, Oregon

Supplementary series, interior views  
6 of 6  
Second story, front room, looking  
southwesterly.

Alex R. Clemens Photo, 1987  
615 SW Caruthers  
Portland OR 97201