



Mc Kinley  
CLIMATIC LABORATORY

# 1

McKinley Climatic Laboratory

Main Facility

Okaloosa, Florida

USAF Staff Photographer

Unknown Date

Eglin Photographic Laboratory

Looking South, Southeast

Photo # 1 of 17

U.S. AIR FORCE  
MCKINLEY CLIMATIC LABORATORY

#2

McKinley Climatic Laboratory  
Main facility  
Okaloosa, Florida  
USAF Staff Photographer  
Unknown Date  
Eglin Photographic Laboratory  
Looking East, South-east  
Photo #2 of 17



#3

McKinley Climatic Laboratory  
Main Facility  
Okaloosa, Florida  
USAF Staff Photographer  
Unknown Date  
Eglin Photo. Lab.  
Looking South, Southeast  
Photo #3 of 17



U.S. AIR FORCE  
McKINLEY CLIMATIC LABORATORY

#4

McKinley Climatic Laboratory  
Main Facility  
Okaloosa, Florida  
USAF Staff Photographer  
Unknown Date  
Eglin Photo Lab.  
Looking East, Southeast  
Photo #4 of 17





DANGER  
HARD HAT  
AREA

#5

McKinley Climatic Laboratory  
Main Chamber Sub-Floor during renovations  
Okaloosa, Florida  
USAF Staff Photographer  
1994  
Eglin AFB  
Viewing Eastern portion of main chamber  
Photo #5 of 17

OFFICIAL U.S.A.F. PHOTOGRAPH  
3246TW/TFOA EGLIN AFB, FL  
PHOTOGRAPHER:  
NEGATIVE NO: 9415248



#6

McKinley Climatic Laboratory  
Main Chamber Ceiling I-beams  
Okaloosa, Florida  
USAF Staff Photographer  
1994 - during renovations  
Eglin AFB  
Looking upward into ceiling  
Photo #6 of 17

OFFICIAL U.S.A.F. PHOTOGRAPH  
3246TW/TFOA EGLIN AFB, FL  
PHOTOGRAPHER:  
NEGATIVE NO: 9411826



# 7

McKinley Climatic Laboratory  
Main Facility roof  
Okaloosa, Florida  
USAF Staff Photographer  
1994 - during renovations  
Eglin AFB  
Photo # 7 of 17

OFFICIAL U.S.A.F. PHOTOGRAPH  
3246TW/TFOA EGLIN AFB, FL  
PHOTOGRAPHER:  
NEGATIVE NO: 9411753



NO SMOKING  
IN CHAMBER

# 8

McKinley Climatic Laboratory  
Temperature-Altitude Chamber  
Okaloosa, Florida  
USAF Staff Photographer  
Unknown Date  
Eglin AFB  
Photo # 8 of 17

OFFICIAL U.S.A.F. PHOTOGRAPH  
3246TW/TFOA EGLIN AFB, FL  
PHOTOGRAPHER:  
NEGATIVE NO: 013094





#9

McKinley Climatic Laboratory

B-1B strategic bomber undergoing low temperature  
testing (-65°F) in the main chamber

Okaloosa, Florida

USAF Staff Photographer

1986

Eglin AFB

Photo #9 of 17

OFFICIAL U.S.A.F. PHOTOGRAPH  
3246TW/TFOA EGLIN AFB, FL  
PHOTOGRAPHER:  
NEGATIVE NO: 624235



#10

McKinley Climatic Laboratory  
B-1B bomber undergoing low temperature  
testing in the Main Chamber

OKaloosa, Florida  
USAF Staff Photographer  
1986

Eglin AFB

Photo #10 of 17

OFFICIAL U.S.A.F. PHOTOGRAPH  
3246TW/TFOA EGLIN AFB, FL  
PHOTOGRAPHER:  
NEGATIVE NO: 625965



# 11

McKinley Climatic Laboratory  
Equipment undergoing high temperature  
testing in the main Chamber  
Okaloosa, Florida  
USAF Staff Photographer  
Unknown Date  
Eglin AFB  
Photo #11 of 17

OFFICIAL U.S.A.F. PHOTOGRAPH  
3246TW/TFOA EGLIN AFB, FL  
PHOTOGRAPHER: 2  
NEGATIVE NO: 009730



#12

McKinley Climatic Laboratory  
F-117A Stealth undergoing Icing tests in  
main Chamber  
Ocala, Florida  
USAF Staff Photographer  
1991  
Eglin AFB  
Photo #12 of 17

OFFICIAL U.S.A.F. PHOTOGRAPH  
3246TW/TFOA EGLIN AFB, FL  
PHOTOGRAPHER:  
NEGATIVE NO: 136423





#13

McKinley Climatic Laboratory  
FB-111 undergoing rain testing in the M.C.  
Okaloosa, Florida  
USAF Staff Photographer  
1970s  
Eglin AFB  
Photo #13 of 17

OFFICIAL U.S.A.F. PHOTOGRAPH  
3246TW/TFOA EGLIN AFB, FL  
PHOTOGRAPHER:  
NEGATIVE NO: 115584



#14

McKinley Climatic laboratory

C-130 undergoing rain testing in the M.C.  
Okaloosa, Florida

USAF Staff photographer

Unknown Date

Eglin AFB

Photo #14 of 17

OFFICIAL U.S.A.F. PHOTOGRAPH  
3246TW/TFOA EGLIN AFB, FL  
PHOTOGRAPHER:  
NEGATIVE NO: 9224005



#15

McKinley Climatic Laboratory  
HH-65 Coast Guard Rescue Helicopter  
Undergoing snow loading test in M.C.  
Okaloosa, Florida  
USAF Staff Photographer  
1985  
Eglin AFB  
Photo #15 of 17

OFFICIAL U.S.A.F. PHOTOGRAPH  
3246TW/TFOA EGLIN AFB, FL  
PHOTOGRAPHER:  
NEGATIVE NO: 316124



# 16

McKinley Climatic Laboratory  
F-117A Stealth Fighter at O<sup>o</sup>F  
Kalcaosa, Florida  
USAF Staff Photographer

1991

Eglin AFB

Photo #16 of 17

OFFICIAL U.S.A.F. PHOTOGRAPH  
3246TW/TFOA EGLIN AFB, FL  
PHOTOGRAPHER:  
NEGATIVE NO: 131367





TDU-9/B

#17

McKinley Climatic Laboratory

TDU-9/B missile undergoing Pressure  
Altitude testing in the Temperature  
Altitude Chamber

Okaloosa, Florida

USAF Staff Photographer


1960s

Eglin AFB

Photo #17 of 17

OFFICIAL U.S.A.F. PHOTOGRAPH  
3246TW/TFOA EGLIN AFB, FL  
PHOTOGRAPHER:  
NEGATIVE NO: 115909

U.S. AIR FORCE  
MCKINLEY CLIMATIC LABORATORY



McKinley Cinnatic Laboratory

Okaloosa County, FL

12/97

Photo. USAF photographer

U. S. AIR FORCE  
McKINLEY CLIMATIC LABORATORY



McKinley Climatic Laboratory

Eglin AFB

Okaloosa County, FL

12/97

Photo by: USAF Photographer



Temperature  
-20 0 -32 -70  
-40 -50 -65 -85 -920  
Inside

B 4 6 6

NARCK

OFFICIAL U. S. A. F. PHOTOGRAPH

46TW/TSTMV EGLIN AFB, FL

PHOTOGRAPHER:

NEGATIVE NO: 9705542





OFFICIAL U. S. A. F. PHOTOGRAPH  
46TW/TSTMV EGLIN AFB, FL

PHOTOGRAPHER:

NEGATIVE NO: 9705542