



"Dowden's Luck"

18511 Beallsville Rd., Poolesville,  
Montgomery County, Maryland

Oct. 1, 1987

Bobbi Hahn

Maryland SHPO

View of property from road, facing East

1 SLIDE

10739



Dowden's Luck"

18511 Beallsville Rd., Poolesville, Montgomery

County, MD

Jo Eyer

May 4, 1986

Maryland Historical Trust

Front (West) facade of main house and side

facade of 3 outbuildings - Photographer facing

~~1 of 26~~

**2 SIDE 2M 39**

East



"Dowden's Luck"

18511 Beallsville Rd., Poolesville, Montgomery

County, MD

May 4, 1986

Jo Eyer

Maryland Historical Trust

Front (West) facade of house

Photographer facing East

3 SLIDE

3 of 39



"Dowden's Luck"

18511 Beallsville Rd., Poolesville,  
Montgomery County, Maryland

May 4, 1986

Jo Eyer

Maryland Historical Trust

North & West facades of house. Mainblock  
1826-40, 1-1/2 story North wing. 1855  
addition. Double chimney, North side of  
main block, serves 5 fireplaces.

3A SLIDE

4739





"Dowden's Luck"

18511 Beallsville Rrd., Poolesville,  
Montgomery County, Maryland

Oct. 1, 1987

Bobbi Hahn

Maryland SHPO

West elevation, maindwelling, porch  
decoration

4 SLIDE

5739



"Dowden's Luck"

18511 Beallsville Rd., Poolesville,  
Montgomery County, Maryland

May 4, 1986 *in block* Jo Eyer

Maryland Historical Trust

South facade of main block

Photographer facing North

**5 SLIDE**

**6 of 39**



"Dowden's Luck"

18511 Beallsville Rd., Poolesville,  
Montgomery County, Maryland

May 4, 1986

Jo Eyer

Maryland Historical Trust

East facade of 3 bay main block and 1855  
addition

Photographer facing West

6 SLIDE

7739



"Dowden's Luck"

18511 Beallsville Rd., Poolesville,  
Montgomery County, Maryland

Oct. 1, 1987

Bobbi Hahn

Maryland SHPO

East elevation, North end

7 SLIDE

8 739





"Dowden's Luck"

18511 Beallsville Rd., Poolesville, Montgomery  
County, MD

Jo Eyer

May 4, 1986

Maryland Historical Trust

North facade of house

Photographer facing South

8 SLIDE

9739



"Dowden's Luck"

18511 Beallsville Rd., Poolesville, Montgomery  
County, MD

Jo Eyer

May 4, 1986

Maryland Historical Trust

Original plain board siding in place under  
asbestos shingles, 6½ inches wide.

9 SLIDE

10 0339

9



"Dowden's Luck"

18511 Beallsville Rd., Poolesville,  
Montgomery County, Maryland

Oct. 1, 1987

Bobbi Hahn

Maryland SHPO

Entrance hall, stairway, front door

Interior: photographer facing West

10 SLIDE

11 of 39



"Dowden's Luck"

18511 Beallsville Rd., Poolesville, Montgomery  
County, MD

Jo Eyer

May 4, 1986

Maryland Historical Trust

Stair landing above front door on West wall of  
main block. Woodwork: simple molding.

JOA-SWEDÉ

12939





"Dowden's Luck"

18511 Beallsville Rd., Poolesville,  
Montgomery County, Maryland

May 4, 1986

Jo Eyer

MarylandHistorical Trust

Interior of East wall of first floor hall.

Doorway opposite front door, opens to back  
yard (formerly six panel door)

12 SLIDE

12 of 39



"Dowden's Luck"

18511 Beallsville Rd., Poolesville, Montgomery  
County, MD

Jo Eyer

May 4, 1986

Maryland Historical Trust

Interior North wall of first floor hall. One  
of two doorways in this wall.

~~12A~~ 12A-5125E

14739

12A



"Dowden's Luck"

18511 Beallsville Rd., Poolesville, Montgomery  
County, MD

Jo Eyer

May 4, 1986

Maryland Historical Trust  
Interior of West wall in first floor hall  
showing (boarded up) front entrance with 2  
pane sidelights and panelled woodwork.

12B<sup>05/25</sup>DE

15739

12 B



"Dowden's Luck"

18511 Beallsville Rd., Poolesville,  
Montgomery County, Maryland

Oct. 1, 1987

Bobbi Hahn

Maryland SHPO

Front parlor, apron windows in West wall

14 SLIDE

15939





"Dowden's Luck"

18511 Beallsville Rd., Poolesville,  
Montgomery County, Maryland

May 4, 1986

Jo Eyer

Maryland Historical Trust

Interior of West wall of front parlor showing double hung, six over six window over apron panel opening. One of two identical windows in this wall.

14A SLIDE

76 739  
17



"Dowden's Luck"

18511 Beallsville Rd., Poolesville,  
Montgomery County, Maryland

May 4, 1986

Jo Eyer

Maryland Historical Trust

Fireplace on North wall of back parlor (or  
dining room). Mantle removed. Cupboard in  
back of chimney.

15 SLIDE

18739



"Dowden's Luck"

18511 Beallsville Rd., Poolesville, Montgomery  
County, MD

Jo Eyer

May 4, 1986

Maryland Historical Trust

~~Second floor hall. North wall. One of two  
identical doorways to two bedrooms.~~

~~15A SLIDE~~ West wall of back parlor showing  
woodwork and six panel door.

15A 19739



"Dowden's Luck"

18511 Beallsville Rd., Poolesville,  
Montgomery County, Maryland

Oct. 1, 1987

Bobbi Hahn

Maryland SHPO

Back parlor, North wall, fireplace mantle  
missing, closet in back of mantle, damaged  
six panel doors

15B <sup>OF</sup> SIDE

20739





"Dowden's Luck"

18511 Beallsville Rd., Poolesville, Montgomery  
County, MD

Jo Eyer

May 4, 1986

Maryland Historical Trust

Four window protrusion on East wall of back  
parlor, overlooking back (East) garden.

16 SLIDE

24 739

16



"Dowden's Luck"

18511 Beallsville Rd., Poolesville, Montgomery  
County, MD

Jo Eyer

May 4, 1986

Maryland Historical Trust

Closed staircase on South wall of 1855 addition  
leading to bedroom directly above dining room.

19 JLE

22739



"Dowden's Luck"

18511 Beallsville Rd., Poolesville, Montgomery  
County, MD

Jo Eyer

May 4, 1986

Maryland Historical Trust

Fireplace on South wall of 1855 addition.

17A of 529 DE

22739

17A



"Dowden's Luck"

18511 Beallsville Rd., Poolesville,  
Montgomery County, Maryland

Oct. 1, 1987

Bobbi Hahn

Maryland SHPO

Kitchen interior, Northeast corner

18 SLIDE

24739





"Dowden's Luck"

18511 Beallsville Rd., Poolesville, Montgomery  
County, MD

Jo Eyer

May 4, 1986

Maryland Historical Trust

Fireplace opening and detached mantle on North  
wall of back bedroom (2 windows face East from  
this room).

20 JLE

25839



"Dowden's Luck"

18511 Beallsville Rd., Poolesville,  
Montgomery County, Maryland

Oct. 1, 1987

Bobbi Hahn

Maryland SHPO

Steps to 1855 bedroom from 1824-40 main  
block. Interior, second floor

of

~~257~~ 39



"Dowden's Luck"

18511 Beallsville Rd., Poolesville,  
Montgomery County, Maryland

Oct. 1, 1987

Bobbi Hahn

Maryland SHPO

Two chimneys join in attic corbelled  
construction, large timbers

23 SLIDE

27 7 39



"Dowden's Luck"

18511 Beallsville Rrd., Poolesville,  
Montgomery County, Maryland

Oct. 1, 1987

Bobbi Hahn

Maryland SHPO

Attic timbers mortised and tenoned

24 SLIDE

28739





"Dowden's Luck"

18511 Beallsville Rd., Poolesville, Montgomery  
County, MD

Jo Eyer

May 4, 1986

Maryland Historical Trust

East side of house. Photograph taken from  
second level of three level, overgrown, terraced  
garden. Photographer facing West.

27 of 54 DE

287739

27



"Dowden's Luck"

18511 Beallsville Rd., Poolesville,  
Montgomery County, Maryland

May 4, 1986

Maryland Jo Eyer

Maryland Historical Trust

Smokehouse of pierced brick construction.  
South & East facades. Photographer facing  
Northwest.

28 SLIDE

~~30~~ 139



"Dowden's Luck"

18511 Beallsville Rd., Poolesville,  
Montgomery County, Maryland

May 4, 1986

Jo Eyer

Maryland Historical Trust

North facade of brick smokehouse. Main house :  
in background. Photographer facing South.

29 SLIDE

34 of 39



"Dowden's Luck"

18511 Beallsville Rd., Poolesville,  
Montgomery County, Maryland

May 4, 1986

Jo Eyer

Maryland Historical Trust

South facade of stone slave quarter.

Photographer facing North.

30. <sup>OF</sup> SLIDE

32739





"Dowden's Luck"

18511 Beallsville Rd., Poolesville,  
Montgomery County, Maryland

May 4, 1986

Jo Eyer

Maryland Historical Trust

North & West facades of stone slave quarter.  
One window boarded up. Stone chimney with  
brick stack.

31 SLIDE

32 of 39



Something went wrong while we were encoding this page.  
Please check the log file to find out the details.

"Dowden's Luck"

18511 Beallsville Rd., Poolesville,  
Montgomery County, Maryland

Oct. 1, 1987

Bobbi Hahn

Maryland SHPO

Slave quarter, interior, West wall,  
fireplace filled with rubble stone

32 <sup>of</sup> SLIDE

34 739



"Dowden's Luck"

18511 Beallsville Rd., Poolesville, Montgomery  
County, MD.

Jo Eyer

May 4, 1986

Maryland Historical Trust

West facade of springhouse, located 196 ft. to  
North of other outbuildings, Water flows West  
to East through this building. (Door to  
building on East facade)

35 8210E

35739



"Dowden's Luck"

18511 Beallsville Rd., Poolesville, Montgomery

County, MD

Jo Eyer

May 4, 1986

Maryland Historical Trust

Stone over stream running into springhouse.

Stone is located 6 ft. West of springhouse.

36 SLIDE 36 739





"Dowden's Luck"

18511 Beallsville Rd., Poolesville,  
Montgomery County, Maryland

Oct. 1, 1987

Bobbi Hahn

Maryland SHPO

Two agricultural storage buildings  
1930-60, East elevation

41 <sup>SE</sup> SLIDE

377, 39



"Dowden's Luck"

18511 Beallsville Rd., Poolesville,  
Montgomery County, Maryland

Oct. 1, 1987

Bobbi Hahn

Maryland SHPO

Two car garage 1930-60

South elevation

42° of SLIDE

88739



"Dowden's Luck"

18511 Beallsville Rd., Poolesville,  
Montgomery County, Maryland

Oct. 1, 1987

Bobbi Hahn

Maryland SHPO

Silo and dairybarn 1930-60

Photographer facing Northeast

44 of

39 7 39