



N-126.3A

MAIN ST.

N-126.3A

Name: ODESSA HISTORIC DISTRICT

Location: 15-19 MAIN STREET, ODESSA, DE

Photographer: VALERIE CESNA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGY +
HISTORIC PRESERVATION, DOVER, DE

Description:

"PUMP HOUSE"

SOUTHWEST SIDE OF MAIN ST. AT 2ND ST.
VIEW FROM NORTH

Photograph Number:

1 OF 40

M
-
S
S



N-126.4
WILSON-WARNER HOUSE
MAIN ST.

N-126.4

Name: ODESSA HISTORIC DISTRICT

Location: 202 MAIN STREET, ODESSA, DE

Photographer: VALERIE CESNA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGY +
HISTORIC PRESERVATION, DOVER, DE

Description:

"WILSON-WARNER HOUSE"

SOUTHWEST SIDE OF MAIN ST. BETWEEN

SECOND + THIRD STR. — VIEW FROM EAST

Photograph Number:

2 of 40



N-126.B
STARR-LORE HOUSE
MAIN STREET

N-126.8

Name: ODESSA HISTORIC DISTRICT

Location: 300 1/2 MAIN STREET, ODESSA, DE

Photographer: VALERIE CESNA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGY +
HISTORIC PRESERVATION, DOVER, DE

Description:

"STARR-LORE HOUSE"

SOUTHWEST SIDE OF MAIN ST. BETWEEN

THIRD + FOURTH STS. — VIEW FROM NORTHEAST

Photograph Number:

3 of 40

3
21-12



N-126.10 + .11

MAIN ST.

N-126.10 + .11

Name: ~~ODessa~~ HISTORIC DISTRICT

Location: MAIN STREET, ODESSA, DE

Photographer: VALERIE CESNA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGY +
HISTORIC PRESERVATION

Description:

SOUTHWEST SIDE OF MAIN STREET AT FOURTH ST.
VIEW FROM NORTH

Photograph Number:

4 OF 40

19-3



N-126.12

MAIN STREET

N-126.12

Name: ~~Odessa~~ HISTORIC DISTRICT

Location: MAIN STREET, ~~Odessa~~, DE

Photographer: VALERIE CESNA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGY +
HISTORIC PRESERVATION, DOVER, DE

Description:

SOUTHWEST SIDE OF MAIN ST. BETWEEN FOURTH
AND FIFTH STS. — VIEW FROM EAST

ST. PAUL'S M.E. CHURCH

Photograph Number:

5 OF 40

25-2



N-126.13

MAIN ST.

N-126.13

Name: ODESSA HISTORIC DISTRICT

Location: 408 MAIN STREET, ODESSA, DE

Photographer: VALERIE CESNA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGY +
HISTORIC PRESERVATION, DOVER, DE

Description:

SOUTHWEST SIDE OF MAIN ST. BETWEEN
FOURTH + FIFTH STS. — VIEW FROM NORTH

Photograph Number:

6 OF 40

3
121



N-126.15

Main St.

N-126.15

Name: ODESSA HISTORIC DISTRICT

Location: 502 MAIN STREET, ODESSA, DE

Photographer: VALERIE CESNA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGY +
HISTORIC PRESERVATION, DOVER, DE

Description:

WEST CORNER MAIN AND FIFTH STS.
VIEW FROM NORTHEAST

Photograph Number:

7 of 40

1313



N-126.16

MAIN ST.

N-126.16

Name: ~~ODessa~~ HISTORIC DISTRICT

Location: 504 MAIN STREET, ODESSA, DE

Photographer: VALERIE CESNA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGY +
HISTORIC PRESERVATION, DOVER, DE

Description:

SOUTHWEST SIDE OF MAIN ST. BETWEEN FIFTH +
SIXTH STS. — VIEW FROM EAST

Photograph Number:

8 of 40

126.16



184

N-126.17

MAIN ST.

N-126.17

Name: ODESSA HISTORIC DISTRICT

Location: 506 MAIN STREET, ODESSA, DE

Photographer: VALERIE CESNA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGY +
HISTORIC PRESERVATION, DOVER, DE

Description:

SOUTHWEST SIDE OF MAIN ST. BETWEEN FIFTH
AND SIXTH STS. — VIEW FROM NORTH

Photograph Number:

9 of 40

12-3



N-126.19 + .20
MAIN ST. WEST OF
ROUTE 13

N-126.19 + .21

Name: ODESSA HISTORIC DISTRICT

Location: 606-608 MAIN STREET, ODESSA, DE

Photographer: VALERIE CESNA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGY +
HISTORIC PRESERVATION, DOVER, DE

Description:

WEST CORNER MAIN + SIXTH STS.,
VIEW FROM EAST

Photograph Number:

10 OF 40

M
6-3



1795
ASSOCIATION
FRIENDS
MEETING
of Christ
—
MEETING
FOR WORSHIP
FIRST DAY
AT 10 O'CLOCK

N-126.24
Zoar Church
Main St.

N-126.24

Name: ODESSA HISTORIC DISTRICT

Location: 607 MAIN STREET, ODESSA, DE

Photographer: VALERIE COSNA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGY +
HISTORIC PRESERVATION, DOVER, DE


Description:

ZOAR M. E. CHURCH
SOUTHWEST SIDE OF MAIN ST. WEST OF SIXTH ST.
VIEW FROM NORTHWEST

Photograph Number:

11 OF 40

M
W



N-126.27
MAIN STREET WEST
OF ROUTE 13

N- 126. 27

Name: ODESSA HISTORIC DISTRICT

Location: 605 MAIN STREET, ODESSA, DE

Photographer: VALERIE CESNA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGY +
HISTORIC PRESERVATION, DOVER, DE

Description:

EAST CORNER MAIN ST. + CORBITTS AVENUE,
VIEW FROM SOUTH

Photograph Number:

12 of 40

2-1-83



N-126.31

ROUTE 13 S (6TH ST.)

N-126.31

Name: ODESSA HISTORIC DISTRICT

Location: 4 SIXTH STREET, ODESSA, DE

Photographer: VALERIE CESNA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGY +
HISTORIC PRESERVATION, DOVER, DE

Description:

SOUTHEAST SIDE OF SIXTH ST. BETWEEN
MAIN + HIGH STS. — VIEW FROM WEST

Photograph Number:

13 OF 40

M
N



N-126.33
MAIN STREET BETWEEN
5TH ST. + 6TH ST. (RTE 13)

N-126.33

Name: ODESSA HISTORIC DISTRICT

Location: 503 MAIN STREET, ODESSA, DE

Photographer: VALERIE COENA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHAEOLOGY +
HISTORIC PRESERVATION, DOVER, DE

Description:

NORTHEAST SIDE OF MAIN STREET BETWEEN
FIFTH + SIXTH STS. — VIEW FROM SOUTH

Photograph Number:

14 OF 40

2
-15



N-126.34

MAIN ST. + RTE. 13N

N-126.34

Name: OVESSA HISTORIC DISTRICT

Location: 501 MAIN STREET, OVESSA, DE

Photographer: VALERIE CESNA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGY +
HISTORIC PRESERVATION, DOVER, DE

Description:

NORTH CORNER MAIN + FIFTH STS.
VIEW FROM SOUTH

Photograph Number:

15 OF 40

2
30
35



N-126.37

MAIN STREET

N-126.37

Name: OYESSA HISTORIC DISTRICT

Location: 407 MAIN ST., OYESSA, DE

Photographer: VALERIE CESNA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGY +
HISTORIC PRESERVATION, DOVER, DE

Description:

NORTHEAST SIDE OF MAIN ST. BETWEEN FOURTH +
FIFTH STS. — VIEW FROM SOUTH

Photograph Number:

16 of 40

29.2



N-126.39 + 39

MAIN ST. AT 4TH ST.

N-126.38 + .39

Name: ODESSA HISTORIC DISTRICT

Location: 401 + 405 MAIN ST., ODESSA, DE

Photographer: VALERIE COSNA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGY +
HISTORIC PRESERVATION, DOVER, DE

Description:

NORTH CORNER MAIN + FOURTH STS.
VIEW FROM SOUTH

Photograph Number:

17 of 40

2-7-28



N-126.40

MAIN ST.

N-126.40

Name: ODESSA HISTORIC DISTRICT

Location: 309 MAIN STREET, ODESSA, DE

Photographer: VALERIE CESNA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGY +
HISTORIC PRESERVATION, DOVER, DE

Description:

"THE ACADEMY"

EAST CORNER MAIN + FOURTH STS.
VIEW FROM SOUTHWEST

Photograph Number:

18 of 40

22-3



N-126.45

MAIN ST.

N-126.45

Name: ~~OVESHA~~ HISTORIC DISTRICT

Location: 209 MAIN STREET, OVESHA, DE

Photographer: VALERIE COENA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGY +
HISTORIC PRESERVATION, DOVER, DE

Description:

EAST CORNER MAIN + THIRD STS.
VIEW FROM WEST

Photograph Number:

19 of 40

24-3



N-126.48
BANK
MAIN ST.

N-126.48

Name: ODESSA HISTORIC DISTRICT

Location: 201 MAIN STREET, ODESSA, DE

Photographer: VALERIE CESNA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGY +
HISTORIC PRESERVATION, DOVER, DE

Description:

"NEW CASTLE NATIONAL BANK OF ODESSA"
NORTH CORNER MAIN + SECOND STS.
VIEW FROM SOUTH

Photograph Number:

20 of 40

M
-
S
S



N-126.49
THE BRICK HOTEL
MAIN ST.

N-126.49

Name: ~~ODESSA~~ HISTORIC DISTRICT

Location: 105 MAIN STREET, ODESSA, DE

Photographer: VALERIE CESNA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGICAL +
HISTORIC PRESERVATION, DOVER, DE

Description:

"THE BRICK HOTEL"

EAST CORNER MAIN + SECOND STS.

VIEW FROM WEST

Photograph Number:

21 of 40

3
-
5
3



N-126.60

N-126.60

Name: ODESSA HISTORIC DISTRICT

Location: 104 HIGH STREET, ODESSA, DE

Photographer: VALERIE CESNA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGY +
HISTORIC PRESERVATION, DOVER, DE

Description:

"COLLINS - SHARP HOUSE"

SOUTH CORNER HIGH + SECOND STS.

VIEW FROM NORTH

Photograph Number:

22 OF 40

3
-
2
5



N-126-61

THIRD ST.

N-126.61

Name: ~~ODessa~~ HISTORIC DISTRICT

Location: THIRD STREET, ODessa, DE

Photographer: VALERIE COSNA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGY +
HISTORIC PRESERVATION, DOVER, DE

Description:

"ENOS HOUSE"

SOUTH CORNER HIGH + SECOND STS.

VIEW FROM NORTH

Photograph Number:

23 OF 40

3-7-8



N-126.62

THIRD ST.

N-126.62

Name: ODESSA HISTORIC DISTRICT

Location: 300 THIRD STREET, ODESSA, DE

Photographer: VALERIE COSNA

Date: MAY 1983

Location of Negative: BUREAU OF ARCHEOLOGY +
HISTORIC PRESERVATION, DOVER, DE

Description:

"TATMAN HOUSE"

WEST CORNER THIRD + HIGH STS.
VIEW FROM EAST

Photograph Number:

24 OF 40

3-26