

Janice Rutherford photo, July 1981 Negative: Marilyn Troup 147 NE Yamhill Street Sheridan, OR 97378

1 of 9

South (front) elevation.



Janice Rutherford photo, July 1981 Negative: Marilyn Troup 147 NE Yamhill Street

Sheridan, OR 97378 2 of 9

South and east elevations.



Janice Rutherford photo, July 1981 Negative: Marilyn Troup 147 NE Yamhill Street Sheridan, OR 97378

3 of 9 South elevation showing woodshed/ garage.



Janice Rutherford photo, July 1981
Negative: Marilyn Troup
147 NE Yamhill Street
Sheridan, OR 97378

4 of 9
North (rear) elevation showing latticed

area way joining house to woodshed.



Janice Rutherford photo, July 1981 Negative: Marilyn Troup 147 NE Yamhill Street Sheridan, OR 97378

5 of 9

West elevation.



Janice Rutherford photo, July 1981 Negative: Marilyn Troup 147 NE Yamhill Street Sheridan, OR 97378

6 of 9 Detail of staircase in entry stairhall.




Janice Rutherford photo, July 1981 Negative: Marilyn Troup 147 NE Yamhill Street Sheridan, OR 97378

7 of 9 Looking south at second story doorway onto front porch deck.



Janice Rutherford photo, July 1981 Negative: Marilyn Troup 147 NE Yamhill Street Sheridan, OR 97378

8 of 9 Detail of typical window with beaded frame with corner blocks and colored border lights in upper sash.



Janice Rutherford photo, July 1981 Negative: Marilyn Troup 147 NE Yamhill Street Sheridan, OR 97378

Sheridan, OR 97378

9 of 9

Detail of typical decorated cast metal door hinge.