



Soo Hotel, Bismarck, N. D.

Soo Hotel

Bismarck, North Dakota

Photo credit: Unknown

Date of photo: ca. 1907-09

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, N.D. 58505

Facade and south exterior wall. Note original large portico
and high parapet wall containing name and date blocks,
since removed.

Photo 1 of 9



RESTAURANT
TRI-STATE
INVESTMENT CO.

THE M...ENCE

THE M...ENCE

CLOTHING

Soo Hotel

Bismarck, North Dakota

Photo credit: ?Unknown

Date of photo: ca. 1911-15

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, N.D. 58505

Historic photo showing new McKenzie Hotel on corner with Soo
Hotel to the right on Fifth Street.

Photo 2 of 9



YES VIRGINIA
CONTEMPORARY GIFTS & HOUSEWARES

 **Robert Knutson**
PHOTOGRAPHY

Blair

ON AN

Soo Hotel

Bismarck, North Dakota

Photo credit: Louis N. Hafermehl, State Historical Society
of North Dakota

Date of photo: October, 1982

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, N.D. 58505

Modern view showing present facade. Note ground level
alterations and removed upper parapet wall.

Photo 3 of 9

SOO HOTEL

Blackstone


Robert Knutson
PHOTOGRAPHY

ON AND OFF SALE

Restaurant

ROBIE'S

YES MICHIGAN
CENTER



Soo Hotel

Bismarck, North Dakota


Photo credit: Louis N. Hafermehl, State Historical Society
of North Dakota

Date of photo: October, 1982

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, N.D. 58505

Modern view of present facade and part of north wall. Oblique angle shows off brickwork and detailing. Note original name block on upper edge of north wall.

Photo 4 of 9



Soo Hotel

Bismarck, North Dakota


Photo credit: Louis N. Hafermehl, State Historical Society
of North Dakota

Date of photo: October, 1982

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, N.D. 58505

Interior view: Second floor looking down south stairway to
street level door.

Photo 5 of 9



Soo Hotel

Bismarck, North Dakota


Photo credit: Louis N. Hafermehl, State Historical Society
of North Dakota

Date of photo: October, 1982

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, N.D. 58505

Interior view: The light shaft seen from Second Floor level,
looking east toward the front of the building. Brickwork
of 1954 elevator is visible at the end of the light shaft,

Photo 6 of 9



Soo Hotel

Bismarck, North Dakota

Photo credit: Louis N. Hafermehl, State Historical Society
of North Dakota

Date of photo: October, 1982

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, N.D. 58505

Interior view: South hallway on Second Floor looking west
toward rear of building.

Photo 7 of 9



Soo Hotel

Bismarck, North Dakota


Photo credit: Louis N. Hafermehl, State Historical Society
of North Dakota

Date of photo: October, 1982

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, N.D. 58505

Interior view: South hallway on Third Floor looking toward
rear of building.

Photo 8 of 9



Soo Hotel
Bismarck, North Dakota

Photo credit: Louis N. Hafermehl, State Historical Society
of North Dakota

Date of photo: October, 1982

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, N.D. 58505

Interior view: Typical hotel room equipped with toilet-bathing facilities. The room is located on the south side of the Second Floor. Note sparse, utilitarian appearance, almost totally lacking in decoration.

Photo 9 of 9