

Photo | of 8

Property of the National Register

AUG 3 1978

Name: Augustine Paper Mill

Location: Near Wilmington, DE

DEC 30 197)

Photographer: Joan M. Norton

Date: 1977

Location of Negative: Div. of Hist. & Cultural Affairs,

B/A&HP, Hall of Records, Dover, DE

Description:

View of mill from Augustine Bridge looking towards the north. Note original mill building (No. 7) in the rear of the complex. Photograph Number:

N-3645 (1)



Photo of 8

Property of the National Register

Name: Augstine Paper Mill

DEC 30 1977

Location: Near Wilmington, DE

AUG 3 1978

Photographer: Joan M. Norton

Date: 1977

Location of Negative: Div. of Hist. & Cultural Affairs,

B/A&HP, Hall of Records, Dover, DE.

Description:

View of complex from Augustine Bridge looking north.

Note rail lines.

Thatamanh Mimher:

N-3645 (2)



Photo 3 of 8

Property of the National Register

le: Augustine Paper Mill

DEC 30 1977

Location: Near Wilmington, DE

AUG 3 1978

Photographer: Joan M. Norton

Date: 1977

Location of Negative: Div. of Hist. & Cultural Affairs,

B/A&HP, Hall of Records, Dover, DE

Description:

View of original mill structure from across the Brandywine looking towards the east. Note spillway from the race.

Photograph Number:

N-3645 (3)




Photo 4 of 8

Property of the National Register

.. Manua: Augustine Paper Mill

DEC 30 1977

Location: Near Wilmington, DE

AUG 3 1978

Photographer: Joan M. Norton

Date: 1977

Location of Negative: Div. of Hist. & Cultural Affairs,

B/A&HP, Hall of Records, Dover, DE

Description:

Detail of north wall of mill showing window detailing

and race

Photograph Number:

N-3645 (4)



Photo 5 of 8

Property of the National Register

Mara: Augustine Paper Mill

DEC 30 1977

Location: Near Wilmington, DE

AUG 3 1970

Photographer: Joan M. Norton

Date: 1977

Location of Negative: Div. of Hist. & Cultural Affairs,

B/A&HP, Hall of Records, Dover, DE

Description:

Upper floor of original mill. Note truss work.

Photograph Number:

N-3645 (5)



Photo 6 of 8

Property of the National Register

Augustine Paper Mill

DEC 3 U 1977

AUG 3 1978

Location: Near Wilmington, DE

Photographer: Joan M. Norton

Date: 1977

Location of Negative: Div. of Hist. & Cultural Affairs

B/A&HP, Hall of Records, Dover, DE

Description:

Archway on upper level of mill with remnants of original framing and fanlight.

Photograph Number:

N-3645 (6)



Photo 7 of 8

Property of the National Register

Augustine Paper Mill

DEC 30 1977 AUG ... 1978

Location: Near Wilmington, DE

Photographer: Joan M. Norton

Date: 1977

Location of Negative: Div. of Hist. & Cultural Affairs,

B/A&HP, Hall of Records, Dover, DE

Description:

Pulley system located in Building 7. 

Photograph Number:

N-3645 (7)



Photo 8 of 8

Property of the National Register

Name: Augustine Paper Mill

DEU 30 1977

Location: Near Wilmington, DE

AUG 3 1978

Photographer: Joan M. Norton

Date: 1977

Location of Negative: Div. of Hist. & Cultural Affairs,

B/A&HP, Hall of Records, Dover, DE

Description:

View of buildings 19 and 20 looking towards the north.

Photograph Number:

N-3645 (8)