



25

STOP

TOYOTA

PUBLIC SCHOOLS

TURLOCK HIGH SCHOOL AUDITORIUM AND CLASSROOM BUILDING  
TURLOCK, CALIFORNIA Stanislaus County

CATHERINE JULIEN  
FEBRUARY 1989

THIS RESTORATION PROJECT OFFICE  
PRINCIPAL FACADE + ENVIRONMENT. FROM NORTH WEST

#1 of 9

Negative: Turlock High School Restoration Fund  
PO Box 1458 Turlock 95381



TURLOCK HIGH SCHOOL PORTAL AND CLASS ROOM  
TURLOCK, CALIFORNIA Stanislaus County

CHASE AND JULIUS


FEBRUARY 1934

THE RESTORATION PROJECT OFFICE

CENTRAL GABLED PORTAL, FROM NORTH

# 2 of 9

Negative: Turlock High School Restoration Fund  
PO Box 1458 Turlock 95381



TURLOCK HIGH SCHOOL RESTORATION AND CASINOOM BUILDING  
TURLOCK, CALIFORNIA Stanislaus County

CATHERINE JULIAN  
FEBRUARY 1989

THIS RESTORATION PROJECT OFFICE  
EXTERIOR OF AUDITORIUM, FROM SOUTHEAST

#3 of 9

Negative: Turlock High School Restoration Fund  
PO Box 1458 Turlock 95381



TURLOCK HIGH SCHOOL AUDITORIUM INTERIOR

TURLOCK, CALIFORNIA Stanislaus County

CATHERINE JULIEN

MARCH 1988

THS RESTORATION PROJECT OFFICE

AUDITORIUM INTERIOR, FROM NORTHEAST

#4 of 9

Negative: Turlock High School Restoration Fund  
PO Box 01458 Turlock 95381





Turlock High School Boys / Girls' Gym

Turlock Ca. 95380

Photographer: Jack Claes D.B.A. The Shutters

Taken October 1990

Original negatives at the Shutters

North entrance of Gym showing steel structure  
that has been added to meet field flat

Camera facing South

Photo # 5 of 9



INDUSTRIAL DISTRICT  
307

Turlock High School Boys' / Girls' Gym

Turlock, Ca 95380

Photographer: Jack Claes D.B.A. The Shutters

Taken October, 1990

Original negatives at The Shutters

West side of Gym showing steel reinforcement  
added to meet Field Act

Camera facing South East

Photo 6 9 9



Turlock High School Boys'/Girls' Gym

Turlock, CA 95380

Photographer: Jack Claes, D.B.A. The Shutters

Taken October, 1990

Original negatives at The Shutters

South end of Boy's/Girls' Gym showing walkway behind bleachers.

Camera facing South-East

Photo 7 of 9



Turlock High School Boys'/Girls' Gym

Turlock, CA 95380

Photographer: Jack Ches, D.B.A. The Shutters

Taken October, 1990


Original negatives at The Shutters

North end of Boys'/Girls' Gym featuring bleachers.

Camera facing North.

Photo 8 of 9





Turlock High School Boys' / Girls' Gym

Turlock, Ca 95380

Photographer: Jack Claes D.B.A. The Shutters

Photograph taken: October 1990

Original negatives at the Shutters

East side of Gym showing steel reinforcement  
added to meet Field Act

Camera facing South ~~East~~ West

Photo 9 of 9