STOP
25
TOYOTA

TURLOCK HIGH SCHOOL ADMINISTRATION AND CLASSROOM BUILDING
TURLOCK, CALIFORNIA Stanislaus County
CATHERINE JULIEN
FEBRUARY 1989
THS RESTORATION PROJECT OFFICE
PRINCIPAL FACADE & ENVIRONMENT. FROM NORTHWEST

#1 of 9

Negative: Turlock High School Restoration Fund
PO Box 1458 Turlock 95381

TURLOCK HIGH SCHOOL RESTORATION AND CLASS FORM

TURLOCK, CALIFORNIA Stanislaus County

CAMERA: JULIER

FEBRUARY 1984

THS RESTORATION PROJECT OFFICE

CENTRAL GABLED PORTAL, FROM NORTH

2 of 9

Negative: Turlock High School Restoration Fund
PO Box 1458 Turlock 95381

TURLOCK HIGH SCHOOL AUDITORIUM AND CHEERLEADER BUILDING
TURLOCK, CALIFORNIA
Stanislaus County
CATHERINE JULIEN
FEBRUARY 1984

THS RESTORATION PROJECT OFFICE
EXTERIOR OF AUDITORIUM, FROM SOUTHEAST

#3 of 9

Negative: Turlock High School Restoration Fund
PO Box 1458 Turlock 95381

TURLOCK HIGH SCHOOL AUDITORIUM [illegible]
TURLOCK, CALIFORNIA Stanislaus County
CATHERINE JULIEN
MARCH 1988
THS RESTORATION PROJECT OFFICE
AUDITORIUM INTERIOR, FROM NORTHEAST
#4 of 9
Negative: Turlock High School Restoration Fund
PO Box 1458 Turlock 95381

Turlock High School Boys | Girls' Gym
Turlock Ca. 95380
Photographer: Jack Claes D.B.A. The Shutters
Taken October 1990
Original negatives at the Shutters
North entrance of Gym showing steel structure
that has been added to meet Field Act
Camera facing South

Photo # 5 of 9

Turlock High School Boys'/Girls' Gym
Turlock, Ca 95380
Photographer: Jack Claes D.B.A. The Shutters
Taken October, 1990
Original negatives at The Shutters
West side of Gym showing steel reinforcement
added to meet Field Act
Camera facing South East

Photo 6 of 9

Turlock High School Boys'/Girls' Gym
Turlock, CA 95380

Photographer: Jack Claes, D.B.A. The Shutters

Taken October, 1990

Original negatives at The Shutters

South end of Boy's/Girls' Gym showing walkway behind bleachers.

Camera facing South-East

Photo 7 of 9

Turlock High School Boys'/Girls' Gym

Turlock, CA 95380

Photographer: Jack Cbes, D.B.A. The Shutters

Taken October, 1990

Original negatives at The Shutters

North end of Boys'/Girls' Gym featuring bleachers.

Camera facing North.

Photo 8 of 9



Turlock High School Boys' / Girls' Gym
Turlock, Ca 95380
Photographer: Jack Claes D.B.A. The Shutters
Photograph taken: October 1990
Original negatives at the Shutters
East side of Gym showing steel reinforcement
added to meet Field Act
Camera facing South ~~East~~ West

Photo 9 of 9