



ONE  
WAY  
→

Photo: # 1  
Buschmann Block 1870; c.1880  
968-972 Ft. Wayne Avenue  
Indianapolis, IN 46202

VIEW: NE corner from NE

Photographer: Slade Associates 5/1/85  
Negative Filed: Slade Associates



ONE  
WAY  
→

Photo: # 2  
Buschmann Block 1870; c.1880  
968-972 Ft. Wayne Avenue  
Indianapolis, IN 46202

VIEW: E elevation from NE

Photographer: Slade Associates 5/1/85  
Negative Filed: Slade Associates



Photo: # 3

Buschmann Block 1870; c.1880

968-972 Ft. Wayne Avenue

Indianapolis, IN 46202

VIEW: W elevation from NW

Photographer: Slade Associates 5/1/85

Negative Filed: Slade Associates





Photo: # 4

Buschmann Block 1870; c. 1880

968-972 Ft. Wayne Avenue

Indianapolis, IN 46202

VIEW: E elevation from E

Photographer: Slade Associates 5/1/85

Negative Filed: Slade Associates





BUSCHMANN'S BLOCK

W. B. BRON BRIGGINS

LEWIS MEIER

W. BUSCHMANN'S

WYBUSCH

Photo: # 5  
Buschmann Block 1870; c. 1880  
968-972 Ft. Wayne Avenue  
Indianapolis, IN 46202

VIEW: E elevation

Photographer: unknown c. 1890

Source: Historic Landmarks Foundation of  
Indiana, Kemper House. Negative made  
from Xerox of album page, found in

building file, initial research,  
Old Northside Historic District.

Negative file: Slade Associates



Photo: # 6

Buschmann Block 1870; c. 1880

968-972 Ft. Wayne Avenue

Indianapolis, IN 46202

VIEW: N elevation from NW

Photographer: Slade Associates 5/1/85

Negative Filed: Slade Associates

HUGGINS

PEPSI MIDWAY ARCHERY  
*and* LANES

MIDWAY  
ARCHERY  
LANES

STOP





Photo: # 7

Buschmann Block 1870; c. 1880

968-972 Ft. Wayne Avenue

Indianapolis, IN 46202

VIEW: S elevation

Photographer: Slade Associates 5/1/85

Negative filed: Slade Associates





Photo: # 8

Buschmann Block 1870; c.1880

968-972 Ft. Wayne Avenue

Indianapolis, IN 46202

VIEW: 1st floor commercial space, N bay,  
looking E

Photographer: Slade Associates 2/6/86

Negative Filed: Slade Associates



Photo: # 9  
Buschmann Block 1870; c. 1880  
968-972 Ft. Wayne Avenue  
Indianapolis, IN 46202

VIEW: 1st floor commercial space, N bay,  
NW corner, original entrance  
Photographer: Slade Associates 2/6/86  
Negative Filed: Slade Associates



Photo: # 10

Buschmann Block 1870; c.1880

968-972 Ft. Wayne Avenue

Indianapolis, IN 46202

VIEW: 1 st floor commercial space, N bay,  
ceiling from SW

Photographer: Slade Associates 2/6/86

Negative Filed: Slade Associates



Photo: # 11

Buschmann Block 1870; c.1880

968-972 Ft. Wayne Avenue

Indianapolis, IN 46202

VIEW: 1st floor commercial space, S bay,  
looking E

Photographer: Slade Associates 2/6/86

Negative Filed: Slade Associates





Photo: # 12

Buschmann Block 1870; c.1880

968-972 Ft. Wayne Avenue

Indianapolis, IN 46202

VIEW: 1st floor commercial space, S bay,  
looking W

Photographer: Slade Associates 2/6/86

Negative Filed: Slade Associates

The Robin Hood Club

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

10 YEAR WARRANTY

Photo: # 13  
Buschmann Block 1870; c.1880  
968-972 Ft. Wayne Avenue  
Indianapolis, IN 46202

VIEW: 1st floor commercial space, S bay,  
looking SW

Photographer: Slade Associates 2/6/86

Negative Filed: Slade Associates



Photo: # 14

Buschmann Block 1870; c. 1880

968-972 Ft. Wayne Avenue

Indianapolis, IN 46202

VIEW: 1st floor archway W of E entrance  
stairs, looking S

Photographer: Slade Associates 2/6/86

Negative Filed: Slade Associates







Photo: # 15

Buschmann Block 1870; c. 1880

968-972 Ft. Wayne Avenue

Indianapolis, IN 46202

VIEW: entrance door to bathroom under E  
entrance stairs

Photographer: Slade Associates 2/6/86

Negative Filed: Slade Associates



Photo: # 16  
Buschmann Block 1870; c. 1880  
968-972 Ft. Wayne Avenue  
Indianapolis, IN 46202

VIEW: E entrance stairs from W

Photographer: Slade Associates 2/6/86  
Negative Filed: Slade Associates



Photo: # 17  
Buschmann Block 1870; c. 1880  
968-972 Ft. Wayne Avenue  
Indianapolis, IN 46202

VIEW: 3rd floor, N bay, looking SE

Photographer: Slade Associates 2/6/86  
Negative Filed: Slade Associates





Photo: # 18

Buschmann Block 1870; c. 1880

968-972 Ft. Wayne Avenue

Indianapolis, IN 46202

VIEW: 3rd floor, N bay, looking NE

Photographer: Slade Associates 2/6/86

Negative Filed: Slade Associates





Photo: # 19

Buschmann Block 1870; c.1880

968-972 Ft. Wayne Avenue

Indianapolis, IN 46202

VIEW: 3rd floor, S bay, looking E

Photographer: Slade Associates 2/6/86

Negative Filed: Slade Associates



Photo: # 20

Buschmann Block 1870; c. 1880

968-972 Ft. Wayne Avenue

Indianapolis, IN 46202

VIEW: 2nd floor, staircase to 3rd floor,  
looking NE

Photographer: Slade Associates 2/6/86

Negative Filed: Slade Associates