



1

80-7-42

Lakeside Historic District  
Burlington, Vermont  
Credit: Courtney Fisher  
Date: May, 1980  
Negative Filed at Vermont Division for  
Historic Preservation  
Description: 42 Conger Avenue (#51); Dwelling  
Type A; View ENE  
Photograph 1



2

80-A-42

Lakeside Historic District

Burlington, Vermont

Credit: Courtney Fisher

Date: May, 1980

Negative Filed at Vermont Division for  
Historic Preservation

Description: 28-30 Conger Avenue (#53); Dwell-  
ing Type B; View ENE

Photograph 2



3

80-#-42

Lakeside Historic District  
Burlington, Vermont  
Credit: Courtney Fisher  
Date: May, 1980  
Negative Filed at Vermont Division for  
Historic Preservation  
Description: 56-58 Conger Avenue (#48); Dwell-  
ing Type C; View ENE  
Photograph 3



4

80-#-42

Lakeside Historic District

Burlington, Vermont

Credit: Courtney Fisher

Date: May, 1980

Negative Filed at Vermont Division for  
Historic Preservation

Description: 57-59 Lakeside Avenue (#5);Dwell-  
ing Type D; View SE

Photograph 4





5

80-A-42

Lakeside Historic District

Burlington, Vermont

Credit: Courtney Fisher

Date: May, 1980

Negative Filed at Vermont Division for  
Historic Preservation

Description: 14-16 Conger Avenue (#56); Dwell-  
ing Type #; View ENE

Photograph 5



77-#-280

6

Lakeside Historic District

Burlington, Vermont

Credit: Clark Schoettle

Date: October, 1977

Negative Filed at Vermont Division for  
Historic Preservation

Description: 63069 Lakeside Avenue (#4);

View SE

Photograph 6



7

80-17-42

Lakeside Historic District  
Burlington, Vermont  
Credit: Courtney Fisher  
Date: May, 1980  
Negative Filed at Vermont Division for  
Historic Preservation  
Description: 28 Central Avenue (#10);  
View ENE  
Photograph 7



79-A-279

~~8~~ 8

Lakeside Historic District

Burlington, Vermont

Credit: Clark Schoettle

Date: October, 1977

Negative Filed at Vermont Division for  
Historic Preservation

Description: 70 Wright Avenue (#11); View NNE  
Photograph 8





89

77-#279

Lakeside Historic District

Burlington, Vermont

Credit: Clark Schoettle

Date: October, 1977

Negative Filed at Vermont Division for  
Historic Preservation

Description: 56 Wright Avenue (#12); View NNW  
Photograph 9



80-A-42

~~10~~ 10

Lakeside Historic District

Burlington, Vermont

Credit: Courtney Fisher


Date: May, 1980

Negative Filed at Vermont Division for  
Historic Preservation

Description: (L to R) 38-40, 44-46 Wright

Avenue (#'s 14 and 13); View WNW

Photograph 10



80-#42

~~#10~~ 11

Lakeside Historic District

Burlington, Vermont

Credit: Courtney Fisher

Date: May, 1980

Negative Filed at Vermont Division for  
Historic Preservation

Description: Central Avenue looking N from  
corner of Harrison Avenue (L to R) 65-67,  
59-61, 53-55, 47-49, 41-43, 31-33, 32-36,  
42-44 Central Avenue (#'s 22, 21, 20, 19, 18,  
17, 31, 29); View N

Photograph 11



80-#42

# 12

Lakeside Historic District

Burlington, Vermont

Credit: Courtney Fisher

Date: May, 1980

Negative Filed at Vermont Division for  
Historic Preservation

Description: Central Avenue looking WNW across  
from corner of Harrison and Conger Avenue  
(L to R) 65-67, 59-61, 53-55, 47-49, 41-43,  
42-44 Central Avenue (#'s 22,21,20,19,18,29)  
View WNW

Photograph 12





~~PL~~ 13

77-#280

Lakeside Historic District

Burlington, Vermont

Credit: Clark Schoettle

Date: October, 1977

Negative Filed at Vermont Division for  
Historic Preservation

Description: (L to R) 40 and 42-44 Central  
Avenue (#'s 30 and 29); View ENE

Photograph 13



NO  
PARKING  
IN THE  
STREET

14

77-A-280

Lakeside Historic District

South Burlington, Vermont

Credit: Clark Schoettle

Date: October, 1977

Negative Filed at Vermont Division for  
Historic Preservation

Description: 32-36 Central Avenue (#31);

View ENE  
Photograph 14



15

80-A-4/2

Lakeside Historic District

Burlington, Vermont

Credit: Courtney Fisher

Date: May, 1980

Negative Filed at Vermont Division for  
Historic Preservation

Description: (L to R) 37, 29-33, 23-27 Conger  
Avenue; 63-69 Lakeside Avenue (#'s 33, 34, 35  
and 4); View NNW

Photograph 15



16

80-A-4/2

Lakeside Historic District

Burlington, Vermont

Credit: Courtney Fisher

Date: May, 1980

Negative Filed at Vermont Division for  
Historic Preservation

Description: Harrison Avenue looking E from  
corner of Central Avenue (L to R) 83-85,  
77-79, 71-73, 65-67, 59-61, 53-55, 47-49,  
41-43 Harrison Avenue (#'s 42, 41, 40, 39, 38  
37, 36, 28); View ESE

Photograph 16





17

80-F-42

Lakeside Historic District

Burlington, Vermont

Credit: Courtney Fisher

Date: May, 1980

Negative Filed at Vermont Division for  
Historic Preservation

Description: E end of Harrison Avenue looking  
NW across Vermont Railroad (L to R) 41-43,  
47-49, 53-55, 59-61, 65-67, 71-73, 77-79, 83-85,  
74-76, 78-80, 84-86 Harrison Avenue. (#'s 28,  
36, 37, 38, 39, 40, 41, 42, 45, 44, 43); View NW  
Photograph 17



18

80-A-42

Lakeside Historic District

Burlington, Vermont


Credit: Courtney Fisher

Date: May, 1980

Negative Filed at Vermont Division for  
Historic Preservation

Description: Conger Avenue looking N from cor-  
ner of Harrison Avenue (L to R) 37, 42, 46,  
56-58, 62-64, 68-70, 74-76 Conger Avenue  
(#'s 33,51,50,48,47,46,45); View N

Photograph 18



19

80-7-42

Lakeside Historic District  
Burlington, Vermont

Credit: Courtney Fisher

Date: May, 1980

Negative Filed at Vermont Division for  
Historic Preservation

Description: (L to R) 79 Lakeside Avenue; 8,  
14-16, 20-22, 24-26, 28-30 Conger Avenue  
(#'s 3, 57, 56, 55, 54, 53); View NE

Photograph 19