



1a

East facing - Sacred Heart Cathedral
Church - 1025 N. Grand Ave, Pueblo, Co.

Direction - NW

10/88

NEGATIVE : COLORADO
OFFICE OF
ARCHAEOLOGY AND
HISTORIC PRESERVATION

Photo taken by
Gary Trujillo



South facing - Sacred Heart Cathedral
Church - 1025 N. Grand Ave. Pueblo, Co.

Direction - N

DATE: 10/88

NEGATIVE: COLORADO OFFICE OF ARCHAEOLOGY
AND HISTORIC PRESERVATION

Photo taken by
Gary Trujillo



3

Sacred Heart Cathedral -

1025 N Grand Ave. front entry-way.

Interior -


Direction - East

DATE 10/88

PHOTO TAKEN BY:

NEGATIVES: COLORADO OFFICE OF ARCHAEOLOGY
AND HISTORIC
PRESERVATION

Photo taken by
Gary Trujillo.



41

Sacred Heart Cathedral, 1025 N. Grand Ave
Pueblo, Co.

Interior - Rose wheel

Direction - East

DATE: 10/88

NEGATIVES: COLORADO OFFICE OF ARCHAEOLOGY
AND HISTORIC PRESERVATION

PHOTO TAKEN BY: GARY TRUJILLO



Sacred Heart Cathedral - 1025 N. Grand Ave ^{# 5}
Pueblo, Colo

DATE: 10/88

Interior -
Direction - South

NEGATIVES: COLORADO OFFICE OF ARCHAEOLOGY
AND HISTORIC
PRESERVATION

Photo taken
by Gary Trujillo



6.

Sacred Heart Cathedral, 1025 N. Grand Ave
Pueblo, Co

DATE 10/88

Interior -

Direction - North

NEGATIVES! COLORADO OFFICE OF ARCHAEOLOGY
AND HISTORIC PRESERVATION

Photos taken by
Cory Trujillo



47

Sacred Heart Cathedral, 1025 N. Grand Ave
Pueblo, Co

Interior. The Nave. DATE 10/88

Direction - South

NEGATIVES: COLORADO OFFICE OF ARCHAEOLOGY
AND HISTORIC PRESERVATION

Photo taken by

Gary Trujillo



#1
Sacred Heart Cathedral, 1025 N. Grand Ave
Pueblo, Colo

Front - East facing
Direction - NW.

DATE: 10/88

NEGATIVES: COLORADO OFFICE OF ARCHAEOLOGY AND
HISTORIC PRESERVATION

PHOTOGRAPHER
CARY TRUJILLO
Photo taken by
Cary Trujillo