



Perkins-Clark House

49 Woodland Street, Hartford, CT

Photo Credit: Stowe-Day Foundation Library, c. 1890

Neg. filed: CT Historical Society, Hartford, CT

The House as it would be seen by someone walking in the driveway from Woodland Street. View is to the northwest showing the front (south) facade and the side (east) facade.

DEC 14 1978

Photo A

MAY 5 1978



Perkins-Clark House

49 Woodland Street, Hartford, CT

Photographer: David F. Ransom, November, 1976

Neg. filed: D.F. Ransom, 33 Sunrise Hill Drive, West
Hartford, CT

View from the west looking east and showing west facade

DEC 14 1978

Photo B

MAY 5 1978



Perkins-Clark House

49 Woodland Street, Hartford, CT

Photographer: Hartford Architecture Conservancy, Autumn, 1975

Neg. filed: Charles Reich, 8 Forest St., Hartford, CT

View to the northwest showing east wing and chimneys added in 1924.

DEC 14 1978

Photo C

MAY 5 1978



Perkins-Clark House

49 Woodland Street, Hartford, CT

Photographer: David F. Ransom, November, 1976

Neg. filed: D.F. Ransom, 33 Sunrise Hill Drive, West
Hartford, CT

South facade showing altered porch and east wing added 1924.

DEC 14 1978

MAY 5 1978

Photo D