



OTRANTO PLANTATION INDIGO VATS

GOOSE CREEK VICINITY, SOUTH CAROLINA

DAVID B. SCHWEIDER

15 MARCH 1988

PRESERVATION CONSULTANTS, INC., CHARLESTON, SC

SOUTH (RIGHT) AND WEST (LEFT) SIDES, FACING
NORTHEAST

PHOTO #1



Otranto Plantation Indigo Vats
Good CREEK vicinity, South CAROLINA

DAVID B. SCHNEIDER

15 MARCH 1988

PRESERVATION CONSULTANTS, INC.,
CHARLESTON, SC

South (left) and EAST (Right) sides,
facing NORTHWEST

PHOTO #2



Otrivito Plantation Indigo Vats
Goose Creek vicinity, South CAROLINA

DAVID B. SCHNEIDER

15 MARCH 1988

PRESERVATION CONSULTANTS, INC.,
CHARLESTON, SC

Detail of RAMP @ north end, facing EAST

PHOTO #3



Otranto Plantation Indigo Vats

Goose Creek vicinity, South Carolina

David B. Schneider

15 MARCH 1988

PRESERVATION CONSULTANTS, INC.,
CHARLESTON, SC

Detail of upper vat, facing north

PHOTO # 4