OMB No. 1024-0018

#### United States Department of the Interior National Park Service

# National Register of Historic Places Registration Form

JAN 2 7 1989 NATIONAL REGISTER

This form is for use in nominating or requesting determinations of eligibility for individual properties or districts. See instructions in *Guidelines* for *Completing National Register Forms* (National Register Bulletin 16). Complete each item by marking "x" in the appropriate box or by entering the requested information. If an item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, styles, materials, and areas of significance, enter only the categories and subcategories listed in the instructions. For additional space use continuation sheets (Form 10-900a). Type all entries.

					وغانية والنائية والنائي ويتوجد والمراجع		
	of Property	77	an Mathle				
nistoric n			se, Nettie,	Fourplex			
ther nam	nes/site number	N/A					
. Loca							
treet & n	and the second secon	2106	-12 S.E. Mai	n		Dot for	publication
		Port		11			
ity, town	Oregon		R county	Multnomah	code	051	zip code 9721
tate .	010900			Multinoman		051	219 0000 9721
Class	ification						
	p of Property	Ci	ategory of Proper	lv	Number of Res	sources with	in Property
C private			] building(s)		Contributing	Noncon	• •
			district		1	1	buildings
		F	site				sites
= .	-Federal						structures
			object				objects
		_			1	1	Total
ame of I	related multiple pro	perty listing:			Number of con	tributing res	ources previously
listor	ic and Archit	ectural Re	sources	_	listed in the Na	-	
	tside Portlan			$\bigcirc$			
<u>. State</u>	/Federal Agency	Certificatio	n	/			
Signatu	re of certifying officia		- i san (	· · · ·		Date	ary 23, 1989
			<u>Historic</u> Pre	servation Of	fice		
State or	Federal agency and	bureau	J	•			
in my c	opinion, the proper	ty 🗌 meets 🗌	does not meet	the National Regi	ster criteria. 🗌 Se	e continuation	sheet.
Signatu	re of commenting or	other official				- Date	
	•						
State or	Federal agency and	bureau					
	nal Park Service		<u>n</u>				
$\mathbf{L}$	certify that this pro	•	R	$\mathcal{A}$	<b></b>		1 4
🖞 entere	d in the National F	legister.	<i>A.l.</i>	Bar	_ Entered in	the	alche
See	e continuation sheet.		Julian	yo pu	National Re	gister	3/8/81
determ	nined eligible for th	e National		V			
Regist	er. 🔲 See continua	tion sheet.					
determ	nined not eligible fo	or the					
Nation	al Register.			· ·			
_							
	ed from the Nation	al Register.					
other,	(explain:)		-				
						<u> </u>	
				-fignature of th	e Keeper		Date of Action

Current Functions (enter categories from instructions) DOMESTIC; Multiple Dwelling			
Materials (enter categories from instructions)			
foundation	Concrete		
walls	Weatherboard		
roof	Asphalt		
other			
-	 Materials (en foundation walls roof		

Describe present and historic physical appearance.

#### EXTERIOR DESCRIPTION

This lot is situated in the middle of the block on the south side of Main. The adjacent homes are of a similar period and add historic character to the flavor of this quiet residential neighborhood. Some foliage is present around the corners of the front elevation and there are several mature maple trees in the backyard. To the east a small side yard provides some open space between the lots. The house sits on a site that is roughly five feet above grade.

The two-and-one-half story fourplex contained within this structure is U-shaped in plan and has a low pitched hip roof covered with composition shingles. From the roof protrude three hip dormers that have a pair of twelve-over-twelve double-hung sash windows surrounded by rectangular shingles, and exposed scroll-cut rafters for ornamentation. At the back of the house, two hip roofs cover the extended appendages of the plan. The eastern portion of the U-shape has an enclosed stairway with a shed roof. The attached front porch stretches the full length of the house with square, wooden columns supporting the hip roof over it. An enclosed balustrade surrounds the porch. Two red brick chimneys with corbelled tops rise from opposite slopes of the roof.

The exterior surface of the house is clad with narrow, horizontal lapped siding and the building has wide cornerboards. The appearance of the front elevation is symmetrical. On the first floor, tripartite windows flank the entryways; the central window is a picture window with transom and the ends are one-over-one double-hung sash windows. In the center of the front elevation are four doors with single recessed panels and single panes of glass. A wide set of concrete steps lined by stone piers, with a central wrought iron hand railing gives access to the front porch. On the second floor of the front elevation, the windows take the form of twelve-over-one double-hung sash. The most typical window type on the east and west elevations is paired one-over-one double-hung sash.

X See continuation sheet

United States Department of the Interior National Park Service

### National Register of Historic Places Continuation Sheet

Section number \_\_\_\_\_ Page \_\_\_\_

On the east side, a concrete driveway with central steps leads to a two-car garage capped by a flat roof with a front parapet. A six-foot tall wooden fence of vertical boards surrounds most of the yard and provides privacy for the occupants. On the ground level between the two wings of the house is a wooden patio recently constructed. Two windows on either side of this patio have shed hoods.

#### INTERIOR DESCRIPTION

The four units are entered through side-by-side doors that are flush and centered on the facade. The two outer doors access the first-floor units; the center doors serve the upper units. The first-floor units are mirror images of each other, as are the upper units.

The first-floor units are arranged shot-gun style: front room, living room with bedroom/bath and kitchen across the back. The floors are fir and the walls are lath-and-plaster. Finishwork includes simple baseboards capped with picture rail molding, and simple window and door surrounds with architrave molding.

In the ground floor units, pocket doors separate the front room and living room. Light fixtures have been replaced with period reproductions. Access to a walk-in closet is via a single pocket door from the front room, or a standard hinged door from the living room. A handsome fireplace with a corbelled mantle enhances the living room. The kitchen, with narrow bevelled tongue-and-groove wainscoting, has a linoleum floor and plain mopboards. The lower cabinets were replaced in 1983, although a built-in cabinet with panelled doors has been retained. The bedroom also has a built-in feature: cupboards with glass doors above a wide drawer.

The second floor units are arranged off a wide staircase/hall which is located in the interior of the building. The stairs are simple with a square capped newel post. The upper floor is also arranged shot-gun style. A flat-arched opening separates the living room from a sitting area; these rooms are at the front of the building. The bedroom is located in the center, and the kitchen and bathroom are across the hall. A flat-arch opening defines the kitchen from an eating area. Access to the rear steps is via the kitchen. The second floor units also make use of the attic. The attic can be characterized as asymmetrical, generally fitting the roofline of the building. Like the main stairs, the steps to the attic are carpeted and have simple one-inch by fourinch balusters and newel post.

8. Statement of Significance	-	· · · · · · · · · · · · · · · · · · ·	
Certifying official has considered the significance of thi nationally			
Applicable National Register Criteria 🗌 A 🗌 B	G C D		
Criteria Considerations (Exceptions)	□c □D		
Areas of Significance (enter categories from instruction Architecture	IS) 	Period of Significance 1910	Significant Dates 1910
		Cultural Affiliation N/A	
Significant Person N/A		Architect/Builder Unknown	
Significant Person		1910 Cultural Affiliation N/A	

State significance of property, and justify criteria, criteria considerations, and areas and periods of significance noted above.

The Nettie Krouse Fourplex, constructed in 1910, is significant under criterion C as an excellent representative of the many small-scale, multi-family housing types which were built throughout the study area between approximately 1905 and 1912. More important, it is a quintessential example of the form which the Craftsman style takes in the study area. The builder and architect are unknown. The date of construction was established by City of Portland building permit records.

Small multi-family dwellings are an important part of the fabric of the inner southeast residential neighborhoods. They were constructed during the area's most significant period of growth when the demand for housing was skyrocketing. This growth coincided with the newly popular Craftsman style which found expression in a wide variety of building types. Characteristic elements of the style include a low-pitched hip or gable roof usually pierced by one or more dormers, expansive porches, and the use of natural materials such as stone, brick and wood. The hallmark of the style is the treatment of the area where the roof joins the wall. Here, wide overhanging eaves and exposed rafters are the rule.

There are 33 small, multi-family buildings included in the survey: 21 duplexes and 12 fourplexes. Of the fourplex property type four are considered potentially eligible for the National Register. The Krouse Fourplex is an exceptionally fine example of both the property type as well as the Craftsman style. The rectangular form with its broad, overhanging eaves with scroll-cut rafters and central dormer; roomy, full-width porch; and multi-light windows are hallmarks of the style. United States Department of the Interior National Park Service

## National Register of Historic Places Continuation Sheet

Section number \_\_\_\_8 Page \_\_\_2

The original owner of the building was Nettie Krouse, a native-born Iowan, who came to Portland around the turn of the century. Widowed before the subject building was constructed, Nettie lived in the house across the street for a number of years before moving into the Krouse Fourplex. She lived there until her death in 1954.

9. Major Biblio	graphical References			
. City of Po:	rtland Building Bureau microform a	nd card files.		
. City of Po:	rtland Bureau of Planning, <u>Portlan</u>	d Historic Resource Inventory, 1983.		
. Multnomah (	County Tax Assessor records, micro	form, and card files, Portland, 1980.		
. Polk, R. L	. and Co., Portland City Directori	es, 1911-1916.		
. Sanborn In	surance Map, 1923.			
. Ticor Title	e Company records, Portland, Orego	ı.		
. Portland R	ealty Atlas 1928, Oregon Historica	Library Collection.		
	ian, June 13, 1954. p. 47.	X See continuation sheet		
preliminary de has been requi previously liste previously dete designated a f recorded by H Survey # recorded by H	ntation on file (NPS): termination of individual listing (36 CFR 67) lested ed in the National Register ermined eligible by the National Register National Historic Landmark listoric American Buildings	Primary location of additional data: X State historic preservation office Other State agency Federal agency X Local government University X Other Specify repository:		
10. Geographic	cal Data			
		WAshington-Oregon 1:62500		
UTM References A 1 0 5 2 1 Zone Eastin C 1 1	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	B		
Verbal Boundary I	Description			
Salisbu	ry Hill addition, E. 28' of Lot 8, Lot 9, Block 2	Block 2		
		See continuation sheet		
Boundary Justifica	Ition			
Taxlot ]	lines			
		See continuation sheet		
11. Form Prepa				
name/title organization				
street & number		telephone (503) 234-4801		
city or town	Portland			

1

United States Department of the Interior National Park Service

## National Register of Historic Places Continuation Sheet

Section number \_\_\_\_9 Page \_\_\_2

. The Oregon Journal, June 13, 1954, p. 16.

. Barry, Mark D. and Associates, "Appraisal Report - 2106-2112 S.E. Main". June 13, 1984.

