



Claude Hayes Miller
Portland, Multnomah, Oregon
Alice I. Duff, photog.

1998

Alice I. Duff, 13051 SE Claybourne, Portland
97236

South elevation, facing north

1 of 16



Claude Hayes Miller
Portland, Multnomah, Oregon

Alice I. Duff, photog.

1998

Alice I. Duff, 13051 SE Claybourne, Portland
97236

South elevation dormer, facing north

2 of 16



Claude Hayes Miller

Portland, Multnomah, Oregon

Alice I. Duff, photog.

1998

Alice I. Duff, 13051 SE Claybourne
Portland 97236

South elevation, facing north, including
Douglas fir in backyard

3 of 16



Claude Hayes Miller
Portland, Multnomah, Oregon
Alice I. Duff, photos
1998.

Alice I. Duff, 13051 SE Claybourne, Portland
97236
South elevation of garage, facing north



Claude Hayes Miller

Portland, Multnomah, Oregon

Alice I. Duff, photog.

1998

Alice I. Duff, 13051 SE Claybourne, Portland
97236

East elevation, facing northwest



Claude Hayes Miller

Portland, Multnomah, Oregon

Alice I. Duff, photog.

1998

Alice I. Duff, 13051 SE Claybourne, Portland

West elevation, facing northeast

97236

6 of 16



Claude Hayes Miller


Portland, Multnomah, Oregon

Alice I. Duff, photog.

1998

Alice I. Duff, 1305 1/2 SE Clayburne, Portland
97236

Handmade wooden trellis on east end
of front porch (facing east)



Claude Hayes Miller

Portland, Multnomah, Oregon

Alice I. Duff, photog.

1998

Alice I. Duff, 13051 SE Claybourne, Portland
97236

Detail of exterior window molding



Claude Hayes Miller
Portland, Multnomah, Oregon

Alice I. Duff, photog.

1998

Alice I. Duff, 13051 SE Claybourne, Portland 97236

Livingroom, west wall



Claude Hayes Miller

Portland, Multnomah, Oregon

Alice I. Duff, photog.

1998

Alice I. Duff, 13051 SE Claybourne, Portland 97236

kitchen, south wall cabinets to right of
swinging door



Claude Hayes Miller

Portland, Multnomah, Oregon

Alice I. Duff, photog.

1998

Alice I. Duff, 13051 SE Claybourne, Portland
97236

Kitchen, south wall cabinet to left of
swinging door



Claude Hayes Miller

Portland, Multnomah, Oregon

Alice I. Duff, photog.

1998

Alice I. Duff, 13051 SE Claybourne St. Portland
97236

First floor bathroom cabinet, west
(interior) wall



Claude Hayes Miller
Portland, Multnomah, Oregon

Alice I. Duff, photo

1998

Alice I. Duff, 13051 SE Claybourne Portland 97236

Dormer bedroom (upstairs), west wall



Claude Hayes Miller

Portland, Multnomah, Oregon

Alice I. Duff, photo.

1998

Alice I. Duff, 13051 SE Claybourne, Portland 97236

Dormer bedroom (upstairs), in closet on
east side, south wall



Claude Hayes Miller
Portland, Multnomah, Oregon
Alice I. Duff, photog.

1998

Alice I. Duff, 13051 SE Claybouane, Portland 97236

First floor bedroom light fixture,
facing west



Claude Hayes Miller

Portland, Multnomah, Oregon

Alice I. Duff, photog

1998

Alice I. Duff, 13051 SE Claybourne St.
Portland 97236

Dormer bedroom (upstairs) light switch,
north (interior) wall