



80V  
0 HZ  
TVS  
808  
808

100 WE DISCOUNT  
WATCHES  
SWISS - JAPAN  
MILITARY - CITIZEN  
TOMMY - TISSOT  
BLANCHOLETTE

110-220 V - 50-60 Hz  
ANASONIC JVC SANYO  
LUGGAGE WATCHES  
SEIKO

LEADING  
100-220 V  
50-60 Hz

COBB'S MEN'S SHOES

TIPPY'S  
MEN'S SHOES

STACY AD  
MEN'S SHOES

110-220 50/60HZ  
FEDERAL CENTRAL STORES

SS

NATIONAL UNION BUILDING (DOWNTOWN HISTORIC DISTRICT DOE)  
918 F STREET, N.W.,  
WASHINGTON, D.C.

PHOTOGRAPHER: WILLIAM BUSHONG

DATE: 9/25/88

NEGATIVE LOCATED: PHOTOGRAPHER.  
6 BROWNS COURT, SE  
WASHINGTON, D.C. 20003

VIEW: FACING SOUTH.

PHOTO #

1 of 5



NATIONAL UNION BUILDING (DOWNTOWN HISTORIC  
918 F STREET, N.W. DISTRICT DOE)  
WASHINGTON, D.C.

PHOTOGRAPHER: WILLIAM BUSHONG

DATE: 9/25/88

NEGATIVE LOCATED: PHOTOGRAPHER  
6 BROWNS COURT, SE  
WASHINGTON, D.C.

VIEW: CAMERA FACING  
SOUTH WEST

20003

PHOTO # 2 of 5.



NATIONAL UNION BUILDING (DOWNTOWN HISTORIC  
DISTRICT DOE)  
918 F STREET, N. W.  
WASHINGTON, D. C.

PHOTOGRAPHER: WILLIAM BUSHONG

DATE: 9/25/88

NEG. LOCATED: PHOTOGRAPHER  
6 BROWNS COURT, SE  
WASHINGTON, D. C.  
20003

VIEW: FACING  
NORTH EAST

PHOTO # 3 OF 5



NATIONAL UNION BUILDING (DOWNTOWN HISTORIC  
918 F STREET, N.W. DISTRICT D0E)  
WASHINGTON, D.C.

PHOTOGRAPHER: WILLIAM BUSHONG

DATE: 9/22/88

NEG. LOCATED: PHOTOGRAPHER  
6 BROWNS CT., SE  
WASHINGTON, D.C.  
20003

VIEW: INTERIOR OF NATIONAL  
UNION BUILDING ELEVATOR  
FACING ENTRANCE (NORTH)

PHOTO # 4 OF 5





NATIONAL UNION BUILDING (DOWNTOWN  
918 F STREET, N.W. HISTORIC DISTRICT  
WASHINGTON, D.C. DOE)

PHOTOGRAPHER: WILLIAM BUSHONG

DATE: 9/22/88

NEG. LOCATED: PHOTOGRAPHER  
6 BROWNS CT., SE  
WASHINGTON, D.C.  
20003

VIEW: INTERIOR PLASTERWORK OF  
NATIONAL UNION BUILDING  
LOCATED IN FIRE INSURANCE  
COMPANY'S OFFICE SUITE,  
NOW COBB'S SAOESTORE,  
(1ST FLOOR)

PHOTO # 5 OF 5