



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Unknown
PHOTO DATE: 1929-30
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-1

DESCRIPTIVE DATA:

First campsite at Sun-Up Ranch. (Looking west)
Jerry A. and Rose Jacka in photo.

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9043
PHOENIX, ARIZ. 85008
602/944-2798



HP-1



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Unknown
PHOTO DATE: 1930/1932
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-2

DESCRIPTIVE DATA:

Tent site during construction of first dwelling
at Sun-Up Ranch. (Looking north) Left to right:
Jerry A. Jacka, Josephine Kubes and Rose Jacka.

STRUCTURE #: A At location of Structure

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9043
PHOENIX, ARIZ. 85068
602/944-2793



HP-2



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Rose Jacka
PHOTO DATE: Probably 1930
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-4.

DESCRIPTIVE DATA:

Construction of first dwelling at Sun-Up Ranch.
(Later became center room of ranch house).
(Looking west) Jerry A. Jacka in photo.

STRUCTURE #: A

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9043
PHOENIX, ARIZ. 85008
602/944-2798





JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Jerry A. Jacka
PHOTO DATE: Probably 1930
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-5

DESCRIPTIVE DATA:

Construction of first dwelling at Sun-Up Ranch
(looking west). (Later became center room of
ranch house). Rose Jacka "chinking" between
building stones with small rocks and concrete.

STRUCTURE #: A

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9043
PHOENIX, ARIZ. 85008
602/944-2788



HP-5



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Unknown
PHOTOD DATE: 1933
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-82

DESCRIPTIVE DATA:

Construction phase of main Sun-Up Ranch house.
Stone and concrete walls nearing completion.
Front of house (Looking southwest). Jerry A.
Jacka holding building stone at right of dwelling.

STRUCTURE #: A

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9043
PHOENIX, ARIZ. 85068
602/944-2793



HP-82



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Jerry A. Jacka
PHOTO DATE: 1933
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-80

DESCRIPTIVE DATA:

Beginning construction of front wall of main Sun-Up Ranch house. Wall is visible at right side of original one-room dwelling which became the center room of the house. Front door frame appears near center of photo.

STRUCTURE #: A

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9043
PHOENIX, ARIZ. 85068
602/944-2793



HP-80



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Unknown
PHOTO DATE: February 17, 1932
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-6

DESCRIPTIVE DATA:

Sun-Up Ranch. First dwelling at left. Mr & Mrs Fred Mayer lived in tent and soon homesteaded the adjoining section of land. (Looking north) Left to right: Josephine Kubes, Jerry A. Jacka, Rose Jacka and Blanche Mayer.

STRUCTURE #: A

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9043
PHOENIX, ARIZ. 85008
602/944-2793



HP 6



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Unknown
PHOTO DATE: February 18, 1933
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-9

DESCRIPTIVE DATA:

First dwelling at Sun-Up Ranch. This room is now center room of ranch house. Windows retained in center room to allow cross ventilation (See #HP-57) (Looking northwest) Left to right: Jerry A. Jacka, Josephine Kubes and Rose Jacka.

STRUCTURE #: A

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9043
PHOENIX, ARIZ. 85008
602/944-2708



HP-9



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Jerry A. Jacka
PHOTO DATE: Early 1930s (probably 1934-35)
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-12

DESCRIPTIVE DATA:

Windmill and concrete/stone water tank at left
(later converted to tool shed/tack room). Pack
train from sheep drive being loaded with barrels
of water. (Looking north)

STRUCTURE #: E & F

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9043
PHOENIX, ARIZ. 85008
602/944-2793



HP-12



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Jerry A. Jacka
PHOTO DATE: Early 1930s
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-18

DESCRIPTIVE DATA:

Sheep watering at Sun-Up Ranch. (Looking north-
east)

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9048
PHOENIX, ARIZ. 85066
602/944-2700



HP-18

247-2700



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Rose Jacka
PHOTO DATE: Early 1930s
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-17

DESCRIPTIVE DATA:

Guest cabin which was originally living quarters
for ranch hand, Bob Slusser (left). Jerry A.
Jacka (right) and an unknown cowboy or sheepman
(center). (Looking north)

STRUCTURE #: C

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9043
PHOENIX, ARIZ. 85008
602/944-2730



HP-17



SUN UP

JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Rose Jacka
PHOTO DATE: 1939-40
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-32

DESCRIPTIVE DATA:

Front of Sun-Up Cafe (later destroyed for I-17
Highway Right-of-Way.) Looking west. Jerry A.
Jacka on horseback.

STRUCTURE #: Demolished

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9043
PHOENIX, ARIZ. 85068
602/944-2790



HP-32



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Jerry D. Jacka
PHOTO DATE: April 1985
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-54

DESCRIPTIVE DATA:

Front of Sun-Up Ranch house. Constructed between 1929 and 1935. Roof extended to cover front concrete "patio" in 1946. Metal sash also replaced old wood windows, but original wood window casings remain to house sash. (Looking southwest)

STRUCTURE #: A & B

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9043
PHOENIX, ARIZ. 85008
602/944-2793



HP-54



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Jerry D. Jacka
PHOTO DATE: April 1985
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-55

DESCRIPTIVE DATA:

South wall of Sun-Up Ranch house. A screen sleeping porch was originally located in dwelling at far left end. During 1945, stone pillars were extended above the low walls and metal sash was added to make an enclosed bedroom. (Looking northwest).

STRUCTURE #: A & B

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9043
PHOENIX, ARIZ. 85008
602/944-2793



HP-55



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Jerry D. Jacka
PHOTO DATE: April 1985
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-56

DESCRIPTIVE DATA:
Rear and north sides of Sun-Up Ranch house.
(Looking southeast)

STRUCTURE #: A & B

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9043
PHOENIX, ARIZ. 85008
602/944-2793



HP-56



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Jerry D. Jacka
PHOTO DATE: April 1985
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-59

DESCRIPTIVE DATA:

Living room of Sun-Up Ranch house. Note original ceiling/roof. Patch to cover stovepipe hole in roof (distant left). Fireplace added in 1948. Original finely troweled concrete floors.

STRUCTURE #: A & B

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9043
PHOENIX, ARIZ. 85088
602/944-2798



HP-59



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Jerry D. Jacka
PHOTO DATE: April 1985
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-57

DESCRIPTIVE DATA:

Center room of Sun-Up Ranch house. Interior of the first dwelling. Note rough stone interior walls and windows at left and right. Although originally "outside" windows, they were retained to allow cross ventilation through kitchen (right) and screen porch/bedroom (left). Finely troweled concrete floors visible.

STRUCTURE #: A & B

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9043
PHOENIX, ARIZ. 85088
602/944-2798



HP-57



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Jerry D. Jacka
PHOTO DATE: April 1985
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-61

DESCRIPTIVE DATA:

Driveway at Sun-Up Ranch. Note desert vegetation.
Citrus orchard visible to left and right of wind-
mill. (Looking northwest)

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9043
PHOENIX, ARIZ. 85008
602/944-2798



HP-61



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Jerry D. Jacka
PHOTO DATE: April 1985
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-58

DESCRIPTIVE DATA:

Kitchen of Sun-Up Ranch house. Ceiling consists of original 2 x 4 rafters and tongue-and-groove roof which still serves as roof and ceiling. Note window of first dwelling (left) which is now the center room and finely troweled concrete floor.

STRUCTURE #: A & B

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9043
PHOENIX, ARIZ. 85009
602/944-2799



HP-58



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Jerry D. Jacka
PHOTO DATE: April 1985
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-66

DESCRIPTIVE DATA:

Smallest of two guest cabins at Sun-Up Ranch constructed about 1933. Originally served as quarters for ranch hand. (Looking southeast)

STRUCTURE #: C

JERRY JACKA PHOTOGRAPHY
P. O. BOX 3043
PHOENIX, ARIZ. 85008
602/944-2798



HP-66



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Jerry D. Jacka
PHOTO DATE: April 1985
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-67

DESCRIPTIVE DATA:

Largest of two guest cabins at Sun-Up Ranch constructed about 1933-34. (Looking southeast)

STRUCTURE #: D

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9043
PHOENIX, ARIZ. 85008
602/944-2783



HP-67



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Jerry D. Jacka
PHOTO DATE: April 1985
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-65

DESCRIPTIVE DATA:

Sun-Up Ranch. Tool shed and tack room constructed
from original concrete and stone water storage tank.
(Looking northwest)

STRUCTURE #: E

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9063
PHOENIX, ARIZ. 85008
602/944-2793



HP-65



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Jerry D. Jacka
PHOTO DATE: April 1985
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-64

DESCRIPTIVE DATA:

Sun-Up Ranch. Elevated water tanks and windmill.
Concrete water storage tank at right constructed
about 1949. Tool shed and tackroom constructed
from stone water tank is visible behind tank towers.
(Looking north)

STRUCTURE #: F

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9043
PHOENIX, ARIZ. 85008
602/944-2793



HP-64



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Jerry D. Jacka
PHOTO DATE: January 1980
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-70 A

DESCRIPTIVE DATA:

Sun-Up Ranch appears in center (see outline).
Gavilan Peak at top left, I-17 runs diagonally
across center. New River also runs diagonally
from left center to lower right. (Looking east
to northeast).

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9043
PHOENIX, ARIZ. 85008
602/944-2789



HP-70 A



JERRY & ROSE JACKA PROPERTY
NEW RIVER, ARIZONA

PHOTOGRAPHER: Jerry D. Jacka
PHOTO DATE: January 1980
NEGATIVE AT: Jacka Photography, Phoenix, Az
NEGATIVE FILE #: HP-70 B

DESCRIPTIVE DATA:

Sun-Up Ranch dwellings in foreground. I-17 frontage road at bottom of print. Main ranch house (largest roof area) and citrus orchard in center. Earthen dam (stock pond) at right front. Cleared area to right of driveway (center) is area used for watering sheep during 1930s. (Looking west).

JERRY JACKA PHOTOGRAPHY
P. O. BOX 9043
PHOENIX, ARIZ. 85068
602/944-2793



HP-70B