

KENTUCKY HISTORIC RESOURCES
Individual Inventory Form

Resource # KE-3
Kenton County

1. Name of Resource:
Pleasant Run Stone House II

2. Original Owner:
Not Known

3. Other Names:

4. Prehistoric Site _____ Building X Object
Historic Site _____ Structure _____ Other _____

5. Location: West side Bromley Road, one
mile south of Kentucky 8, near
Bromley vicinity

6. Owner's Name:
Mr. & Mrs. James R. Lewis [P]

7. Owner's Address:
717 Bromley Road
Bromley, Kentucky 41016

8. Evaluation: [G]

9. Recognition & Date:
Nat.Landmark _____ Local Landmark _____
Nat.Register _____ HABS/HAER _____
Highway Marker _____ KY Inventory _____ X
KY Landmark Certificate _____

10. N.R.Status & Date:

11. N.R.Group:
District Name: []
Mult.Resource Area: []
Thematic Name: Early Stone Buildings []

12. Historical Themes:
Primary: Architecture [030]
Secondary: []
Other: []

13. Statement of Significance:
This is one of two dry-stone houses on
this creek of a different building tradi-
tion than others in Kentucky (outside
Campbell County), having a four-room plan,
eyebrow windows, interior chimneys, gable
end windows, gable eaves, and solid []

14. History:
Built by a German from Pennsylvania.
Has only had three owners. Al Hageman
just before present owners.

16. Date:
Original Building 2nd 1/4 19th C. [7]
Addition []

17. Style:
Greek Revival [31]
[]

18. Architect/Builder:
Not Known

19. No. of Stories: 1 3/4 [1.5]

20. Original Floor Plan:
Four Room [4R]

21. Single Pile _____ Double Pile X N.A.

22. Roof Form & Material: Original _____
Gable _____ Not Original _____

23. Structural Material:
Stone [S]

24. Exterior Material:
Stone [S]

25. Foundation Material:
Stone [S]

26. Major Alterations: None _____
Moved/Rebuilt _____ Other _____
Additions _____

27. Special Features:
Two stone bridges

28. Outbuildings: Stone smokehouse,
carriage barn, bank barn [3]

29. Original Function:
Residence [01A]

30. Present Use:
Residence [01A]

31. Condition:
Excellent [E]

32. Endangered: Yes _____
No X

33. Attach Photos:
Roll: 31 Photo Nos: 1- No. of Slides: X

15. Source of historical information and/or contact
person: Owner

34. Prepared by: Carolyn Murray-Wooley

35. Organization: Kentucky Heritage Council

36. Date: June 1984

37. New Survey X Resurvey _____

KENTUCKY HISTORIC RESOURCES
Individual Inventory Form

Resource # KE-3


38. UTM Point of Primary Building: Zone Easting Northing 39. G.I.S. Mod. []
 Quadrant: Covington 16 711080 4327380 40. Coord. Accuracy []

41. UTM Points of Boundary (for N. R. eligible sites only):

A.	16	711170	4327450	D.	16	711060	4327470
B.	16	711130	4327300	E.	--	-----	-----
C.	16	710950	4327380	F.	--	-----	-----

42. Total Acreage in Present Property: 43. Acreage included in proposed N.R. boundary: 4 acres

44. Site Plan (and boundary description and justification for N.R. sites):



Site enclosed A - B - C - D as shown, which is the present property line. A - B is on the road, and B - C is with a small branch.

Stone house, smokehouse and stable are contributing. Bank barn is non-contributing because of alterations.

3 contributing buildings

45. Description and House Plan:

One and three-fourths story, four-bay, four-room, dry-stone house, ca. 36 x 42; masonry broken coursed limestone, with sawn stone lintels and sills. Entrance with transom, four-panel door, in second bay from south corner. Eaves extend all around house. Small second floor windows on front and rear below eaves. Two full-size windows each floor in gable ends. All 6/6 sash, most original glass. Round loopholes to attic in each end. Exterior cellar entrance on southeast front.

Two interior chimneys at roof ridge had fireplaces on each side—one in each of the four rooms. The one in living hall still functions, has Greek Revival mantel. Woodwork all Greek Revival except west room which has Gothic; four-panel doors. Floor joists have regular vertical saw marks, a few circular; joists rest on longitudinal summer beam.

A modern family room and enclosed porch have been added to the rear, which have not damaged the structure or primary appearance of the house.

There is a two-room stone smoke quarters house just behind the house; a frame carriage barn on the north side; and a stone and frame bank barn (altered) west of the house. All are located on the west bank of Pleasant Run Creek. A 20th century stone bridge crosses the creek from the road. An older 19th century bridge crosses the creek branch southwest of the house. Wooded hillside behind house.

13. Statement of Significance (Continued)

stone lintels. Unaltered and in very good condition.