



Tufveson House

Minot, ND

Photo Credit: Anonymous

Date: ca. 1906

Negative Location: State Historical Society of ND
Heritage Center
Bismarck, ND

View: facade from south

Photo: 1/20



Tufveson House

Minot, ND

Photo Credit: Cultural Research & Management, Inc.

Date: August 19, 1983

Negative Location: CRM, Inc.

P.O. Box 2154

Bismarck, ND 58502

View: facade from south

Photo: 2/20



Tufveson House

Minot, ND

Photo Credit: Cultural Research & Management, Inc.

Date: October 29, 1983

Negative Location: CRM, Inc.
P.O. Box 2154
Bismarck, ND 58502

View: facade from south

Photo: 3/20



Tufveson House

Minot, ND

Photo Credit: Cultural Research & Management, Inc.

Date: August 19, 1983

Negative Location: CRM, Inc.

P.O. Box 2154

Bismarck, ND 58502

View: Detail of facade from south

Photo: 4/20



Tufveson House

Minot, ND

Photo Credit: Cultural Research & Management, Inc.

Date: August 19, 1983

Negative Location: CRM, Inc.

P.O. Box 2154

Bismarck ND 58502

View: West & north elevations from northwest

Photo: 5/20



Tufveson House

Minot, ND

Photo Credit: Cultural Research & Management, Inc.

Date: August 19, 1983

Negative location: CRM, Inc.

P.O. Box 2154

Bismarck, ND 58502

View: east elevation from east

Photo: 6/20



Tufveson House

Minot, ND

Photo Credit: Cultural Research & Management, Inc.

Date: August 19, 1983

Negative Location: CRM, Inc.

P.O. Box 2154

Bismarck, ND 58502

View: detail of facade porch from southeast

Photo: 7/20



Tufveson House

Minot, ND

Photo Credit: Cultural Research & Management, Inc.

Date: August 19, 1983

Negative Location: CRM, Inc.

P.O. Box 2154

Bismarck, ND 58502

View: fishpond from east

Photo: 8/20



Tufveson House

Minot, ND

Photo Credit: Cultural Research & Management, Inc.

Date: August 19, 1983

Negative Location: CRM, Inc.
P.O. Box 2154
Bismarck, ND 58502

View: garage from southwest

Photo: 9/20



Tufveson House

Minot, ND

Photo Credit: Cultural Research & Management, Inc.

Date: August 19, 1983

Negative Location: CRM, Inc.

P.O. Box 2154

Bismarck, ND 58502

View: Entrance area and replacement staircase
from southwest

Photo: 10/20



Tufveson House

Minot, ND

Photo Credit: Cultural Research & Management

Date: October 29, 1983

Negative Location: CRM, Inc.
P.O. Box 2154
Bismarck ND 58502

View: Front parlor from north

Photo: 11/20



Tufveson House

Minot, ND

Photo Credit: Cultural Research & Management, Inc.

Date: August 19, 1983

Negative Location: CRM, Inc.

P.O. Box 2154

Bismarck, ND 58502

View: Living room opening into dining room
from south

Photo: 12/20



Tufveson House

Minot, ND

Photo Credit: Cultural Research & Management, Inc.

Date: August 19, 1983

Negative Location: CRM, Inc.

P.O. Box 2154

Bismarck, ND 58502

View: kitchen from northeast

Photo: 13/20



Tufveson House

Minot, ND

Photo Credit: Cultural Research & Management

Date: October 29, 1983

Negative Location: CRM, Inc.
P.O. Box 2154
Bismarck, ND 58502

View: Servants' stairs from east

Photo: 14/20



Tufveson House

Minot, ND

Photo Credit: Cultural Research & Management, Inc.

Date: August 19, 1983

Negative Location: CRM, Inc.
P.O. Box 2154
Bismarck, ND 58502

View: Morning room from west

Photo: 15/20



Tufveson House

Minot, ND

Photo Credit: Cultural Research & Management, Inc.

Date: August 19, 1983

Negative Location: Cultural Research & Mgmt, Inc.
P.O. Box 2154
Bismarck, ND 58502

View: south bedroom parlor from east

Photo: 16/20



Tufveson House

Minot, ND

Photo Credit: Cultural Research & Management, Inc.

Date: August 19, 1983

Negative Location: CRM, Inc.

P.O. Box 2154

Bismarck ND 58502

View: south bedroom parlor and bedroom from west

Photo: 17/20



Tufveson House

Minot, ND

Photo Credit: Cultural Research & Management, Inc.

Date: August 19, 1983

Negative Location: CRM, Inc.

P.O. Box 2154

Bismarck, ND 58502

View: west bedroom & parlor from southeast

Photo: 18/20



Tufveson House

Minot, ND

Photo Credit: Cultural Research & Management

Date: October 29, 1983

Negative Location: CRM, Inc.
P.O. Box 2154
Bismarck, ND

View: Facade & west elevation from southwest

Photo: 19/20



Tufveson House

Minot, ND

Photo Credit: Cultural Research & Management

Date: October 29, 1983

Negative Location: CRM, Inc.
P.O. Box 2154
Bismarck, ND 58502

View: Facade from south

Photo: 20/20